

Preliminary Map Report

A final EDR Report will be delivered after quality review is conducted.




Nationwide Customer Service

Telephone: 1-800-352-0050

Internet: www.edrnet.com

Environmental Corp. of America
3056 Bayard Street
Atlanta, GA 30344

March 07, 2019



- ★ Target Property
- ▲ Sites
- National Priority List Sites
- Dept. Defense Sites
- Indian Reservations BIA

EDR PUR-IQ[®] Report

"the intelligent way to conduct historical research"

The EDR PUR-IQ report facilitates historical research planning required to complete the Phase I ESA process. The report identifies the *likelihood* of prior use coverage by searching proprietary EDR-Prior Use Reports[®] comprising nationwide information on: city directories, fire insurance maps, aerial photographs, historical topographic maps, flood maps and National Wetland Inventory maps.

Coverage in the following historical information sources may be used as a guide to develop your historical research strategy:

- 1. Building Permits:** Building Permits are available for ATLANTA, GA (1985 - 2012).
- 2. City Directory:** Coverage exists for portions of ATLANTA, GA for 1870-1997
- 3. Fire Insurance Map:** When you order online any EDR Package or the EDR Radius Map with EDR Sanborn Map Search/Print, you receive site specific Sanborn Map coverage information at no charge.
- 4. Aerial Photograph:** Coverage exists for portions of Fulton County for the following decades: 1980s, 1960s, 1940s, 1930s, 1970s Shipping time 3-5 business days.
- 5. Topographic Map:** The USGS 7.5 min. quad topo sheet(s) associated with this site:

Historical: Coverage exists for FULTON County

Current: Coverage exists for Atlanta, GA

6. Flood Insurance Rate Maps (FEMA) : Coverage is available for Fulton County

EDR's network of professional researchers, located throughout the United States, accesses the most extensive national collections of city directory, fire insurance maps, aerial photographs, flood maps and historical topographic map resources available for Atlanta, GA. These collections may be located in multiple libraries throughout the country. To ensure maximum coverage, EDR will often assign researchers at these multiple locations on your behalf.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2015 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

STREET AND ADDRESS INFORMATION

©2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to TomTom North America, Inc. The use of this material is subject to the terms of a license agreement.

You will be held liable for any unauthorized copying or disclosure of this material.

PRELIMINARY REPORT - FINAL TO FOLLOW

25b5b91a-3de3-45ee-8af5-62421e2c4061

PRELIMINARY EXECUTIVE SUMMARY

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E 1527-13) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

TARGET PROPERTY INFORMATION

ADDRESS

3056 BAYARD STREET
ATLANTA, GA 30344

COORDINATES

Latitude (North):	33.6710280 - 33° 40' 15.70"
Longitude (West):	84.4313060 - 84° 25' 52.70"
Universal Transverse Mercator:	Zone 16
UTM X (Meters):	738155.0
UTM Y (Meters):	3728642.0

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property:	ATLANTA, GA
Source:	U.S. Geological Survey

SEARCH RESULTS

Sites were identified.

Sites listed in ***bold italics*** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

STANDARD ENVIRONMENTAL RECORDS

Federal CERCLIS list

SEMS: SEMS (Superfund Enterprise Management System) tracks hazardous waste sites, potentially hazardous waste sites, and remedial activities performed in support of EPA's Superfund Program across the United States. The list was formerly know as CERCLIS, renamed to SEMS by the EPA in 2015. The list contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). This dataset also contains sites which are either proposed to or on the National Priorities List (NPL) and the sites which are in the screening and assessment phase for possible inclusion on the NPL.

A review of the SEMS list, as provided by EDR, and dated 12/12/2018 has revealed that there are 4 SEMS sites within approximately 0.5 miles of the target property.

PRELIMINARY EXECUTIVE SUMMARY

<u>Site</u>	<u>Address</u>	<u>Dist / Dir</u>	<u>Map ID</u>	<u>Page</u>
NEWELL RECYCLING FAC	1359 CENTRAL AVE.	1/8 - 1/4 (0.144 mi.) SSW	A10	46
CROSBY STEVENS CO	1645 CENTRAL AVE	1/8 - 1/4 (0.230 mi.) WSW	C14	77
VIRGINIA CAROLINA CH	3171 NORMAN BERRY DR	1/4 - 1/2 (0.251 mi.) SE	17	82
MGA HOLDINGS	3015 R N MARTIN STRE	1/4 - 1/2 (0.365 mi.) WNW	F29	101

Federal CERCLIS NFRAP site list

SEMS-ARCHIVE: SEMS-ARCHIVE (Superfund Enterprise Management System Archive) tracks sites that have no further interest under the Federal Superfund Program based on available information. The list was formerly known as the CERCLIS-NFRAP, renamed to SEMS ARCHIVE by the EPA in 2015. EPA may perform a minimal level of assessment work at a site while it is archived if site conditions change and/or new information becomes available. Archived sites have been removed and archived from the inventory of SEMS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list the site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. The decision does not necessarily mean that there is no hazard associated with a given site; it only means that, based upon available information, the location is not judged to be potential NPL site.

A review of the SEMS-ARCHIVE list, as provided by EDR, and dated 12/13/2018 has revealed that there are 2 SEMS-ARCHIVE sites within approximately 0.5 miles of the target property.

<u>Site</u>	<u>Address</u>	<u>Dist / Dir</u>	<u>Map ID</u>	<u>Page</u>
ALLIED CHEMICAL CORP	1427 CENTRAL AVE	1/4 - 1/2 (0.318 mi.) W	D21	86
ATLANTA UTILITY WORK	1504 WASHINGTON AVE	1/4 - 1/2 (0.476 mi.) NW	36	108

Federal RCRA CORRACTS facilities list

CORRACTS: CORRACTS is a list of handlers with RCRA Corrective Action Activity. This report shows which nationally-defined corrective action core events have occurred for every handler that has had corrective action activity.

A review of the CORRACTS list, as provided by EDR, and dated 03/01/2018 has revealed that there are 2 CORRACTS sites within approximately 1 mile of the target property.

<u>Site</u>	<u>Address</u>	<u>Dist / Dir</u>	<u>Map ID</u>	<u>Page</u>
LAFARGE ROAD MARKING	2675 MARTIN ST	1/2 - 1 (0.886 mi.) NNW	43	113
SAFETY-KLEEN CORP 3-	3440 LANG AVE	1/2 - 1 (0.933 mi.) SE	47	134

PRELIMINARY EXECUTIVE SUMMARY

Federal RCRA generators list

RCRA-CESQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

A review of the RCRA-CESQG list, as provided by EDR, and dated 03/01/2018 has revealed that there is 1 RCRA-CESQG site within approximately 0.25 miles of the target property.

<u>Site</u>	<u>Address</u>	<u>Dist / Dir</u>	<u>Map ID</u>	<u>Page</u>
NEWELL RECYCLING OF	1359 CENTRAL AVE	1/8 - 1/4 (0.144 mi.) SSW	A5	10

State- and tribal - equivalent CERCLIS

SHWS: The State Hazardous Waste Sites records are the states' equivalent to CERCLIS. These sites may or may not already be listed on the federal CERCLIS list. Priority sites planned for cleanup using state funds (state equivalent of Superfund) are identified along with sites where cleanup will be paid for by potentially responsible parties. The data come from the Department of Natural Resources' Hazardous Site Inventory.

A review of the SHWS list, as provided by EDR, and dated 07/01/2018 has revealed that there is 1 SHWS site within approximately 1 mile of the target property.

<u>Site</u>	<u>Address</u>	<u>Dist / Dir</u>	<u>Map ID</u>	<u>Page</u>
TIFT SITE Facility Id: 10393	SOUTH MARTIN STREET	1/4 - 1/2 (0.259 mi.) SE	18	83

GA NON-HSI: Georgia Non Hazardous Site Inventory Sites.

A review of the GA NON-HSI list, as provided by EDR, and dated 12/31/2018 has revealed that there are 15 GA NON-HSI sites within approximately 1 mile of the target property.

<u>Site</u>	<u>Address</u>	<u>Dist / Dir</u>	<u>Map ID</u>	<u>Page</u>
GENERAL CHEMICAL COR	1427 CENTRAL AVE	1/4 - 1/2 (0.318 mi.) W	D22	90
EAST POINT AUTO BODY	1466 CENTRAL AVENUE	1/4 - 1/2 (0.322 mi.) WSW	E24	97
3141 VIVIAN SYKES ST	3141 VIVIAN SYKES ST	1/4 - 1/2 (0.348 mi.) WSW	E25	97
SOUTHERN TRANSFORMER	3015 RN MARTIN STREE	1/4 - 1/2 (0.365 mi.) WNW	F27	101
D&N ELECTRIC COMPANY	3015 R.N. MARTIN STR	1/4 - 1/2 (0.365 mi.) WNW	F28	101
Not reported	28 THIRD ST.	1/4 - 1/2 (0.470 mi.) NNE	35	108
LEGGETTE & PLATT	3030 PLANT ST	1/4 - 1/2 (0.489 mi.) WNW	37	109
3080 SYLVAN ROAD	3080 SYLVAN RD. AND	1/2 - 1 (0.729 mi.) E	39	111
FORMER CROWE MARINE	3067 MAIN ST	1/2 - 1 (0.730 mi.) W	40	112
FORMER EASTERN AIRLI	900 TOFFIE TERRACE,	1/2 - 1 (0.837 mi.) S	41	112
VACANT PARKING LOT	SE CORNER OF VIRGINI	1/2 - 1 (0.865 mi.) S	42	113
1200 VIRGINIA AVENUE	1200 VIRGINIA AVENUE	1/2 - 1 (0.897 mi.) S	44	128
HARRIS-STONE CLEANER	3303 MAIN ST	1/2 - 1 (0.916 mi.) WSW	45	129
ATTWOOD CANVAS FACIL	1526 EAST FORREST AV	1/2 - 1 (0.931 mi.) NNW	46	133

PRELIMINARY EXECUTIVE SUMMARY

<u>Site</u>	<u>Address</u>	<u>Dist / Dir</u>	<u>Map ID</u>	<u>Page</u>
DAIRY QUEEN	1519 NORMAN BERRY DR	1/2 - 1 (0.985 mi.) NNW	48	153

State and tribal landfill and/or solid waste disposal site lists

SWF/LF: The Solid Waste Facilities/Landfill Sites records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. The data come from the Department of Natural Resources' Operating Solid Waste Facilities' list.

A review of the SWF/LF list, as provided by EDR, and dated 10/11/2017 has revealed that there is 1 SWF/LF site within approximately 0.5 miles of the target property.

<u>Site</u>	<u>Address</u>	<u>Dist / Dir</u>	<u>Map ID</u>	<u>Page</u>
SANITATION TRANSFER Permit Number: PBR-060-122TS Operating Status: 1	3125 MARTIN ST	1/8 - 1/4 (0.156 mi.) SE	B11	47

State and tribal leaking storage tank lists

LUST: The Leaking Underground Storage Tank Incident Reports contain an inventory of reported leaking underground storage tank incidents. The data come from the Department of Natural Resources' Confirmed Release List.

A review of the LUST list, as provided by EDR, and dated 03/30/2018 has revealed that there are 13 LUST sites within approximately 0.5 miles of the target property.

<u>Site</u>	<u>Address</u>	<u>Dist / Dir</u>	<u>Map ID</u>	<u>Page</u>
EAST POINT MUNICIPAL Cleanup Status: NFA - No Further Action Cleanup Status: NFA - Clean Closure Facility Id: 00600231	3120 BAYARD ST	1/8 - 1/4 (0.141 mi.) WSW	4	7
NEWELL RECYCLING OF Cleanup Status: NFA - No Further Action Facility Id: 00600531	1359 CENTRAL AVE	1/8 - 1/4 (0.144 mi.) SSW	A6	21
SOUTHERN ZINC CO Cleanup Status: NFA - Clean Closure Facility Id: 00600469	1359 CENTRAL AVE	1/8 - 1/4 (0.144 mi.) SSW	A8	26
SANITATION TRANSFER Cleanup Status: NFA - No Further Action Facility Id: 00601110	3125 MARTIN ST	1/8 - 1/4 (0.156 mi.) SE	B11	47
CARDEN'S GLASS CO IN Cleanup Status: NFA - No Further Action Facility Id: 09060657	1392 CENTRAL AVE	1/4 - 1/2 (0.262 mi.) SW	19	84
YARBROUGH MOTOR CO Cleanup Status: NFA - No Further Action Facility Id: 09060831	3272 BACHELOR STREET	1/4 - 1/2 (0.316 mi.) S	20	85
GENERAL CHEMICAL COR	1427 CENTRAL AVE	1/4 - 1/2 (0.318 mi.) W	D22	90

PRELIMINARY EXECUTIVE SUMMARY

Cleanup Status: NFA - Suspected Release
 Cleanup Status: NFA - No Further Action
 Facility Id: 00600583

NAV SVCS Cleanup Status: NFA -Monitoring Only (MNA) Facility Id: 00600459	1454 WILLINGHAM DR	1/4 - 1/2 (0.357 mi.) SW	26	97
DOBBS INTERNATIONAL Cleanup Status: NFA - No Further Action Facility Id: 00601342	3160 AERO COURT	1/4 - 1/2 (0.401 mi.) WSW	30	102
PALLETT EXPRESS INC Cleanup Status: NFA - No Further Action Facility Id: 10000974	3131 AERO COURT	1/4 - 1/2 (0.414 mi.) W	31	104
FIRST BAPTIST CHURCH Cleanup Status: NFA - No Further Action Facility Id: 09060709	20 FIFTH STREET	1/4 - 1/2 (0.435 mi.) NNE	32	105
NEWELL TRANSPORTATIO Cleanup Status: NFA - No Further Action Facility Id: 09060557	1525 WILLINGHAM DRIV	1/4 - 1/2 (0.466 mi.) WSW	G33	106
B&W SVC CO INC Cleanup Status: NFA - Clean Closure Facility Id: 00600452	3082 PLANT ST	1/4 - 1/2 (0.496 mi.) W	38	110

State and tribal registered storage tank lists

UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the Department of Natural Resources' Underground Storage Tank Database.

A review of the UST list, as provided by EDR, and dated 01/14/2019 has revealed that there are 4 UST sites within approximately 0.25 miles of the target property.

<u>Site</u>	<u>Address</u>	<u>Dist / Dir</u>	<u>Map ID</u>	<u>Page</u>
EAST POINT MUNICIPAL Status: Removed from Ground Status: Currently in Use Facility Status: Active Facility Id: 600231	3120 BAYARD ST	1/8 - 1/4 (0.141 mi.) WSW	4	7
NEWELL RECYCLING OF Status: Removed from Ground Facility Status: Inactive Facility Id: 600531	1359 CENTRAL AVE	1/8 - 1/4 (0.144 mi.) SSW	A6	21
SOUTHERN ZINC CO Status: Closed in Ground Facility Status: Inactive Facility Id: 600469	1359 CENTRAL AVE	1/8 - 1/4 (0.144 mi.) SSW	A8	26
SANITATION TRANSFER Status: Removed from Ground Facility Status: Inactive	3125 MARTIN ST	1/8 - 1/4 (0.156 mi.) SE	B11	47

PRELIMINARY EXECUTIVE SUMMARY

Facility Id: 601110

State and tribal institutional control / engineering control registries

INST CONTROL: Sites on the Public Record Listing that have institutional controls or limitations on use are sites with Risk Reduction Standards of 3, 4, and 5.

A review of the INST CONTROL list, as provided by EDR, and dated 11/06/2018 has revealed that there is 1 INST CONTROL site within approximately 0.5 miles of the target property.

<u>Site</u>	<u>Address</u>	<u>Dist / Dir</u>	<u>Map ID</u>	<u>Page</u>
BUS DOCTOR OF ATLANT	1525 WILLINGHAM DR.	1/4 - 1/2 (0.466 mi.) WSW	G34	107

State and tribal voluntary cleanup sites

VCP: Georgia's Voluntary Remediation Program Act was created to encourage voluntary investigation and remediation of contaminated properties.

A review of the VCP list, as provided by EDR, and dated 08/30/2018 has revealed that there is 1 VCP site within approximately 0.5 miles of the target property.

<u>Site</u>	<u>Address</u>	<u>Dist / Dir</u>	<u>Map ID</u>	<u>Page</u>
Not reported	1427 CENTRAL AVENUE	1/4 - 1/2 (0.318 mi.) W	D23	96

State and tribal Brownfields sites

BROWNFIELDS: The Brownfields Public Record lists properties where response actions under the Georgia Hazardous Site Reuse and Redevelopment Act are planned, ongoing or completed.

A review of the BROWNFIELDS list, as provided by EDR, and dated 11/06/2018 has revealed that there is 1 BROWNFIELDS site within approximately 0.5 miles of the target property.

<u>Site</u>	<u>Address</u>	<u>Dist / Dir</u>	<u>Map ID</u>	<u>Page</u>
BUS DOCTOR OF ATLANT	1525 WILLINGHAM DR.	1/4 - 1/2 (0.466 mi.) WSW	G34	107

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

PRELIMINARY EXECUTIVE SUMMARY

US BROWNFIELDS: The EPA's listing of Brownfields properties from the Cleanups in My Community program, which provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

A review of the US BROWNFIELDS list, as provided by EDR, and dated 12/17/2018 has revealed that there is 1 US BROWNFIELDS site within approximately 0.5 miles of the target property.

<u>Site</u>	<u>Address</u>	<u>Dist / Dir</u>	<u>Map ID</u>	<u>Page</u>
NO MAN'S LAND	SOUTH MARTIN STREET	1/8 - 1/4 (0.176 mi.) SE	B12	74

Local Lists of Landfill / Solid Waste Disposal Sites

SWRCY: A listing of recycling facility locations.

A review of the SWRCY list, as provided by EDR, and dated 07/06/2018 has revealed that there is 1 SWRCY site within approximately 0.5 miles of the target property.

<u>Site</u>	<u>Address</u>	<u>Dist / Dir</u>	<u>Map ID</u>	<u>Page</u>
NEWELL RECYCLING OF	1359 CENTRAL AVE., S	1/8 - 1/4 (0.144 mi.) SSW	A7	24

ODI: An open dump is defined as a disposal facility that does not comply with one or more of the Part 257 or Part 258 Subtitle D Criteria.

A review of the ODI list, as provided by EDR, and dated 06/30/1985 has revealed that there is 1 ODI site within approximately 0.5 miles of the target property.

<u>Site</u>	<u>Address</u>	<u>Dist / Dir</u>	<u>Map ID</u>	<u>Page</u>
CITY OF ATLANTA - GU	1359 GUN CLUB ROAD	1/8 - 1/4 (0.212 mi.) SSW	13	76

Other Ascertainable Records

RCRA NonGen / NLR: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

A review of the RCRA NonGen / NLR list, as provided by EDR, and dated 03/01/2018 has revealed that there are 3 RCRA NonGen / NLR sites within approximately 0.25 miles of the target property.

<u>Site</u>	<u>Address</u>	<u>Dist / Dir</u>	<u>Map ID</u>	<u>Page</u>
SOUTHERN ZINC	1359 CENTRAL AVE	1/8 - 1/4 (0.144 mi.) SSW	A9	34
ACME BOX & SALVAGE C	1645 CENTRAL AVENUE	1/8 - 1/4 (0.230 mi.) WSW	C15	79
PLASMET E-SOLUTIONS	3245 MARYLAND AVE	1/8 - 1/4 (0.246 mi.) SSW	16	81

PRELIMINARY EXECUTIVE SUMMARY

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR Hist Cleaner: EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR Hist Cleaner list, as provided by EDR, has revealed that there are 3 EDR Hist Cleaner sites within approximately 0.125 miles of the target property.

<u>Site</u>	<u>Address</u>	<u>Dist / Dir</u>	<u>Map ID</u>	<u>Page</u>
DEE S CCIN OPERATED	3058 BAYARD ST	0 - 1/8 (0.062 mi.) WNW	1	7
ONE PRICE DRY CLEANI	3025 N DRUID RD NE H	0 - 1/8 (0.122 mi.) NNE	2	7
WALKERS FUNERAL HOME	712 S BAYARD ST	0 - 1/8 (0.123 mi.) N	3	7

PRELIMINARY EXECUTIVE SUMMARY

Due to poor or inadequate address information, the following sites were not mapped. Count: 7 records

<u>Site Name</u>	<u>Database(s)</u>
J M ZELLNER & SON TRANSFER CO	LUST, UST, Financial Assurance
GENERAL CHEMICAL CORPORATION	SHWS
HENRY CHANIN/MARTEL MANUFACTURING	SEMS
SOUTHERN EMS	SWF/LF
CENTENNIAL OLYMPIC PARK	GA NON-HSI
GWCC (TRACT II)	GA NON-HSI
GWCC (TRACT I)	GA NON-HSI

PRELIMINARY MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
STANDARD ENVIRONMENTAL RECORDS								
<i>Federal NPL site list</i>								
NPL	1.000		0	0	0	0	NR	0
Proposed NPL	1.000		0	0	0	0	NR	0
NPL LIENS	1.000		0	0	0	0	NR	0
<i>Federal Delisted NPL site list</i>								
Delisted NPL	1.000		0	0	0	0	NR	0
<i>Federal CERCLIS list</i>								
FEDERAL FACILITY	0.500		0	0	0	NR	NR	0
SEMS	0.500		0	2	2	NR	NR	4
<i>Federal CERCLIS NFRAP site list</i>								
SEMS-ARCHIVE	0.500		0	0	2	NR	NR	2
<i>Federal RCRA CORRACTS facilities list</i>								
CORRACTS	1.000		0	0	0	2	NR	2
<i>Federal RCRA non-CORRACTS TSD facilities list</i>								
RCRA-TSDF	0.500		0	0	0	NR	NR	0
<i>Federal RCRA generators list</i>								
RCRA-LQG	0.250		0	0	NR	NR	NR	0
RCRA-SQG	0.250		0	0	NR	NR	NR	0
RCRA-CESQG	0.250		0	1	NR	NR	NR	1
<i>Federal institutional controls / engineering controls registries</i>								
LUCIS	0.500		0	0	0	NR	NR	0
US ENG CONTROLS	0.500		0	0	0	NR	NR	0
US INST CONTROL	0.500		0	0	0	NR	NR	0
<i>Federal ERNS list</i>								
ERNS	TP		NR	NR	NR	NR	NR	0
<i>State- and tribal - equivalent CERCLIS</i>								
SHWS	1.000		0	0	1	0	NR	1
GA NON-HSI	1.000		0	0	7	8	NR	15
<i>State and tribal landfill and/or solid waste disposal site lists</i>								
SWF/LF	0.500		0	1	0	NR	NR	1
<i>State and tribal leaking storage tank lists</i>								
LUST	0.500		0	4	9	NR	NR	13
INDIAN LUST	0.500		0	0	0	NR	NR	0
<i>State and tribal registered storage tank lists</i>								
FEMA UST	0.250		0	0	NR	NR	NR	0

PRELIMINARY MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
UST	0.250		0	4	NR	NR	NR	4
AST	0.250		0	0	NR	NR	NR	0
INDIAN UST	0.250		0	0	NR	NR	NR	0
State and tribal institutional control / engineering control registries								
INST CONTROL	0.500		0	0	1	NR	NR	1
AUL	0.500		0	0	0	NR	NR	0
State and tribal voluntary cleanup sites								
VCP	0.500		0	0	1	NR	NR	1
INDIAN VCP	0.500		0	0	0	NR	NR	0
State and tribal Brownfields sites								
BROWNFIELDS	0.500		0	0	1	NR	NR	1
ADDITIONAL ENVIRONMENTAL RECORDS								
Local Brownfield lists								
US BROWNFIELDS	0.500		0	1	0	NR	NR	1
Local Lists of Landfill / Solid Waste Disposal Sites								
SWRCY	0.500		0	1	0	NR	NR	1
HIST LF	0.500		0	0	0	NR	NR	0
INDIAN ODI	0.500		0	0	0	NR	NR	0
DEBRIS REGION 9	0.500		0	0	0	NR	NR	0
ODI	0.500		0	1	0	NR	NR	1
IHS OPEN DUMPS	0.500		0	0	0	NR	NR	0
Local Lists of Hazardous waste / Contaminated Sites								
US HIST CDL	TP		NR	NR	NR	NR	NR	0
CDL	TP		NR	NR	NR	NR	NR	0
DEL SHWS	1.000		0	0	0	0	NR	0
US CDL	TP		NR	NR	NR	NR	NR	0
Local Land Records								
LIENS 2	TP		NR	NR	NR	NR	NR	0
Records of Emergency Release Reports								
HMIRS	TP		NR	NR	NR	NR	NR	0
SPILLS	TP		NR	NR	NR	NR	NR	0
SPILLS 90	TP		NR	NR	NR	NR	NR	0
Other Ascertainable Records								
RCRA NonGen / NLR	0.250		0	3	NR	NR	NR	3
FUDS	1.000		0	0	0	0	NR	0
DOD	1.000		0	0	0	0	NR	0
SCRD DRYCLEANERS	0.500		0	0	0	NR	NR	0

PRELIMINARY MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
US FIN ASSUR	TP		NR	NR	NR	NR	NR	0
EPA WATCH LIST	TP		NR	NR	NR	NR	NR	0
2020 COR ACTION	0.250		0	0	NR	NR	NR	0
TSCA	TP		NR	NR	NR	NR	NR	0
TRIS	TP		NR	NR	NR	NR	NR	0
SSTS	TP		NR	NR	NR	NR	NR	0
ROD	1.000		0	0	0	0	NR	0
RMP	TP		NR	NR	NR	NR	NR	0
RAATS	TP		NR	NR	NR	NR	NR	0
PRP	TP		NR	NR	NR	NR	NR	0
PADS	TP		NR	NR	NR	NR	NR	0
ICIS	TP		NR	NR	NR	NR	NR	0
FTTS	TP		NR	NR	NR	NR	NR	0
MLTS	TP		NR	NR	NR	NR	NR	0
COAL ASH DOE	TP		NR	NR	NR	NR	NR	0
COAL ASH EPA	0.500		0	0	0	NR	NR	0
PCB TRANSFORMER	TP		NR	NR	NR	NR	NR	0
RADINFO	TP		NR	NR	NR	NR	NR	0
HIST FTTS	TP		NR	NR	NR	NR	NR	0
DOT OPS	TP		NR	NR	NR	NR	NR	0
CONSENT	1.000		0	0	0	0	NR	0
INDIAN RESERV	1.000		0	0	0	0	NR	0
FUSRAP	1.000		0	0	0	0	NR	0
UMTRA	0.500		0	0	0	NR	NR	0
LEAD SMELTERS	TP		NR	NR	NR	NR	NR	0
US AIRS	TP		NR	NR	NR	NR	NR	0
US MINES	0.250		0	0	NR	NR	NR	0
ABANDONED MINES	0.250		0	0	NR	NR	NR	0
FINDS	TP		NR	NR	NR	NR	NR	0
UXO	1.000		0	0	0	0	NR	0
ECHO	TP		NR	NR	NR	NR	NR	0
DOCKET HWC	TP		NR	NR	NR	NR	NR	0
FUELS PROGRAM	0.250		0	0	NR	NR	NR	0
AIRS	TP		NR	NR	NR	NR	NR	0
COAL ASH	0.500		0	0	0	NR	NR	0
DRYCLEANERS	0.250		0	0	NR	NR	NR	0
Financial Assurance	TP		NR	NR	NR	NR	NR	0
NPDES	TP		NR	NR	NR	NR	NR	0
TIER 2	TP		NR	NR	NR	NR	NR	0
UIC	TP		NR	NR	NR	NR	NR	0

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP	1.000	0	0	0	0	NR	0
EDR Hist Auto	0.125	0	NR	NR	NR	NR	0
EDR Hist Cleaner	0.125	3	NR	NR	NR	NR	3

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

RGA HWS	TP	NR	NR	NR	NR	NR	0
---------	----	----	----	----	----	----	---

PRELIMINARY MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
RGA LF	TP		NR	NR	NR	NR	NR	0
RGA LUST	TP		NR	NR	NR	NR	NR	0
- Totals --		0	3	18	24	10	0	55

NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site
Database(s)
EPA ID Number
EDR ID Number

1
WNW
< 1/8
0.062 mi.
330 ft.
DEE S CCIN OPERATED LAUNDRY
3058 BAYARD ST
EAST POINT, GA 30344
EDR Hist Cleaner
1009341537
N/A

EDR Hist Cleaner:

Year: Name: Type:
1970 DEE S CCIN OPERATED LAUNDRY: LAUNDRIES SELF SERVE

2
NNE
< 1/8
0.122 mi.
645 ft.
ONE PRICE DRY CLEANING
3025 N DRUID RD NE HI
ATLANTA, GA 30329
EDR Hist Cleaner
1020055489
N/A

EDR Hist Cleaner:

Year: Name: Type:
2003 ONE PRICE DRY CLEANING: Drycleaning Plants, Except Rugs
2004 ONE PRICE DRY CLEANING: Drycleaning Plants, Except Rugs
2005 ONE PRICE DRY CLEANING: Drycleaning Plants, Except Rugs

3
North
< 1/8
0.123 mi.
651 ft.
WALKERS FUNERAL HOME
712 S BAYARD ST
EAST POINT, GA 30044
EDR Hist Cleaner
1020116534
N/A

EDR Hist Cleaner:

Year: Name: Type:
1970 WALKERS FUNERAL HOME: Drycleaning Plants, Except Rugs

4
WSW
1/8-1/4
0.141 mi.
744 ft.
EAST POINT MUNICIPAL SERVICE CEN
3120 BAYARD ST
EAST POINT, GA 30344
LUST
UST
Financial Assurance
U001478091
N/A

LUST:

Facility ID: 00600231
Leak ID: Not reported
Description: Not reported
Cleanup Status: NFA - No Further Action
Date Received: 01/07/1999
Project Officer: EPD Migration
Project Name: UST - 1 - EAST POINT MUNICIPAL SERVICE CEN
Site Code Description: Potential GUST trust fund reimbursement site
No Further Action Date: 04/25/2006

Facility ID: 00600231
Leak ID: Not reported
Description: Not reported
Cleanup Status: NFA - Clean Closure
Date Received: Not reported

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

EAST POINT MUNICIPAL SERVICE CEN (Continued)

U001478091

Project Officer: EPD Migration
Project Name: UST - CLOSURE - EAST POINT MUNICIPAL SERVICE CEN
Site Code Description: Potential GUST trust fund reimbursement site
No Further Action Date: 04/14/2003

Facility:

Facility Id: 600231
Facility Status: Active
Facility Type: City
District: Not reported
Owner Name: City of point
Contact ID: Not reported
Owner Address: 3120 bayard street
Owner City: east point
Owner State: GA
Owner Zip: 30344
Owner Telephone: 404 2707098

Tank:

Tank ID: 1
Tank Status: Removed from Ground
Tank Material: Bare Steel
Pipe Type: Pressurized
Tank Overfill Type: Not reported
Install Date: 05/01/1978
Facility ID: 600231
Status Date: Not reported
Product: Gas (Historical Use)
Pipe Material: Galvanized Steel
Overfill Protection: Not reported
Overfill Installed: Not reported
Tank Exempt From Spill: Not reported
Date Spill Device Installed: Not reported

Tank ID: 2
Tank Status: Removed from Ground
Tank Material: Bare Steel
Pipe Type: Gravity Fed
Tank Overfill Type: Not reported
Install Date: 05/01/1978
Facility ID: 600231
Status Date: Not reported
Product: Gas (Historical Use)
Pipe Material: Galvanized Steel
Overfill Protection: Not reported
Overfill Installed: Not reported
Tank Exempt From Spill: Not reported
Date Spill Device Installed: Not reported

Tank ID: 3
Tank Status: Removed from Ground
Tank Material: Bare Steel
Pipe Type: Pressurized
Tank Overfill Type: Not reported
Install Date: 05/01/1978
Facility ID: 600231
Status Date: Not reported

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

EAST POINT MUNICIPAL SERVICE CEN (Continued)

U001478091

Product:	Gas (Historical Use)
Pipe Material:	Galvanized Steel
Overfill Protection:	Not reported
Overfill Installed:	Not reported
Tank Exempt From Spill:	Not reported
Date Spill Device Installed:	Not reported
Tank ID:	4
Tank Status:	Removed from Ground
Tank Material:	Bare Steel
Pipe Type:	Pressurized
Tank Overfill Type:	Not reported
Install Date:	05/01/1978
Facility ID:	600231
Status Date:	Not reported
Product:	Gas (Historical Use)
Pipe Material:	Galvanized Steel
Overfill Protection:	Not reported
Overfill Installed:	Not reported
Tank Exempt From Spill:	Not reported
Date Spill Device Installed:	Not reported
Tank ID:	5
Tank Status:	Removed from Ground
Tank Material:	Bare Steel
Pipe Type:	Pressurized
Tank Overfill Type:	Not reported
Install Date:	05/01/1978
Facility ID:	600231
Status Date:	Not reported
Product:	Used Oil
Pipe Material:	Galvanized Steel
Overfill Protection:	True
Overfill Installed:	Not reported
Tank Exempt From Spill:	True
Date Spill Device Installed:	Not reported
Tank ID:	6
Tank Status:	Removed from Ground
Tank Material:	Bare Steel
Pipe Type:	Pressurized
Tank Overfill Type:	Not reported
Install Date:	05/01/1978
Facility ID:	600231
Status Date:	Not reported
Product:	Other
Pipe Material:	Galvanized Steel
Overfill Protection:	Not reported
Overfill Installed:	Not reported
Tank Exempt From Spill:	Not reported
Date Spill Device Installed:	Not reported
Tank ID:	7
Tank Status:	Removed from Ground
Tank Material:	Bare Steel
Pipe Type:	Pressurized
Tank Overfill Type:	Not reported

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

EAST POINT MUNICIPAL SERVICE CEN (Continued)

U001478091

Install Date: 05/01/1978
Facility ID: 600231
Status Date: Not reported
Product: Other
Pipe Material: Galvanized Steel
Overfill Protection: Not reported
Overfill Installed: Not reported
Tank Exempt From Spill: Not reported
Date Spill Device Installed: Not reported

Tank ID: 8
Tank Status: Currently in Use
Tank Material: Double Walled
Pipe Type: Pressurized
Tank Overfill Type: Not reported
Install Date: 01/06/1999
Facility ID: 600231
Status Date: Not reported
Product: Gas (Historical Use)
Pipe Material: Fiberglass Reinforced Plastic
Overfill Protection: Not reported
Overfill Installed: 01/15/1999
Tank Exempt From Spill: Not reported
Date Spill Device Installed: 01/15/1999

Tank ID: 9
Tank Status: Currently in Use
Tank Material: Double Walled
Pipe Type: Pressurized
Tank Overfill Type: Not reported
Install Date: 01/06/1999
Facility ID: 600231
Status Date: Not reported
Product: Diesel
Pipe Material: Fiberglass Reinforced Plastic
Overfill Protection: Not reported
Overfill Installed: 01/15/1999
Tank Exempt From Spill: Not reported
Date Spill Device Installed: 01/15/1999

GA Financial Assurance 1:
Region: 1
Facility ID: 600231
Financial Responsibility: Self Insured

A5
SSW
1/8-1/4
0.144 mi.
761 ft.
NEWELL RECYCLING OF ATLANTA LLC
1359 CENTRAL AVE
EAST POINT, GA 30344
Site 1 of 6 in cluster A

RCRA-CESQG 1000204676
ICIS GAD078117272
US AIRS
FINDS
ECHO

RCRA-CESQG:
Date form received by agency: 04/24/2015
Facility name: NEWELL RECYCLING OF ATLANTA LLC
Facility address: 1359 CENTRAL AVE
EAST POINT, GA 30344

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

NEWELL RECYCLING OF ATLANTA LLC (Continued)

1000204676

EPA ID: GAD078117272
Mailing address: CENTRAL AVENUE
EAST POINT, GA 30344
Contact: NICHOLAS A HEFTY
Contact address: STEEL DRIVE
TUCKER, GA 30084
Contact country: US
Contact telephone: 404-766-1621
Telephone ext.: 15132
Contact email: NH@NRATL.COM
EPA Region: 04
Land type: Private
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name: NEWELL RECYCLING OF ATLANTA LLC
Owner/operator address: CENTRAL AVE
EAST POINT, GA 30344
Owner/operator country: US
Owner/operator telephone: 404-766-1621
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 07/22/2014
Owner/Op end date: Not reported

Owner/operator name: NEWELL RECYCLING OF ATLANTA LLC
Owner/operator address: CENTRAL AVE
EAST POINT, GA 30344
Owner/operator country: US
Owner/operator telephone: 404-766-1621
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 07/22/2014
Owner/Op end date: Not reported

Handler Activities Summary:

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

NEWELL RECYCLING OF ATLANTA LLC (Continued)

1000204676

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D009
. Waste name: MERCURY

Historical Generators:

Date form received by agency: 08/20/1980
Site name: NEWELL INDUSTRIES OF ATLANTA
Classification: Not a generator, verified

Facility Has Received Notices of Violations:

Regulation violated: Not reported
Area of violation: Universal Waste - Small Quantity Handlers
Date violation determined: 02/09/2012
Date achieved compliance: 05/14/2012
Violation lead agency: EPA
Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Used Oil - Generators
Date violation determined: 02/09/2012
Date achieved compliance: 05/14/2012
Violation lead agency: EPA
Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 02/09/2012

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

NEWELL RECYCLING OF ATLANTA LLC (Continued)**1000204676**

Date achieved compliance: 05/14/2012
Violation lead agency: EPA
Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:

Evaluation date: 02/09/2012
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Used Oil - Generators
Date achieved compliance: 05/14/2012
Evaluation lead agency: EPA

Evaluation date: 02/09/2012
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Universal Waste - Small Quantity Handlers
Date achieved compliance: 05/14/2012
Evaluation lead agency: EPA

Evaluation date: 02/09/2012
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 05/14/2012
Evaluation lead agency: EPA

ICIS:

Enforcement Action ID: GA000A0000131210031200010
FRS ID: 110006836095
Action Name: NEWELL RECYCLING OF ATLANTA LLC 131210031200010
Facility Name: NEWELL RECYCLING OF ATLANTA LLC
Facility Address: 1359 CENTRAL AVE
EAST POINT, GA 30344
Enforcement Action Type: Notice of Violation
Facility County: FULTON
Program System Acronym: AIR
Enforcement Action Forum Desc: Administrative - Informal
EA Type Code: NOV
Facility SIC Code: 5093
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 33.668561
Longitude in Decimal Degrees: -84.433087
Permit Type Desc: Not reported
Program System Acronym: GA0000001312100312
Facility NAICS Code: 423930
Tribal Land Code: Not reported

Enforcement Action ID: GA000A0000131210031200008
FRS ID: 110006836095
Action Name: NEWELL RECYCLING OF ATLANTA LLC 131210031200008
Facility Name: NEWELL RECYCLING OF ATLANTA LLC
Facility Address: 1359 CENTRAL AVE
EAST POINT, GA 30344

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

NEWELL RECYCLING OF ATLANTA LLC (Continued)**1000204676**

Enforcement Action Type: Notice of Violation
 Facility County: FULTON
 Program System Acronym: AIR
 Enforcement Action Forum Desc: Administrative - Informal
 EA Type Code: NOV
 Facility SIC Code: 5093
 Federal Facility ID: Not reported
 Latitude in Decimal Degrees: 33.668561
 Longitude in Decimal Degrees: -84.433087
 Permit Type Desc: Not reported
 Program System Acronym: GA0000001312100312
 Facility NAICS Code: 423930
 Tribal Land Code: Not reported

Enforcement Action ID: GA000A0000131210031200007
 FRS ID: 110006836095
 Action Name: NEWELL RECYCLING OF ATLANTA LLC 131210031200007
 Facility Name: NEWELL RECYCLING OF ATLANTA LLC
 Facility Address: 1359 CENTRAL AVE
 EAST POINT, GA 30344

Enforcement Action Type: Notice of Violation
 Facility County: FULTON
 Program System Acronym: AIR
 Enforcement Action Forum Desc: Administrative - Informal
 EA Type Code: NOV
 Facility SIC Code: 5093
 Federal Facility ID: Not reported
 Latitude in Decimal Degrees: 33.668561
 Longitude in Decimal Degrees: -84.433087
 Permit Type Desc: Not reported
 Program System Acronym: GA0000001312100312
 Facility NAICS Code: 423930
 Tribal Land Code: Not reported

Enforcement Action ID: GA000A0000131210031200006
 FRS ID: 110006836095
 Action Name: NEWELL RECYCLING OF ATLANTA LLC 131210031200006
 Facility Name: NEWELL RECYCLING OF ATLANTA LLC
 Facility Address: 1359 CENTRAL AVE
 EAST POINT, GA 30344

Enforcement Action Type: Notice of Violation
 Facility County: FULTON
 Program System Acronym: AIR
 Enforcement Action Forum Desc: Administrative - Informal
 EA Type Code: NOV
 Facility SIC Code: 5093
 Federal Facility ID: Not reported
 Latitude in Decimal Degrees: 33.668561
 Longitude in Decimal Degrees: -84.433087
 Permit Type Desc: Not reported
 Program System Acronym: GA0000001312100312
 Facility NAICS Code: 423930
 Tribal Land Code: Not reported

Enforcement Action ID: 04-200042737
 FRS ID: 110006836095
 Action Name: Newell Recycling

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

NEWELL RECYCLING OF ATLANTA LLC (Continued)**1000204676**

Facility Name: NEWELL RECYCLING, LLC
Facility Address: 1359 CENTRAL AVENUE
EAST POINT, GA 30344
Enforcement Action Type: Letter of Violation/ Warning Letter
Facility County: FULTON
Program System Acronym: ICIS
Enforcement Action Forum Desc: Administrative - Informal
EA Type Code: LOVWL
Facility SIC Code: Not reported
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 33.668428
Longitude in Decimal Degrees: -84.433106
Permit Type Desc: Not reported
Program System Acronym: 2200016083
Facility NAICS Code: Not reported
Tribal Land Code: Not reported

US AIRS (AFS):

Envid: 1000204676
Region Code: 04
County Code: GA121
Programmatic ID: AIR GA0000001312100312
Facility Registry ID: 110006836095
D and B Number: Not reported
Facility Site Name: NEWELL RECYCLING OF ATLANTA LLC
Primary SIC Code: 5093
NAICS Code: 423930
Default Air Classification Code: SMI
Facility Type of Ownership Code: Not reported
Air CMS Category Code: SMI
HPV Status: Not reported

US AIRS (AFS):

Region Code: 04
Programmatic ID: AIR GA0000001312100312
Facility Registry ID: 110006836095
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1986-07-31 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 04
Programmatic ID: AIR GA0000001312100312
Facility Registry ID: 110006836095
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1987-05-09 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

NEWELL RECYCLING OF ATLANTA LLC (Continued)**1000204676**

Region Code: 04
 Programmatic ID: AIR GA0000001312100312
 Facility Registry ID: 110006836095
 Air Operating Status Code: OPR
 Default Air Classification Code: SMI
 Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
 Activity Date: 1989-08-25 00:00:00
 Activity Status Date: Not reported
 Activity Group: Compliance Monitoring
 Activity Type: Inspection/Evaluation
 Activity Status: Not reported

Region Code: 04
 Programmatic ID: AIR GA0000001312100312
 Facility Registry ID: 110006836095
 Air Operating Status Code: OPR
 Default Air Classification Code: SMI
 Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
 Activity Date: 1990-01-22 00:00:00
 Activity Status Date: Not reported
 Activity Group: Compliance Monitoring
 Activity Type: Inspection/Evaluation
 Activity Status: Not reported

Region Code: 04
 Programmatic ID: AIR GA0000001312100312
 Facility Registry ID: 110006836095
 Air Operating Status Code: OPR
 Default Air Classification Code: SMI
 Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
 Activity Date: 1991-03-21 00:00:00
 Activity Status Date: Not reported
 Activity Group: Compliance Monitoring
 Activity Type: Inspection/Evaluation
 Activity Status: Not reported

Region Code: 04
 Programmatic ID: AIR GA0000001312100312
 Facility Registry ID: 110006836095
 Air Operating Status Code: OPR
 Default Air Classification Code: SMI
 Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
 Activity Date: 1991-10-22 00:00:00
 Activity Status Date: Not reported
 Activity Group: Compliance Monitoring
 Activity Type: Inspection/Evaluation
 Activity Status: Not reported

Region Code: 04
 Programmatic ID: AIR GA0000001312100312
 Facility Registry ID: 110006836095
 Air Operating Status Code: OPR
 Default Air Classification Code: SMI
 Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
 Activity Date: 1994-08-17 00:00:00
 Activity Status Date: Not reported
 Activity Group: Compliance Monitoring

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

NEWELL RECYCLING OF ATLANTA LLC (Continued)**1000204676**

Activity Type:	Inspection/Evaluation
Activity Status:	Not reported
Region Code:	04
Programmatic ID:	AIR GA0000001312100312
Facility Registry ID:	110006836095
Air Operating Status Code:	OPR
Default Air Classification Code:	SMI
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	1996-06-05 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported
Region Code:	04
Programmatic ID:	AIR GA0000001312100312
Facility Registry ID:	110006836095
Air Operating Status Code:	OPR
Default Air Classification Code:	SMI
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	1998-06-03 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported
Region Code:	04
Programmatic ID:	AIR GA0000001312100312
Facility Registry ID:	110006836095
Air Operating Status Code:	OPR
Default Air Classification Code:	SMI
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	1998-06-04 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported
Region Code:	04
Programmatic ID:	AIR GA0000001312100312
Facility Registry ID:	110006836095
Air Operating Status Code:	OPR
Default Air Classification Code:	SMI
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	2000-05-31 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported
Region Code:	04
Programmatic ID:	AIR GA0000001312100312
Facility Registry ID:	110006836095
Air Operating Status Code:	OPR
Default Air Classification Code:	SMI
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

NEWELL RECYCLING OF ATLANTA LLC (Continued)**1000204676**

Activity Date:	2002-09-30 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported
Region Code:	04
Programmatic ID:	AIR GA0000001312100312
Facility Registry ID:	110006836095
Air Operating Status Code:	OPR
Default Air Classification Code:	SMI
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	2004-09-30 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported
Region Code:	04
Programmatic ID:	AIR GA0000001312100312
Facility Registry ID:	110006836095
Air Operating Status Code:	OPR
Default Air Classification Code:	SMI
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	2005-09-30 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported
Region Code:	04
Programmatic ID:	AIR GA0000001312100312
Facility Registry ID:	110006836095
Air Operating Status Code:	OPR
Default Air Classification Code:	SMI
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	2006-11-09 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported
Region Code:	04
Programmatic ID:	AIR GA0000001312100312
Facility Registry ID:	110006836095
Air Operating Status Code:	OPR
Default Air Classification Code:	SMI
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	2007-09-28 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported
Region Code:	04
Programmatic ID:	AIR GA0000001312100312
Facility Registry ID:	110006836095

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

NEWELL RECYCLING OF ATLANTA LLC (Continued)

1000204676

Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2010-02-04 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 04
Programmatic ID: AIR GA0000001312100312
Facility Registry ID: 110006836095
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2013-01-09 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 04
Programmatic ID: AIR GA0000001312100312
Facility Registry ID: 110006836095
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1989-10-03 00:00:00
Activity Status Date: 1989-10-03 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Region Code: 04
Programmatic ID: AIR GA0000001312100312
Facility Registry ID: 110006836095
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1989-10-23 00:00:00
Activity Status Date: 1989-10-23 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Region Code: 04
Programmatic ID: AIR GA0000001312100312
Facility Registry ID: 110006836095
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1990-02-14 00:00:00
Activity Status Date: 1990-02-14 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

NEWELL RECYCLING OF ATLANTA LLC (Continued)

1000204676

FINDS:

Registry ID: 110006836095

Environmental Interest/Information System

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

TSCA SUBMITTER

AIR SYNTHETIC MINOR

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and it Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

Registry ID: 110001323871

Environmental Interest/Information System

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

NEWELL RECYCLING OF ATLANTA LLC (Continued)

1000204676

National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

AIR SYNTHETIC MINOR

US EPA TRIS (Toxics Release Inventory System) contains information from facilities on the amounts of over 300 listed toxic chemicals that these facilities release directly to air, water, land, or that are transported off-site.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

The FINDS: database may contain additional details for this site.
Please contact your EDR Account Executive for more information

ECHO:

Envid: 1000204676
Registry ID: 110001323871
DFR URL: <http://echo.epa.gov/detailed-facility-report?fid=110001323871>

Envid: 1000204676
Registry ID: 110006836095
DFR URL: <http://echo.epa.gov/detailed-facility-report?fid=110006836095>

A6
SSW
1/8-1/4
0.144 mi.
761 ft.

NEWELL RECYCLING OF ATLANTA INC
1359 CENTRAL AVE
EAST POINT, GA 30344
Site 2 of 6 in cluster A

LUST **U004194042**
UST **N/A**
Financial Assurance
TIER 2

LUST:

Facility ID: 00600531
Leak ID: Not reported
Description: Not reported
Cleanup Status: NFA - No Further Action
Date Received: 04/22/2003
Project Officer: EPD Migration
Project Name: UST - 1 - NEWELL RECYCLING OF ATLANTA INC
Site Code Description: Potential GUST trust fund contractor site
No Further Action Date: 11/04/2003

Facility:

Facility Id: 600531
Facility Status: Inactive

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

NEWELL RECYCLING OF ATLANTA INC (Continued)

U004194042

Facility Type:	Industrial
District:	Not reported
Owner Name:	NEWELL RECYCLING OF ATLANTA INC
Contact ID:	Not reported
Owner Address:	1359 CENTRAL AVE
Owner City:	EAST POINT
Owner State:	GA
Owner Zip:	30344
Owner Telephone:	404 7661621

Tank:

Tank ID:	D
Tank Status:	Removed from Ground
Tank Material:	Composite
Pipe Type:	Suction (American)
Tank Overfill Type:	Not reported
Install Date:	09/01/1992
Facility ID:	600531
Status Date:	Not reported
Product:	Diesel
Pipe Material:	Fiberglass Reinforced Plastic
Overfill Protection:	Not reported
Overfill Installed:	09/01/1992
Tank Exempt From Spill:	Not reported
Date Spill Device Installed:	09/01/1992

Tank ID:	G
Tank Status:	Removed from Ground
Tank Material:	Composite
Pipe Type:	Suction (American)
Tank Overfill Type:	Not reported
Install Date:	09/01/1992
Facility ID:	600531
Status Date:	Not reported
Product:	Gas (Historical Use)
Pipe Material:	Fiberglass Reinforced Plastic
Overfill Protection:	Not reported
Overfill Installed:	09/01/1992
Tank Exempt From Spill:	Not reported
Date Spill Device Installed:	09/01/1992

GA Financial Assurance 1:

Region:	1
Facility ID:	600531
Financial Responsibility:	G.U.S.T. Trust Fund

GA TIER 2:

Reporting Year:	2017
Facility ID:	6109792
Facility Country:	Not reported
Company Name:	Newell Recycling Southeast
Date Submitted:	02/26/2018
Filing Type:	312
SIC Code:	Not reported
NAICS Code:	423930
Dun&Bradstreet Code:	96-921-4782

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

NEWELL RECYCLING OF ATLANTA INC (Continued)**U004194042**

Chemicals Same as Last Year: Not reported
Data Tier 2 Signed: Not reported
Dikes/Saveguard Measures: Not reported
Facility Department: Not reported
Facility Date Modified: 05/10/2018
State Fees Total: Not reported
Mailing Address: Not reported
Mailing City,St,Zip: Not reported
Mailing Country: Not reported
Latitude: 33.669225
Longitude: -84.432912
Lat/Long Location Desc: Not reported
Lat/Long Method: Not reported
Number Employees on Site: Not reported
Site Coordinate Abbrvtns Sbmtd: Not reported
Fire District: Not reported
Notes: Not reported
Validity: Not reported

Inventory:

Facility Id: 6109792
Year: 2017
Chemical Inventory ID: Not reported
Acute Health Risks: False
Average Daily Amount: 46569
Average Daily Amount Code: Not reported
CB Record ID: Not reported
Chemical Same as Last Year: Not reported
Chronic Health Risk: True
CAS Number: 68476346
EHS Substance: Not reported
Last Modified: Not reported
Days on Site: Not reported
Chemical Name: Diesel Fuel
Fire Hazard: Not reported
Gas: False
Liquid: True
Max Daily Amount: 93138
Max Daily Amount Code: Not reported
Max Amount in Largest Container: Not reported
Mixture Form: True
Sudden Release of Pressure Hazard: Not reported
Pure Form: True
Reactive Hazard: False
Solid: False
Facility Name: SA Recycling (East Point)
Contact Info: Name: Bart Hanks Contact Type: Fac. Emergency Coordinator Email: bhanks@newellrecycling.com 24-hour Phone :404-265-6500
Contact Type: Fac. Emergency Coordinator
Email: bhanks@newellrecycling.com
Phone1: 404-265-6500
Phone2: 404-766-1621
Phone3: Not reported
Phone4: Not reported
Phone5: Not reported
Hazardous 1 least hazardous/4 most hazardous: 0
Flammable 1 least flammable/4 most flammable: 2
Reactive 1 least reactive/4 very reactive: 0

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

NEWELL RECYCLING OF ATLANTA INC (Continued)

U004194042

Any characteristic over/above H F and R category: -

A7
SSW
1/8-1/4
0.144 mi.
761 ft.

NEWELL RECYCLING OF ATLANTA, INC.
1359 CENTRAL AVE., STE. A
EAST POINT, GA 30344

SWRCY S104886373
SPILLS N/A

Site 3 of 6 in cluster A

SWRCY:

City/State/Zip: EAST POINT
Contact Name: Christiana Culberson
Phone: 404-766-1621
Fax: Not reported
Email: recyclers@newellrecycling.com
Web Address: www.newellrecycling.com
Pick Up: True
Rail Access: True
Operation Hrs: 8-4; M-F; 8-Noon Sat.
Type Recy: Collector, Processor
Notes: Accepts all ferrous and non-ferrous metal
Date Contacted: 2011-02-15 00:00:00
Materials Accepted: metals, ferrous metals, metal appliances, autos, non ferrous metals, aluminum cans

SPILLS:

CTS Number: Not reported
Spill Number: 08
UN Number: Not reported
UN Number2: Not reported
Report Number: Not reported
Report Date: Not reported
Report Time: Not reported
Spill Date: 11/30/95
Spill Time: Not reported
Incident Type: Not reported
Material Involved: UNKNOWN
Quantity: Not reported
Phase: Not reported
Radioactive: Not reported
Material 2: Not reported
Quantity 2: Not reported
Phase 2: Not reported
Radioactive 2: Not reported
Waterway Impctd: NO
Evacuation: Not reported
Caller: Not reported
Organization: Not reported
Org Phone: Not reported
Primary Concern: Not reported
Associate Name: Not reported
Investigation Date: Not reported
Resolved: Not reported
Closure Date: Not reported
Ten Days Follow Up: Not reported
Transferred Record: Not reported
Fire: Not reported
Police: Not reported

PRELIMINARY MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

NEWELL RECYCLING OF ATLANTA, INC. (Continued)

S104886373

Sheriff:	Not reported
GSP:	Not reported
Medical:	Not reported
EPA:	Not reported
USCG:	Not reported
EMA:	Not reported
DRN:	Not reported
DOT:	Not reported
Responsible Prty:	Not reported
RP Contact:	Not reported
RP Address:	Not reported
RP Phone:	Not reported
RP City:	Not reported
Action Code:	Not reported
Action:	ERT EMERGENCY
Investigator:	Not reported
EOC Operator:	Not reported
Time EOC Notifd:	Not reported
Time Dispatched:	Not reported
Complaint Code:	Not reported
Complaint ID:	Not reported
Cmplaint Referred:	Not reported
Report Sum:	Not reported
At:	Not reported
DDO:	Not reported
Date Recieved:	Not reported
Comments:	Not reported
Comments 1:	Not reported
Referred:	Not reported
Comments 2:	Not reported
Substance:	Not reported
Comments 3:	Not reported
Location:	Not reported
Comments 4:	Not reported
Source:	Not reported
Comments 5:	Not reported
Details:	Not reported
Additional Info:	Not reported
Comments 6:	Not reported
Comments 7:	Not reported
Incident:	Not reported
Primary Concern 1 Description:	Not reported
Primary Concern 2:	Not reported
Primary Concern 2 Description:	Not reported
Source Address 1:	Not reported
Source Address 2:	Not reported
Source City:	Not reported
Source State:	Not reported
Source Zip:	Not reported
Direction:	Not reported
Caller Address 1:	Not reported
Caller Address 2:	Not reported
Caller City:	Not reported
Caller State:	Not reported
Caller Zip:	Not reported
Comp City:	Not reported
Branch:	Not reported

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

NEWELL RECYCLING OF ATLANTA, INC. (Continued)**S104886373**

BDesc: Not reported
Program: Not reported
Prog Desc: Not reported
Accept Date: Not reported
Assign Date: Not reported
FUI Need: Not reported
Refer 2: Not reported
Contact: Not reported
Active: Not reported
Facility ID: Not reported
Approved Date: Not reported
Facility Status: Not reported

A8 **SOUTHERN ZINC CO**
SSW **1359 CENTRAL AVE**
1/8-1/4 **EAST POINT, GA 30344**
0.144 mi.
761 ft.

Site 4 of 6 in cluster A

LUST **U003550746**
UST **N/A**
AIRS
Financial Assurance
NPDES
TIER 2

LUST:

Facility ID: 00600469
Leak ID: Not reported
Description: Not reported
Cleanup Status: NFA - Clean Closure
Date Received: Not reported
Project Officer: EPD Migration
Project Name: UST - CLOSURE - SOUTHERN ZINC CO
Site Code Description: Owner/Operator funded site
No Further Action Date: 04/23/1997

Facility:

Facility Id: 600469
Facility Status: Inactive
Facility Type: Industrial
District: Not reported
Owner Name: US ZINC CORP
Contact ID: Not reported
Owner Address: PO BOX 611
Owner City: HOUSTON
Owner State: TX
Owner Zip: 77001
Owner Telephone: 713 9261705

Tank:

Tank ID: 1
Tank Status: Closed in Ground
Tank Material: Bare Steel
Pipe Type: Not reported
Tank Overfill Type: Not reported
Install Date: 05/22/1978
Facility ID: 600469
Status Date: Not reported
Product: Diesel
Pipe Material: Galvanized Steel
Overfill Protection: Not reported
Overfill Installed: Not reported
Tank Exempt From Spill: Not reported

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

SOUTHERN ZINC CO (Continued)**U003550746**

Date Spill Device Installed: Not reported

AIRS:

Record Type: Not reported
 State County FIPS: Not reported
 State Facility Id: 12100006
 Facility Registry Id: Not reported
 Facility Category: Not reported
 Oris Facility code: Not reported
 SIC Primary: 3341
 NAICS Primary: 331419
 Dun&Bradstreet Number: Not reported
 Tri Id number: Not reported
 NTI Site id: Not reported
 Facility County: Not reported
 Site Description: Secondary Zinc Refiner
 Submittal Flag: Not reported
 Tribal Code: Not reported
 AIRS Number: 12100006
 Operational Status: X
 SIC Code: Not reported
 Contact Name: Dennis Hoffman
 Contact Company: Not reported
 Contact Telephone: 0
 Contact Fax: Not reported
 Contact Email: no@email.com
 Contact Address: Not reported
 Contact City,St,Zip: GA 0
 Year: 2016
 Classification: SM
 Contact Type: Permit Contact
 Permit Number: Not reported
 Issued Date: Not reported
 Latitude: 33.668561
 Longitude: -84.433087

Control Device Information:

Year: Not reported
 Record Type: Not reported
 State County Fips: Not reported
 State Facility Identifier: Not reported
 Emission Unit ID: Not reported
 Process ID: Not reported
 Pollutant Code: Not reported
 Primary Pct control Efficiency: Not reported
 Pct Capture Efficiency: Not reported
 Total Capture Control Efficiency: Not reported
 Primary Device Type Code: Not reported
 Secondary Device Type Code: Not reported
 Control System Description: Not reported
 Third Control Device Type Code: Not reported
 Fourth Control Device Type Code: Not reported
 Submittal Flag: Not reported
 Tribal Code: Not reported

PRELIMINARY MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

SOUTHERN ZINC CO (Continued)**U003550746**

Airs Emissions:

Year:	Not reported
Record Type:	Not reported
State County Fips:	Not reported
State Facility Identifier:	Not reported
Emission Unit ID:	Not reported
Process Id:	Not reported
Pollutant Code:	Not reported
Emission Release Point ID:	Not reported
Start Date:	Not reported
End Date:	Not reported
Start Time:	Not reported
End Time:	Not reported
Emission Numeric Value:	Not reported
Emission Unit Numerator:	Not reported
Emission Type:	Not reported
Em Reliability Indicator:	Not reported
Factor Numeric Value:	Not reported
Factor Unit Numerator:	Not reported
Factor Unit Denominator:	Not reported
Material:	Not reported
Material Id:	Not reported
Emission Calculation Method Code:	Not reported
Ef Reliability Indicator:	Not reported
Rule Effectiveness:	Not reported
Rule Effectiveness Method:	Not reported
Hap Emissions Performance Level:	Not reported
Control Status:	Not reported
Emission Data Level:	Not reported
Submittal Flag:	Not reported
Tribal Code:	Not reported

Airs EP:

Year:	Not reported
Record Type:	Not reported
State County Fips:	Not reported
State Facility Identifier:	Not reported
Emission Unit ID:	Not reported
Emission Release Point ID:	Not reported
Process ID:	Not reported
Scn Number:	Not reported
Process Mact Code:	Not reported
Emission Process Description:	Not reported
Winter Throughput Pct:	Not reported
Spring Throughput Pct:	Not reported
Summer Throughput Pct:	Not reported
Fall Throughput Pct:	Not reported
Annual Average Days Per Week:	Not reported
Annual Average Weeks Per Year:	Not reported
Annual Average Hours Per Day:	Not reported
Annual Average Hours Per Year:	Not reported
Heat Content:	Not reported
Sulfur Content:	Not reported
Ash Content:	Not reported
Process Mact compliance Status:	Not reported
Submittal Flag:	Not reported

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

SOUTHERN ZINC CO (Continued)**U003550746**

Tribal Code: Not reported

Emission Release Points:

Year: Not reported
Record Type: Not reported
State County Fips: Not reported
State Facility Identifier: Not reported
Emission Release Point ID: Not reported
Emission Release Point Type: Not reported
Stack Height: Not reported
Stack Diameter: Not reported
Stack Fenceline Distance: Not reported
Exit Gas Temperature: Not reported
Exit Gas Velocity: Not reported
Exit Gas Flowrate: Not reported
X Coordinate: Not reported
Y Coordinate: Not reported
Utm Zone: Not reported
X Y coordinate Type: Not reported
Horizontal Area Fugitive: Not reported
Release Height Fugitive: Not reported
Fugitive Dimensions Unit: Not reported
Emission Release Point Description: Not reported
Submittal Flag: Not reported
Horizontal Collection method Code: Not reported
Horizontal Accuracy Measure: Not reported
Horizontal Reference datum Code: Not reported
Reference Point Code: Not reported
Source Map scale Number: Not reported
Coordinate Data source Code: Not reported
Tribal Code: Not reported

Airs EU:

Year: Not reported
Record Type: Not reported
State County Fips: Not reported
State Facility Identifier: Not reported
Emission Unit ID: Not reported
Oris Boiler ID: Not reported
Sic Unit Level: Not reported
Naics Unit Level: Not reported
Design Capacity: Not reported
Design Capacity Unit Numerator: Not reported
Design Capacity Unit Denominator: Not reported
Max Nameplate Capacity: Not reported
Emission Unit Description: Not reported
Submittal Flag: Not reported
Tribal Code: Not reported

Process Annual Throughput:

Year: Not reported
Record Type: Not reported
State County fips: Not reported
State Facility identifier: Not reported
Emission Unit id: Not reported
Process ID: Not reported

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

SOUTHERN ZINC CO (Continued)

U003550746

Start Date:	Not reported
End Date:	Not reported
Start Time:	Not reported
End Time:	Not reported
Actual Throughput:	Not reported
Throughput Unit numerator:	Not reported
Material:	Not reported
Material lo:	Not reported
Period Days per week:	Not reported
Period Weeks per period:	Not reported
Period Hours per day:	Not reported
Period Hours per period:	Not reported
Submittal Flag:	Not reported
Tribal Code:	Not reported

Transaction Table:

Year:	Not reported
Record Type:	Not reported
State County fips:	Not reported
Organization Name:	Not reported
Transaction Type:	Not reported
Inventory Year:	Not reported
Inventory Type code:	Not reported
Transaction Create date:	Not reported
Incremental Submission number:	Not reported
Reliability Indicator:	Not reported
Transaction Comments:	Not reported
Contact Person name:	Not reported
Contact Phone number:	Not reported
Telephone Number type name:	Not reported
Electronic Address text:	Not reported
Electronic Address type name:	Not reported
Source Type:	Not reported
Affiliation Type:	Not reported
Format Version:	Not reported
Tribal Code:	Not reported

GA Financial Assurance 1:

Region:	1
Facility ID:	600469
Financial Responsibility:	Not Marked

NPDES:

NPDES Id:	Not reported
Notice of Intent Num:	2198
Facility Type Desc:	Not reported
NOI Type:	Notice of Intent
River Basin:	Not reported
Permit Sub Type:	Not reported

GA TIER 2:

Reporting Year:	2016
Facility ID:	5850267
Facility Country:	Not reported

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

SOUTHERN ZINC CO (Continued)**U003550746**

Company Name:	Newell Recycling Southeast
Date Submitted:	02/21/2017
Filing Type:	312
SIC Code:	Not reported
NAICS Code:	423930
Dun&Bradstreet Code:	96-921-4782
Chemicals Same as Last Year:	Not reported
Data Tier 2 Signed:	Not reported
Dikes/Saveguard Measures:	Not reported
Facility Department:	Not reported
Facility Date Modified:	03/09/2017
State Fees Total:	Not reported
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Mailing Country:	Not reported
Latitude:	33.669225
Longitude:	-84.432912
Lat/Long Location Desc:	Not reported
Lat/Long Method:	Not reported
Number Employees on Site:	Not reported
Site Coordinate Abbrvtns Sbmtd:	Not reported
Fire District:	Not reported
Notes:	Not reported
Validity:	Not reported
Inventory:	
Facility Id:	5850267
Year:	2016
Chemical Inventory ID:	Not reported
Acute Health Risks:	False
Average Daily Amount:	46569.0
Average Daily Amount Code:	Not reported
CB Record ID:	Not reported
Chemical Same as Last Year:	Not reported
Chronic Health Risk:	True
CAS Number:	68476346
EHS Substance:	Not reported
Last Modified:	Not reported
Days on Site:	Not reported
Chemical Name:	Diesel Fuel
Fire Hazard:	True
Gas:	False
Liquid:	True
Max Daily Amount:	93138.0
Max Daily Amount Code:	Not reported
Max Amount in Largest Container:	Not reported
Mixture Form:	True
Sudden Release of Pressure Hazard:	False
Pure Form:	True
Reactive Hazard:	False
Solid:	False
Facility Name:	Newell Recycling Southeast (East Point)
Contact Info:	Bart Hanks
Contact Type:	Fac. Emergency Coordinator
Email:	bhanks@newellrecycling.com
Phone1:	404-265-6500
Phone2:	404-766-1621
Phone3:	Not reported

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

SOUTHERN ZINC CO (Continued)

U003550746

Phone4: Not reported
Phone5: Not reported
Hazardous 1 least hazardous/4 most hazardous: 0
Flammable 1 least flammable/4 most flammable: 2
Reactive 1 least reactive/4 very reactive: 0
Any characteristic over/above H F and R category: -

Inventory:

Facility Id: 5850267
Year: 2016
Chemical Inventory ID: Not reported
Acute Health Risks: False
Average Daily Amount: 46569.0
Average Daily Amount Code: Not reported
CB Record ID: Not reported
Chemical Same as Last Year: Not reported
Chronic Health Risk: True
CAS Number: 68476346
EHS Substance: Not reported
Last Modified: Not reported
Days on Site: Not reported
Chemical Name: Diesel Fuel
Fire Hazard: True
Gas: False
Liquid: True
Max Daily Amount: 93138.0
Max Daily Amount Code: Not reported
Max Amount in Largest Container: Not reported
Mixture Form: True
Sudden Release of Pressure Hazard: False
Pure Form: True
Reactive Hazard: False
Solid: False
Facility Name: Newell Recycling Southeast (East Point)
Contact Info: Bart Hanks
Contact Type: Fac. Emergency Coordinator
Email: bhanks@newellrecycling.com
Phone1: 404-265-6500
Phone2: 404-766-1621
Phone3: Not reported
Phone4: Not reported
Phone5: Not reported
Hazardous 1 least hazardous/4 most hazardous: 0
Flammable 1 least flammable/4 most flammable: 2
Reactive 1 least reactive/4 very reactive: 0
Any characteristic over/above H F and R category: -

Reporting Year: 2015
Facility ID: 5402793
Facility Country: Not reported
Company Name: Newell Recycling of Atlanta, LLC
Date Submitted: 02/17/2016
Filing Type: 312
SIC Code: Not reported
NAICS Code: 423930
Dun&Bradstreet Code: 96-921-4782
Chemicals Same as Last Year: Not reported
Data Tier 2 Signed: Not reported

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

SOUTHERN ZINC CO (Continued)**U003550746**

Dikes/Saveguard Measures:	Not reported
Facility Department:	Not reported
Facility Date Modified:	02/17/2016
State Fees Total:	Not reported
Mailing Address:	Not reported
Mailing City, St, Zip:	Not reported
Mailing Country:	Not reported
Latitude:	33.669225
Longitude:	-84.432912
Lat/Long Location Desc:	Not reported
Lat/Long Method:	Not reported
Number Employees on Site:	Not reported
Site Coordinate Abbrvtns Sbmtd:	Not reported
Fire District:	Not reported
Notes:	Not reported
Validity:	Not reported
Inventory:	
Facility Id:	5402793
Year:	2015
Chemical Inventory ID:	Not reported
Acute Health Risks:	False
Average Daily Amount:	46569.0
Average Daily Amount Code:	Not reported
CB Record ID:	Not reported
Chemical Same as Last Year:	Not reported
Chronic Health Risk:	True
CAS Number:	68476346
EHS Substance:	Not reported
Last Modified:	Not reported
Days on Site:	Not reported
Chemical Name:	Diesel Fuel
Fire Hazard:	True
Gas:	False
Liquid:	True
Max Daily Amount:	93138.0
Max Daily Amount Code:	Not reported
Max Amount in Largest Container:	Not reported
Mixture Form:	True
Sudden Release of Pressure Hazard:	False
Pure Form:	True
Reactive Hazard:	False
Solid:	False
Facility Name:	Newell Recycling of Atlanta, LLC
Contact Info:	Joe Carrico
Contact Type:	Emergency Contact
Email:	jc@nratl.com
Phone1:	404-766-1621
Phone2:	770-354-0573
Phone3:	Not reported
Phone4:	Not reported
Phone5:	Not reported
Hazardous 1 least hazardous/4 most hazardous:	0
Flammable 1 least flammable/4 most flammable:	2
Reactive 1 least reactive/4 very reactive:	0
Any characteristic over/above H F and R category:	-

Inventory:

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

SOUTHERN ZINC CO (Continued)

U003550746

Facility Id: 5402793
Year: 2015
Chemical Inventory ID: Not reported
Acute Health Risks: False
Average Daily Amount: 46569.0
Average Daily Amount Code: Not reported
CB Record ID: Not reported
Chemical Same as Last Year: Not reported
Chronic Health Risk: True
CAS Number: 68476346
EHS Substance: Not reported
Last Modified: Not reported
Days on Site: Not reported
Chemical Name: Diesel Fuel
Fire Hazard: True
Gas: False
Liquid: True
Max Daily Amount: 93138.0
Max Daily Amount Code: Not reported
Max Amount in Largest Container: Not reported
Mixture Form: True
Sudden Release of Pressure Hazard: False
Pure Form: True
Reactive Hazard: False
Solid: False
Facility Name: Newell Recycling of Atlanta, LLC
Contact Info: Joe Carrico
Contact Type: Emergency Contact
Email: jc@nratl.com
Phone1: 404-766-1621
Phone2: 770-354-0573
Phone3: Not reported
Phone4: Not reported
Phone5: Not reported
Hazardous 1 least hazardous/4 most hazardous: 0
Flammable 1 least flammable/4 most flammable: 2
Reactive 1 least reactive/4 very reactive: 0
Any characteristic over/above H F and R category: -

A9 SOUTHERN ZINC
SSW 1359 CENTRAL AVE
1/8-1/4 EAST POINT, GA 30344
0.144 mi.
761 ft. Site 5 of 6 in cluster A

SPILLS 1000408213
RCRA NonGen / NLR GAD016762585

SPILLS:
CTS Number: Not reported
Spill Number: Not reported
UN Number: Not reported
UN Number2: Not reported
Report Number: Not reported
Report Date: Not reported
Report Time: Not reported
Spill Date: Not reported
Spill Time: Not reported
Incident Type: Not reported
Material Involved: Not reported
Quantity: Not reported

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

SOUTHERN ZINC (Continued)

1000408213

Phase:	Not reported
Radioactive:	Not reported
Material 2:	Not reported
Quantity 2:	Not reported
Phase 2:	Not reported
Radioactive 2:	Not reported
Waterway Impctd:	Not reported
Evacuation:	Not reported
Caller:	JENNIFER TANNER
Organization:	Not reported
Org Phone:	Not reported
Primary Concern:	Air Qualit
Associate Name:	Not reported
Investigation Date:	Not reported
Resolved:	Not reported
Closure Date:	06/11/2003
Ten Days Follow Up:	Not reported
Transferred Record:	Not reported
Fire:	Not reported
Police:	Not reported
Sheriff:	Not reported
GSP:	Not reported
Medical:	Not reported
EPA:	Not reported
USCG:	Not reported
EMA:	Not reported
DRN:	Not reported
DOT:	Not reported
Responsible Prty:	Not reported
RP Contact:	Not reported
RP Address:	Not reported
RP Phone:	Not reported
RP City:	Not reported
Action Code:	Not reported
Action:	Not reported
Investigator:	Not reported
EOC Operator:	Not reported
Time EOC Notifd:	Not reported
Time Dispatched:	Not reported
Complaint Code:	19263
Complaint ID:	Not reported
Cmplaint Referred:	Not reported
Report Sum:	Not reported
At:	Not reported
DDO:	Not reported
Date Recieved:	10/11/2002
Comments:	Not reported
Comments 1:	Not reported
Referred:	Not reported
Comments 2:	Not reported
Substance:	Not reported
Comments 3:	Not reported
Location:	1359 CENTRAL AVENUE
Comments 4:	Not reported
Source:	NEWELL RECYCLING
Comments 5:	Not reported
Details:	EXCESSIVE FUGITIVE EMIISIONS COMING FROM ADJOINING FACILITY. CALLER

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

SOUTHERN ZINC (Continued)

1000408213

DESCRIBED IT AS IF IT WAS SNOWING.

Additional Info:	Not reported
Comments 6:	Not reported
Comments 7:	Not reported
Incident:	Not reported
Primary Concern 1 Description:	Not reported
Primary Concern 2:	Not reported
Primary Concern 2 Description:	Not reported
Source Address 1:	1359 CENTRAL AVENUE
Source Address 2:	Not reported
Source City:	EAST POINT
Source State:	Georgia
Source Zip:	Not reported
Direction:	75 S TO CENTRAL AVENUE TAKE CENTRAL EAST TO FACILITY
Caller Address 1:	1336 CENTRAL AVENUE
Caller Address 2:	Not reported
Caller City:	EAST POINT
Caller State:	Georgia
Caller Zip:	Not reported
Comp City:	EAST POINT
Branch:	Not reported
BDesc:	Not reported
Program:	Not reported
Prog Desc:	Not reported
Accept Date:	10/11/2002
Assign Date:	10/11/2002
FUI Need:	Not reported
Refer 2:	Not reported
Contact:	JOE CARRICO
Active:	Not reported
Facility ID:	Not reported
Approved Date:	Not reported
Facility Status:	Not reported
Spill Action:	
Complaint Code:	19263
Code Desc:	Initial Investigation
Event Date:	10/11/2002
Comments:	I Recieved The Complaint Call While Filling In At The Receptionist Desk. After Pleading For Someone To Come Today, I Advised The Complainant That There Were Two Specialists Assigned To Fulton County And That One Was On Leave And The Other Had Just Left To Investigate A Complaint In Walker County. I Contacted The Atlanta Office To See If Someone From There Could Check Into The Concerns And Jim Asked If I Would Investigate. Investigate Complaint, Met With Jennifer Tanner At Business Which Is Located Across The Street From Newell And Observed Particulate On The Vehicles In The Parking Lot. The Employees Had Scooped Some Of The Particulate From The Vehicles And Had It In An Envelope. At The Time Of The Inspection, The Fugitive Emissions Were Negligible But Ms. Tanner Insisted That Earlier In The Morning That It Was Like "Snow Falling". I Apologized For Not Being Able To Get There Sooner And Advised Her That I Would Go Across The Street And Investigate Even Though The Problem Had Subsided, I Also Asked Her To Keep Us Informed Of Future Incidents. I Proceeded Across The Street To Newell And I Was Advised By Sam Foster, The Buyer That "No One Was At The Facility That Could Talk With Me About The Problem". I Persisted To Ask If There Actually Was No One At All On Site And He Said I Might Could Ask The Ladies At The Cashier Window. Ms. Janet Wagner Came Out

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

SOUTHERN ZINC (Continued)**1000408213**

And Gave Me A Card With Joe Carrico'S Name And Number And She Said That He Was The Only One That Could Talk To Me And That He Would Not Be Back In Until Monday.

Investigator: j.r. campbell
Entry Date: 10/15/2002

Complaint Code: 19263
Code Desc: Other
Event Date: 10/15/2002
Comments: Joe Carrico Called And Apologized For The Employees Not Finding Someone To Show Me Around. He Stated That We Were Welcome To Come To The Facility At Any Time And That He Was Going To Advise All Office Staff On Procedures.

Investigator: j.r. campbell
Entry Date: 10/16/2002

Complaint Code: 19263
Code Desc: Other
Event Date: 10/17/2002
Comments: Discussed Complaint With R. Kestle And S. Wix To Advise Of Situation. S. Wix Will Discuss With J. Sommerville Possibility Of Atl Office Handling Future Site Visits With Mtn. Office Handling Enforcement.

Investigator: j.r. campbell
Entry Date: 10/22/2002

Complaint Code: 19263
Code Desc: Other
Event Date: 10/22/2002
Comments: Complainant Called And Stated That The Problem Was Happening Again And That It Was "Like It Was Snowing". I Advised S. Wix And She Contacted Atlanta Office To See If Someone Could Go By And Check On The Site. T. Bethune Said Tilden Could Go. Tilden Caled Back After His Site Visit And Said The Problem Had Stopped By The Time He Got There.

Investigator: j.r. campbell
Entry Date: 10/22/2002

Complaint Code: 19263
Code Desc: Follow-Up Investigation
Event Date: 06/04/2003
Comments: Re-Check Complaint, No Problems Observed The Day Of The Inspection But The Staff At The Complainants Office Stated That On Monday It Was "Like Snow" Again And They Called The Atlanta Office But No One Returned Their Call. I Advised I Would Follow Up And Get Back With Them.

Investigator: j.r. campbell
Entry Date: 06/06/2003

Complaint Code: 19263
Code Desc: Other
Event Date: 06/06/2003
Comments: Called And Spoke With Joe Carrico And He Stated That They Had An Explosion Monday That Caused The Excursion, But That It Was Repaired. He Also Stated That Someone Else From Epd Had Been By And That They Were Scheduled To Come Back Monday And Observe The Operation. I Called The Complaint And Advised Of Findings And She Said That Someone Else From Epd Had Been There Also But That She Did Not Have The Card. I Advised I Would Try To Find Out And Get Back With Her.

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

SOUTHERN ZINC (Continued)**1000408213**

Investigator:	j.r. campbell
Entry Date:	06/06/2003
Complaint Code:	19263
Code Desc:	Referred To
Event Date:	06/09/2003
Comments:	Discussed With Stacey And Mansour, Complaint Referred To Mansour For Follow Up. See Complaint # 22545 For Further Info. Recommend This Complaint # Be Resolved.
Investigator:	j.r. campbell
Entry Date:	06/09/2003
CTS Number:	Not reported
Spill Number:	1059
UN Number:	Not reported
UN Number2:	Not reported
Report Number:	Not reported
Report Date:	Not reported
Report Time:	Not reported
Spill Date:	01/16/92
Spill Time:	Not reported
Incident Type:	Not reported
Material Involved:	GASOLINE/FUEL OIL
Quantity:	Not reported
Phase:	Not reported
Radioactive:	Not reported
Material 2:	Not reported
Quantity 2:	Not reported
Phase 2:	Not reported
Radioactive 2:	Not reported
Waterway Impctd:	Not reported
Evacuation:	Not reported
Caller:	Not reported
Organization:	Not reported
Org Phone:	Not reported
Primary Concern:	Not reported
Associate Name:	Not reported
Investigation Date:	Not reported
Resolved:	Not reported
Closure Date:	Not reported
Ten Days Follow Up:	Not reported
Transferred Record:	Not reported
Fire:	Not reported
Police:	Not reported
Sheriff:	Not reported
GSP:	Not reported
Medical:	Not reported
EPA:	Not reported
USCG:	Not reported
EMA:	Not reported
DRN:	Not reported
DOT:	Not reported
Responsible Prty:	Not reported
RP Contact:	Not reported
RP Address:	Not reported
RP Phone:	Not reported

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

SOUTHERN ZINC (Continued)**1000408213**

RP City:	Not reported
Action Code:	Not reported
Action:	NONE
Investigator:	Not reported
EOC Operator:	Not reported
Time EOC Notifd:	Not reported
Time Dispatched:	Not reported
Complaint Code:	Not reported
Complaint ID:	Not reported
Complaint Referred:	Not reported
Report Sum:	Not reported
At:	Not reported
DDO:	Not reported
Date Recieved:	Not reported
Comments:	Not reported
Comments 1:	Not reported
Referred:	ERT
Comments 2:	Not reported
Substance:	Not reported
Comments 3:	Not reported
Location:	Not reported
Comments 4:	Not reported
Source:	Not reported
Comments 5:	Not reported
Details:	Not reported
Additional Info:	Not reported
Comments 6:	Not reported
Comments 7:	Not reported
Incident:	Not reported
Primary Concern 1 Description:	Not reported
Primary Concern 2:	Not reported
Primary Concern 2 Description:	Not reported
Source Address 1:	Not reported
Source Address 2:	Not reported
Source City:	Not reported
Source State:	Not reported
Source Zip:	Not reported
Direction:	Not reported
Caller Address 1:	Not reported
Caller Address 2:	Not reported
Caller City:	Not reported
Caller State:	Not reported
Caller Zip:	Not reported
Comp City:	Not reported
Branch:	Not reported
BDesc:	Not reported
Program:	Not reported
Prog Desc:	Not reported
Accept Date:	Not reported
Assign Date:	Not reported
FUI Need:	Not reported
Refer 2:	Not reported
Contact:	Not reported
Active:	Not reported
Facility ID:	Not reported
Approved Date:	Not reported
Facility Status:	Not reported

PRELIMINARY MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

SOUTHERN ZINC (Continued)**1000408213**

CTS Number:	Not reported
Spill Number:	1442
UN Number:	Not reported
UN Number2:	Not reported
Report Number:	Not reported
Report Date:	Not reported
Report Time:	Not reported
Spill Date:	03/25/92
Spill Time:	Not reported
Incident Type:	Not reported
Material Involved:	HAZARDOUS MATERIAL
Quantity:	Not reported
Phase:	Not reported
Radioactive:	Not reported
Material 2:	Not reported
Quantity 2:	Not reported
Phase 2:	Not reported
Radioactive 2:	Not reported
Waterway Impctd:	Not reported
Evacuation:	Not reported
Caller:	Not reported
Organization:	Not reported
Org Phone:	Not reported
Primary Concern:	Not reported
Associate Name:	Not reported
Investigation Date:	Not reported
Resolved:	Not reported
Closure Date:	Not reported
Ten Days Follow Up:	Not reported
Transferred Record:	Not reported
Fire:	Not reported
Police:	Not reported
Sheriff:	Not reported
GSP:	Not reported
Medical:	Not reported
EPA:	Not reported
USCG:	Not reported
EMA:	Not reported
DRN:	Not reported
DOT:	Not reported
Responsible Prty:	Not reported
RP Contact:	Not reported
RP Address:	Not reported
RP Phone:	Not reported
RP City:	Not reported
Action Code:	Not reported
Action:	NONE
Investigator:	Not reported
EOC Operator:	Not reported
Time EOC Notifd:	Not reported
Time Dispatched:	Not reported
Complaint Code:	Not reported
Complaint ID:	Not reported
Complaint Referred:	Not reported
Report Sum:	Not reported
At:	Not reported
DDO:	Not reported

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

SOUTHERN ZINC (Continued)

1000408213

Date Recieved:	Not reported
Comments:	Not reported
Comments 1:	Not reported
Referred:	none
Comments 2:	Not reported
Substance:	Not reported
Comments 3:	Not reported
Location:	Not reported
Comments 4:	Not reported
Source:	Not reported
Comments 5:	Not reported
Details:	Not reported
Additional Info:	Not reported
Comments 6:	Not reported
Comments 7:	Not reported
Incident:	Not reported
Primary Concern 1 Description:	Not reported
Primary Concern 2:	Not reported
Primary Concern 2 Description:	Not reported
Source Address 1:	Not reported
Source Address 2:	Not reported
Source City:	Not reported
Source State:	Not reported
Source Zip:	Not reported
Direction:	Not reported
Caller Address 1:	Not reported
Caller Address 2:	Not reported
Caller City:	Not reported
Caller State:	Not reported
Caller Zip:	Not reported
Comp City:	Not reported
Branch:	Not reported
BDesc:	Not reported
Program:	Not reported
Prog Desc:	Not reported
Accept Date:	Not reported
Assign Date:	Not reported
FUI Need:	Not reported
Refer 2:	Not reported
Contact:	Not reported
Active:	Not reported
Facility ID:	Not reported
Approved Date:	Not reported
Facility Status:	Not reported
CTS Number:	Not reported
Spill Number:	1442
UN Number:	Not reported
UN Number2:	Not reported
Report Number:	Not reported
Report Date:	Not reported
Report Time:	Not reported
Spill Date:	03/25/92
Spill Time:	Not reported
Incident Type:	Not reported
Material Involved:	3
Quantity:	Not reported

PRELIMINARY MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

SOUTHERN ZINC (Continued)**1000408213**

Phase:	Not reported
Radioactive:	Not reported
Material 2:	Not reported
Quantity 2:	Not reported
Phase 2:	Not reported
Radioactive 2:	Not reported
Waterway Impctd:	Not reported
Evacuation:	Not reported
Caller:	Not reported
Organization:	Not reported
Org Phone:	Not reported
Primary Concern:	Not reported
Associate Name:	Not reported
Investigation Date:	Not reported
Resolved:	Not reported
Closure Date:	Not reported
Ten Days Follow Up:	Not reported
Transferred Record:	Not reported
Fire:	Not reported
Police:	Not reported
Sheriff:	Not reported
GSP:	Not reported
Medical:	Not reported
EPA:	Not reported
USCG:	Not reported
EMA:	Not reported
DRN:	Not reported
DOT:	Not reported
Responsible Prty:	Not reported
RP Contact:	Not reported
RP Address:	Not reported
RP Phone:	Not reported
RP City:	Not reported
Action Code:	Not reported
Action:	Not reported
Investigator:	Not reported
EOC Operator:	Not reported
Time EOC Notifd:	Not reported
Time Dispatched:	Not reported
Complaint Code:	Not reported
Complaint ID:	Not reported
Cmplaint Referred:	Not reported
Report Sum:	Not reported
At:	Not reported
DDO:	Not reported
Date Recieved:	Not reported
Comments:	Not reported
Comments 1:	Not reported
Referred:	Not reported
Comments 2:	Not reported
Substance:	Not reported
Comments 3:	Not reported
Location:	Not reported
Comments 4:	Not reported
Source:	Not reported
Comments 5:	Not reported
Details:	Not reported

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

SOUTHERN ZINC (Continued)

1000408213

Additional Info: Not reported
Comments 6: Not reported
Comments 7: Not reported
Incident: Not reported
Primary Concern 1 Description: Not reported
Primary Concern 2: Not reported
Primary Concern 2 Description: Not reported
Source Address 1: Not reported
Source Address 2: Not reported
Source City: Not reported
Source State: Not reported
Source Zip: Not reported
Direction: Not reported
Caller Address 1: Not reported
Caller Address 2: Not reported
Caller City: Not reported
Caller State: Not reported
Caller Zip: Not reported
Comp City: Not reported
Branch: Not reported
BDesc: Not reported
Program: Not reported
Prog Desc: Not reported
Accept Date: Not reported
Assign Date: Not reported
FUI Need: Not reported
Refer 2: Not reported
Contact: Not reported
Active: Not reported
Facility ID: Not reported
Approved Date: Not reported
Facility Status: Not reported

RCRA NonGen / NLR:

Date form received by agency: 05/05/2004
Facility name: SOUTHERN ZINC
Facility address: 1359 CENTRAL AVE
EAST POINT, GA 30344
EPA ID: GAD016762585
Mailing address: CENTRAL AVE
EAST POINT, GA 30344
Contact: KEITH SARGENT
Contact address: 1359 CENTRAL AVE
EAST POINT, GA 30344
Contact country: US
Contact telephone: 404-761-6434
Contact email: Not reported
EPA Region: 04
Land type: Other land type
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: OPERNAME
Owner/operator address: OPERSTREET
OPERCITY, WY 99999

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

SOUTHERN ZINC (Continued)

1000408213

Owner/operator country: Not reported
Owner/operator telephone: 404-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: U S ZINC
Owner/operator address: OWNERSTREET
OWNERCITY, WY 99999

Owner/operator country: Not reported
Owner/operator telephone: 404-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001

. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKEY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D002

. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

SOUTHERN ZINC (Continued)

1000408213

- . Waste code: D003
- . Waste name: A MATERIAL IS CONSIDERED TO BE A REACTIVE HAZARDOUS WASTE IF IT IS NORMALLY UNSTABLE, REACTS VIOLENTLY WITH WATER, GENERATES TOXIC GASES WHEN EXPOSED TO WATER OR CORROSIVE MATERIALS, OR IF IT IS CAPABLE OF DETONATION OR EXPLOSION WHEN EXPOSED TO HEAT OR A FLAME. ONE EXAMPLE OF SUCH WASTE WOULD BY WASTE GUNPOWDER.

Historical Generators:

Date form received by agency: 11/13/1989
Site name: SOUTHERN ZINC
Classification: Small Quantity Generator

- . Waste code: D000
- . Waste name: Not Defined
- . Waste code: D001
- . Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKEY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.
- . Waste code: D002
- . Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.
- . Waste code: D003
- . Waste name: A MATERIAL IS CONSIDERED TO BE A REACTIVE HAZARDOUS WASTE IF IT IS NORMALLY UNSTABLE, REACTS VIOLENTLY WITH WATER, GENERATES TOXIC GASES WHEN EXPOSED TO WATER OR CORROSIVE MATERIALS, OR IF IT IS CAPABLE OF DETONATION OR EXPLOSION WHEN EXPOSED TO HEAT OR A FLAME. ONE EXAMPLE OF SUCH WASTE WOULD BY WASTE GUNPOWDER.

Facility Has Received Notices of Violations:

Regulation violated: Not reported
Area of violation: Generators - Pre-transport
Date violation determined: 06/03/1993
Date achieved compliance: 09/03/1993
Violation lead agency: State
Enforcement action: FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date: 06/03/1993
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

SOUTHERN ZINC (Continued)

1000408213

Evaluation Action Summary:

Evaluation date: 06/03/1993
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: Generators - Pre-transport
Date achieved compliance: 09/03/1993
Evaluation lead agency: State

A10 **NEWELL RECYCLING FACILITY FIRE**
SSW **1359 CENTRAL AVE.**
1/8-1/4 **EAST POINT, GA 30344**
0.144 mi.
761 ft. **Site 6 of 6 in cluster A**

SEMS **1024089190**
FINDS **GAN000405932**

SEMS:

Site ID: 0405932
EPA ID: GAN000405932
Cong District: Not reported
FIPS Code: 13121
Latitude: +33.669092
Longitude: -84.431940
FF: N
NPL: Not on the NPL
Non NPL Status: Removal Only Site (No Site Assessment Work Needed)

SEMS Detail:

Region: 04
Site ID: 0405932
EPA ID: GAN000405932
Site Name: NEWELL RECYCLING FACILITY FIRE
NPL: N
FF: N
OU: 00
Action Code: PJ
Action Name: RP EM REM
SEQ: 1
Start Date: 2018-01-22 05:00:00
Finish Date: 1/23/2018 5:00:00 AM
Qual: S
Current Action Lead: EPA Ovrsght

FINDS:

Registry ID: 110070224744

Environmental Interest/Information System
SUPERFUND (NON-NPL)

The FINDS: database may contain additional details for this site.
Please contact your EDR Account Executive for more information

PRELIMINARY MAP FINDINGS

Map ID			EDR ID Number
Direction			
Distance			
Distance (ft.)	Site	Database(s)	EPA ID Number

B11 **SANITATION TRANSFER STATION**
SE **3125 MARTIN ST**
1/8-1/4 **EAST POINT, GA 30344**
0.156 mi.
825 ft. **Site 1 of 2 in cluster B**

SWF/LF **U001478758**
LUST **N/A**
UST
Financial Assurance
NPDES
TIER 2

SWF/LF:

Status:	Not reported
Facility Type Description:	Transfer Station
Facility Mgr Name:	JEFF CLEM
Facility Mgr Addr:	3045 DONAL LEE HOLLOWELL PKWY
Facility Mgr City/State/Zip:	ATLANTA, GA 30318
Facility Mgr Telephone:	404 792-2660
Incoming Waste Stream Type:	Not reported
Permit Number:	PBR-060-122TS
Operating Status:	Not reported
Dominion:	Public
Type:	TS
Owner Name:	BFI TRANSFER SYSTEMS OF GEORGIA LLC
Owner Address:	325 MARBLE MILL ROAD
Owner City:	MARIETTA
Owner State:	GA
Owner Zip:	30060
Owner Phone:	770 514-2910
Mailing Address:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Date Ceased Accepting Waste:	Not reported
EDR Link ID:	PBR-060-122TS
Date Closed:	Not reported
Post Closure Period:	Not reported

Status:	Not reported
Facility Type Description:	Transfer Station
Facility Mgr Name:	JEFF CLEM
Facility Mgr Addr:	Not reported
Facility Mgr City/State/Zip:	Not reported
Facility Mgr Telephone:	404 792-2660
Incoming Waste Stream Type:	Not reported
Permit Number:	PBR-060-122TS
Operating Status:	1
Dominion:	Not reported
Type:	Not reported
Owner Name:	BFI TRANSFER SYSTEMS OF GEORGIA LLC
Owner Address:	Not reported
Owner City:	Not reported
Owner State:	Not reported
Owner Zip:	Not reported
Owner Phone:	514-2910
Mailing Address:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Date Ceased Accepting Waste:	Not reported
EDR Link ID:	PBR-060-122TS
Date Closed:	Not reported
Post Closure Period:	Not reported

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

SANITATION TRANSFER STATION (Continued)**U001478758****LUST:**

Facility ID:	00601110
Leak ID:	Not reported
Description:	Not reported
Cleanup Status:	NFA - No Further Action
Date Received:	01/20/1999
Project Officer:	Ron Wallace
Project Name:	UST - 1 - SANITATION TRANSFER STATION
Site Code Description:	Owner/Operator funded site
No Further Action Date:	06/27/2005

Facility:

Facility Id:	601110
Facility Status:	Inactive
Facility Type:	County
District:	Not reported
Owner Name:	CITY OF EAST POINT
Contact ID:	Not reported
Owner Address:	2777 EAST POINT ST
Owner City:	EAST POINT
Owner State:	GA
Owner Zip:	30344
Owner Telephone:	404 7652744

Tank:

Tank ID:	1
Tank Status:	Removed from Ground
Tank Material:	Bare Steel
Pipe Type:	Not reported
Tank Overfill Type:	Not reported
Install Date:	05/02/1972
Facility ID:	601110
Status Date:	Not reported
Product:	Gas (Historical Use)
Pipe Material:	Unknown
Overfill Protection:	Not reported
Overfill Installed:	Not reported
Tank Exempt From Spill:	Not reported
Date Spill Device Installed:	Not reported

Tank ID:	2
Tank Status:	Removed from Ground
Tank Material:	Bare Steel
Pipe Type:	Not reported
Tank Overfill Type:	Not reported
Install Date:	05/02/1972
Facility ID:	601110
Status Date:	Not reported
Product:	Gas (Historical Use)
Pipe Material:	Unknown
Overfill Protection:	Not reported
Overfill Installed:	Not reported
Tank Exempt From Spill:	Not reported
Date Spill Device Installed:	Not reported

PRELIMINARY MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

SANITATION TRANSFER STATION (Continued)**U001478758**

GA Financial Assurance 1:

Region: 1
 Facility ID: 601110
 Financial Responsibility: G.U.S.T. Trust Fund

NPDES:

NPDES Id: Not reported
 Notice of Intent Num: 2780
 Facility Type Desc: Not reported
 NOI Type: Notice of Intent
 River Basin: Not reported
 Permit Sub Type: Not reported

GA TIER 2:

Reporting Year: 2017
 Facility ID: 6089889
 Facility Country: Not reported
 Company Name: BFI Transfer Systems of Georgia, LLC
 Date Submitted: 02/22/2018
 Filing Type: 311 312
 SIC Code: Not reported
 NAICS Code: 562111
 Dun&Bradstreet Code: 018442465
 Chemicals Same as Last Year: Not reported
 Data Tier 2 Signed: Not reported
 Dikes/Saveguard Measures: Not reported
 Facility Department: Not reported
 Facility Date Modified: 02/22/2018
 State Fees Total: Not reported
 Mailing Address: Not reported
 Mailing City,St,Zip: Not reported
 Mailing Country: Not reported
 Latitude: 33.66981101
 Longitude: -84.43006979
 Lat/Long Location Desc: Not reported
 Lat/Long Method: Not reported
 Number Employees on Site: Not reported
 Site Coordinate Abbrvtns Sbmtd: Not reported
 Fire District: Not reported
 Notes: Not reported
 Validity: Not reported

Inventory:

Facility Id: 6089889
 Year: 2017
 Chemical Inventory ID: Not reported
 Acute Health Risks: True
 Average Daily Amount: 5325
 Average Daily Amount Code: Not reported
 CB Record ID: Not reported
 Chemical Same as Last Year: Not reported
 Chronic Health Risk: True
 CAS Number: 68476346
 EHS Substance: Not reported
 Last Modified: Not reported
 Days on Site: Not reported

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

SANITATION TRANSFER STATION (Continued)

U001478758

Chemical Name: Diesel Fuel #2
Fire Hazard: Not reported
Gas: False
Liquid: True
Max Daily Amount: 10650
Max Daily Amount Code: Not reported
Max Amount in Largest Container: Not reported
Mixture Form: True
Sudden Release of Pressure Hazard: Not reported
Pure Form: False
Reactive Hazard: False
Solid: False
Facility Name: East Point Transfer Station
Contact Info: Name: Howard Palmour Contact Type: Emergency Contact Email: hpalmour@republicservices.com Work Phone :678-945-8086 24-ho
Contact Type: Emergency Contact
Email: hpalmour@republicservices.com
Phone1: 678-945-8086
Phone2: 770-294-2977
Phone3: Not reported
Phone4: Not reported
Phone5: Not reported
Hazardous 1 least hazardous/4 most hazardous: 0
Flammable 1 least flammable/4 most flammable: 2
Reactive 1 least reactive/4 very reactive: 0
Any characteristic over/above H F and R category: -

Inventory:

Facility Id: 6089889
Year: 2017
Chemical Inventory ID: Not reported
Acute Health Risks: True
Average Daily Amount: 5325
Average Daily Amount Code: Not reported
CB Record ID: Not reported
Chemical Same as Last Year: Not reported
Chronic Health Risk: True
CAS Number: 68476346
EHS Substance: Not reported
Last Modified: Not reported
Days on Site: Not reported
Chemical Name: Diesel Fuel #2
Fire Hazard: Not reported
Gas: False
Liquid: True
Max Daily Amount: 10650
Max Daily Amount Code: Not reported
Max Amount in Largest Container: Not reported
Mixture Form: True
Sudden Release of Pressure Hazard: Not reported
Pure Form: False
Reactive Hazard: False
Solid: False
Facility Name: East Point Transfer Station
Contact Info: Name: Howard Palmour Contact Type: Emergency Contact Email: hpalmour@republicservices.com Work Phone :678-945-8086 24-ho
Contact Type: Emergency Contact
Email: hpalmour@republicservices.com

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

SANITATION TRANSFER STATION (Continued)

U001478758

Phone1: 678-945-8086
Phone2: 770-294-2977
Phone3: Not reported
Phone4: Not reported
Phone5: Not reported
Hazardous 1 least hazardous/4 most hazardous: 0
Flammable 1 least flammable/4 most flammable: 2
Reactive 1 least reactive/4 very reactive: 0
Any characteristic over/above H F and R category: -

Inventory:

Facility Id: 6089889
Year: 2017
Chemical Inventory ID: Not reported
Acute Health Risks: True
Average Daily Amount: 5325
Average Daily Amount Code: Not reported
CB Record ID: Not reported
Chemical Same as Last Year: Not reported
Chronic Health Risk: True
CAS Number: 68476346
EHS Substance: Not reported
Last Modified: Not reported
Days on Site: Not reported
Chemical Name: Diesel Fuel #2
Fire Hazard: Not reported
Gas: False
Liquid: True
Max Daily Amount: 10650
Max Daily Amount Code: Not reported
Max Amount in Largest Container: Not reported
Mixture Form: True
Sudden Release of Pressure Hazard: Not reported
Pure Form: False
Reactive Hazard: False
Solid: False
Facility Name: East Point Transfer Station
Contact Info: Name: Howard Palmour Contact Type: Emergency Contact Email: hpalmour@republicservices.com Work Phone :678-945-8086 24-ho
Contact Type: Emergency Contact
Email: hpalmour@republicservices.com
Phone1: 678-945-8086
Phone2: 770-294-2977
Phone3: Not reported
Phone4: Not reported
Phone5: Not reported
Hazardous 1 least hazardous/4 most hazardous: 0
Flammable 1 least flammable/4 most flammable: 2
Reactive 1 least reactive/4 very reactive: 0
Any characteristic over/above H F and R category: -

Inventory:

Facility Id: 6089889
Year: 2017
Chemical Inventory ID: Not reported
Acute Health Risks: True
Average Daily Amount: 5325
Average Daily Amount Code: Not reported

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

SANITATION TRANSFER STATION (Continued)

U001478758

CB Record ID:	Not reported
Chemical Same as Last Year:	Not reported
Chronic Health Risk:	True
CAS Number:	68476346
EHS Substance:	Not reported
Last Modified:	Not reported
Days on Site:	Not reported
Chemical Name:	Diesel Fuel #2
Fire Hazard:	Not reported
Gas:	False
Liquid:	True
Max Daily Amount:	10650
Max Daily Amount Code:	Not reported
Max Amount in Largest Container:	Not reported
Mixture Form:	True
Sudden Release of Pressure Hazard:	Not reported
Pure Form:	False
Reactive Hazard:	False
Solid:	False
Facility Name:	East Point Transfer Station
Contact Info:	Name: Howard Palmour Contact Type: Emergency Contact Email: hpalmour@republicservices.com Work Phone :678-945-8086 24-ho
Contact Type:	Emergency Contact
Email:	hpalmour@republicservices.com
Phone1:	678-945-8086
Phone2:	770-294-2977
Phone3:	Not reported
Phone4:	Not reported
Phone5:	Not reported
Hazardous 1 least hazardous/4 most hazardous:	0
Flammable 1 least flammable/4 most flammable:	2
Reactive 1 least reactive/4 very reactive:	0
Any characteristic over/above H F and R category:	-

Inventory:

Facility Id:	6089889
Year:	2017
Chemical Inventory ID:	Not reported
Acute Health Risks:	True
Average Daily Amount:	5325
Average Daily Amount Code:	Not reported
CB Record ID:	Not reported
Chemical Same as Last Year:	Not reported
Chronic Health Risk:	True
CAS Number:	68476346
EHS Substance:	Not reported
Last Modified:	Not reported
Days on Site:	Not reported
Chemical Name:	Diesel Fuel #2
Fire Hazard:	Not reported
Gas:	False
Liquid:	True
Max Daily Amount:	10650
Max Daily Amount Code:	Not reported
Max Amount in Largest Container:	Not reported
Mixture Form:	True
Sudden Release of Pressure Hazard:	Not reported
Pure Form:	False

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

SANITATION TRANSFER STATION (Continued)

U001478758

Reactive Hazard: False
Solid: False
Facility Name: East Point Transfer Station
Contact Info: Name: Howard Palmour Contact Type: Emergency Contact Email: hpalmour@republicservices.com Work Phone :678-945-8086 24-ho
Contact Type: Emergency Contact
Email: hpalmour@republicservices.com
Phone1: 678-945-8086
Phone2: 770-294-2977
Phone3: Not reported
Phone4: Not reported
Phone5: Not reported
Hazardous 1 least hazardous/4 most hazardous: 0
Flammable 1 least flammable/4 most flammable: 2
Reactive 1 least reactive/4 very reactive: 0
Any characteristic over/above H F and R category: -

Inventory:

Facility Id: 6089889
Year: 2017
Chemical Inventory ID: Not reported
Acute Health Risks: True
Average Daily Amount: 5325
Average Daily Amount Code: Not reported
CB Record ID: Not reported
Chemical Same as Last Year: Not reported
Chronic Health Risk: True
CAS Number: 68476346
EHS Substance: Not reported
Last Modified: Not reported
Days on Site: Not reported
Chemical Name: Diesel Fuel #2
Fire Hazard: Not reported
Gas: False
Liquid: True
Max Daily Amount: 10650
Max Daily Amount Code: Not reported
Max Amount in Largest Container: Not reported
Mixture Form: True
Sudden Release of Pressure Hazard: Not reported
Pure Form: False
Reactive Hazard: False
Solid: False
Facility Name: East Point Transfer Station
Contact Info: Name: Howard Palmour Contact Type: Emergency Contact Email: hpalmour@republicservices.com Work Phone :678-945-8086 24-ho
Contact Type: Emergency Contact
Email: hpalmour@republicservices.com
Phone1: 678-945-8086
Phone2: 770-294-2977
Phone3: Not reported
Phone4: Not reported
Phone5: Not reported
Hazardous 1 least hazardous/4 most hazardous: 0
Flammable 1 least flammable/4 most flammable: 2
Reactive 1 least reactive/4 very reactive: 0
Any characteristic over/above H F and R category: -

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

SANITATION TRANSFER STATION (Continued)

U001478758

Reporting Year: 2016
Facility ID: 5850031
Facility Country: Not reported
Company Name: BFI Transfer Systems of Georgia, LLC
Date Submitted: 02/28/2017
Filing Type: 311 312
SIC Code: Not reported
NAICS Code: 562111
Dun&Bradstreet Code: 020138298
Chemicals Same as Last Year: Not reported
Data Tier 2 Signed: Not reported
Dikes/Saveguard Measures: Not reported
Facility Department: Not reported
Facility Date Modified: 02/28/2017
State Fees Total: Not reported
Mailing Address: Not reported
Mailing City,St,Zip: Not reported
Mailing Country: Not reported
Latitude: 33.66981101
Longitude: -84.43006979
Lat/Long Location Desc: Not reported
Lat/Long Method: Not reported
Number Employees on Site: Not reported
Site Coordinate Abbrvtns Sbmtd: Not reported
Fire District: Not reported
Notes: Not reported
Validity: Not reported

Inventory:

Facility Id: 5850031
Year: 2016
Chemical Inventory ID: Not reported
Acute Health Risks: True
Average Daily Amount: 3550.0
Average Daily Amount Code: Not reported
CB Record ID: Not reported
Chemical Same as Last Year: Not reported
Chronic Health Risk: False
CAS Number: 68476346
EHS Substance: Not reported
Last Modified: Not reported
Days on Site: Not reported
Chemical Name: Diesel Fuel #2
Fire Hazard: True
Gas: False
Liquid: True
Max Daily Amount: 7100.0
Max Daily Amount Code: Not reported
Max Amount in Largest Container: Not reported
Mixture Form: False
Sudden Release of Pressure Hazard: False
Pure Form: True
Reactive Hazard: False
Solid: False
Facility Name: East Point Transfer Station
Contact Info: Howard Palmour
Contact Type: Emergency Contact
Email: hpalmour@republicservices.com

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

SANITATION TRANSFER STATION (Continued)**U001478758**

Phone1:	770-294-2977	
Phone2:	678-945-8086	
Phone3:	Not reported	
Phone4:	Not reported	
Phone5:	Not reported	
Hazardous 1 least hazardous/4 most hazardous:		0
Flammable 1 least flammable/4 most flammable:		2
Reactive 1 least reactive/4 very reactive:		0
Any characteristic over/above H F and R category:		-
Inventory:		
Facility Id:	5850031	
Year:	2016	
Chemical Inventory ID:	Not reported	
Acute Health Risks:	True	
Average Daily Amount:	3550.0	
Average Daily Amount Code:	Not reported	
CB Record ID:	Not reported	
Chemical Same as Last Year:	Not reported	
Chronic Health Risk:	False	
CAS Number:	68476346	
EHS Substance:	Not reported	
Last Modified:	Not reported	
Days on Site:	Not reported	
Chemical Name:	Diesel Fuel #2	
Fire Hazard:	True	
Gas:	False	
Liquid:	True	
Max Daily Amount:	7100.0	
Max Daily Amount Code:	Not reported	
Max Amount in Largest Container:	Not reported	
Mixture Form:	False	
Sudden Release of Pressure Hazard:	False	
Pure Form:	True	
Reactive Hazard:	False	
Solid:	False	
Facility Name:	East Point Transfer Station	
Contact Info:	Howard Palmour	
Contact Type:	Emergency Contact	
Email:	hpalmour@republicservices.com	
Phone1:	770-294-2977	
Phone2:	678-945-8086	
Phone3:	Not reported	
Phone4:	Not reported	
Phone5:	Not reported	
Hazardous 1 least hazardous/4 most hazardous:		0
Flammable 1 least flammable/4 most flammable:		2
Reactive 1 least reactive/4 very reactive:		0
Any characteristic over/above H F and R category:		-
Inventory:		
Facility Id:	5850031	
Year:	2016	
Chemical Inventory ID:	Not reported	
Acute Health Risks:	True	
Average Daily Amount:	3550.0	
Average Daily Amount Code:	Not reported	
CB Record ID:	Not reported	

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

SANITATION TRANSFER STATION (Continued)**U001478758**

Chemical Same as Last Year:	Not reported
Chronic Health Risk:	False
CAS Number:	68476346
EHS Substance:	Not reported
Last Modified:	Not reported
Days on Site:	Not reported
Chemical Name:	Diesel Fuel #2
Fire Hazard:	True
Gas:	False
Liquid:	True
Max Daily Amount:	7100.0
Max Daily Amount Code:	Not reported
Max Amount in Largest Container:	Not reported
Mixture Form:	False
Sudden Release of Pressure Hazard:	False
Pure Form:	True
Reactive Hazard:	False
Solid:	False
Facility Name:	East Point Transfer Station
Contact Info:	Howard Palmour
Contact Type:	Emergency Contact
Email:	hpalmour@republicservices.com
Phone1:	770-294-2977
Phone2:	678-945-8086
Phone3:	Not reported
Phone4:	Not reported
Phone5:	Not reported
Hazardous 1 least hazardous/4 most hazardous:	0
Flammable 1 least flammable/4 most flammable:	2
Reactive 1 least reactive/4 very reactive:	0
Any characteristic over/above H F and R category:	-

Inventory:

Facility Id:	5850031
Year:	2016
Chemical Inventory ID:	Not reported
Acute Health Risks:	True
Average Daily Amount:	3550.0
Average Daily Amount Code:	Not reported
CB Record ID:	Not reported
Chemical Same as Last Year:	Not reported
Chronic Health Risk:	False
CAS Number:	68476346
EHS Substance:	Not reported
Last Modified:	Not reported
Days on Site:	Not reported
Chemical Name:	Diesel Fuel #2
Fire Hazard:	True
Gas:	False
Liquid:	True
Max Daily Amount:	7100.0
Max Daily Amount Code:	Not reported
Max Amount in Largest Container:	Not reported
Mixture Form:	False
Sudden Release of Pressure Hazard:	False
Pure Form:	True
Reactive Hazard:	False
Solid:	False

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

SANITATION TRANSFER STATION (Continued)**U001478758**

Facility Name: East Point Transfer Station
 Contact Info: Howard Palmour
 Contact Type: Emergency Contact
 Email: hpalmour@republicservices.com
 Phone1: 770-294-2977
 Phone2: 678-945-8086
 Phone3: Not reported
 Phone4: Not reported
 Phone5: Not reported
 Hazardous 1 least hazardous/4 most hazardous: 0
 Flammable 1 least flammable/4 most flammable: 2
 Reactive 1 least reactive/4 very reactive: 0
 Any characteristic over/above H F and R category: -

Inventory:

Facility Id: 5850031
 Year: 2016
 Chemical Inventory ID: Not reported
 Acute Health Risks: True
 Average Daily Amount: 3550.0
 Average Daily Amount Code: Not reported
 CB Record ID: Not reported
 Chemical Same as Last Year: Not reported
 Chronic Health Risk: False
 CAS Number: 68476346
 EHS Substance: Not reported
 Last Modified: Not reported
 Days on Site: Not reported
 Chemical Name: Diesel Fuel #2
 Fire Hazard: True
 Gas: False
 Liquid: True
 Max Daily Amount: 7100.0
 Max Daily Amount Code: Not reported
 Max Amount in Largest Container: Not reported
 Mixture Form: False
 Sudden Release of Pressure Hazard: False
 Pure Form: True
 Reactive Hazard: False
 Solid: False
 Facility Name: East Point Transfer Station
 Contact Info: Howard Palmour
 Contact Type: Emergency Contact
 Email: hpalmour@republicservices.com
 Phone1: 770-294-2977
 Phone2: 678-945-8086
 Phone3: Not reported
 Phone4: Not reported
 Phone5: Not reported
 Hazardous 1 least hazardous/4 most hazardous: 0
 Flammable 1 least flammable/4 most flammable: 2
 Reactive 1 least reactive/4 very reactive: 0
 Any characteristic over/above H F and R category: -

Inventory:

Facility Id: 5850031
 Year: 2016
 Chemical Inventory ID: Not reported

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

SANITATION TRANSFER STATION (Continued)

U001478758

Acute Health Risks:	True
Average Daily Amount:	3550.0
Average Daily Amount Code:	Not reported
CB Record ID:	Not reported
Chemical Same as Last Year:	Not reported
Chronic Health Risk:	False
CAS Number:	68476346
EHS Substance:	Not reported
Last Modified:	Not reported
Days on Site:	Not reported
Chemical Name:	Diesel Fuel #2
Fire Hazard:	True
Gas:	False
Liquid:	True
Max Daily Amount:	7100.0
Max Daily Amount Code:	Not reported
Max Amount in Largest Container:	Not reported
Mixture Form:	False
Sudden Release of Pressure Hazard:	False
Pure Form:	True
Reactive Hazard:	False
Solid:	False
Facility Name:	East Point Transfer Station
Contact Info:	Howard Palmour
Contact Type:	Emergency Contact
Email:	hpalmour@republicservices.com
Phone1:	770-294-2977
Phone2:	678-945-8086
Phone3:	Not reported
Phone4:	Not reported
Phone5:	Not reported
Hazardous 1 least hazardous/4 most hazardous:	0
Flammable 1 least flammable/4 most flammable:	2
Reactive 1 least reactive/4 very reactive:	0
Any characteristic over/above H F and R category:	-
Reporting Year:	2015
Facility ID:	5417995
Facility Country:	Not reported
Company Name:	BFI Transfer Systems of Georgia, LLC
Date Submitted:	02/29/2016
Filing Type:	312
SIC Code:	Not reported
NAICS Code:	562111
Dun&Bradstreet Code:	020138298
Chemicals Same as Last Year:	Not reported
Data Tier 2 Signed:	Not reported
Dikes/Saveguard Measures:	Not reported
Facility Department:	Not reported
Facility Date Modified:	02/29/2016
State Fees Total:	Not reported
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Mailing Country:	Not reported
Latitude:	33.66981101532491
Longitude:	-84.43006979231262
Lat/Long Location Desc:	Not reported

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

SANITATION TRANSFER STATION (Continued)

U001478758

Lat/Long Method: Not reported
Number Employees on Site: Not reported
Site Coordinate Abbrvtns Sbmtd: Not reported
Fire District: Not reported
Notes: Not reported
Validity: Not reported

Inventory:

Facility Id: 5417995
Year: 2015
Chemical Inventory ID: Not reported
Acute Health Risks: False
Average Daily Amount: 18000.0
Average Daily Amount Code: Not reported
CB Record ID: Not reported
Chemical Same as Last Year: Not reported
Chronic Health Risk: True
CAS Number: 68476346
EHS Substance: Not reported
Last Modified: Not reported
Days on Site: Not reported
Chemical Name: OILS, FUEL: 2-D
Fire Hazard: True
Gas: False
Liquid: True
Max Daily Amount: 36000.0
Max Daily Amount Code: Not reported
Max Amount in Largest Container: Not reported
Mixture Form: False
Sudden Release of Pressure Hazard: False
Pure Form: True
Reactive Hazard: False
Solid: False
Facility Name: East Point Transfer Station
Contact Info: Howard Palmour
Contact Type: Emergency Contact
Email: hpalmour@republicservices.com
Phone1: 6789458086
Phone2: 7702942977
Phone3: 7702942977
Phone4: Not reported
Phone5: Not reported
Hazardous 1 least hazardous/4 most hazardous: 0
Flammable 1 least flammable/4 most flammable: 2
Reactive 1 least reactive/4 very reactive: 0
Any characteristic over/above H F and R category: -

Inventory:

Facility Id: 5417995
Year: 2015
Chemical Inventory ID: Not reported
Acute Health Risks: False
Average Daily Amount: 18000.0
Average Daily Amount Code: Not reported
CB Record ID: Not reported
Chemical Same as Last Year: Not reported
Chronic Health Risk: True
CAS Number: 68476346

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

SANITATION TRANSFER STATION (Continued)

U001478758

EHS Substance:	Not reported
Last Modified:	Not reported
Days on Site:	Not reported
Chemical Name:	OILS, FUEL: 2-D
Fire Hazard:	True
Gas:	False
Liquid:	True
Max Daily Amount:	36000.0
Max Daily Amount Code:	Not reported
Max Amount in Largest Container:	Not reported
Mixture Form:	False
Sudden Release of Pressure Hazard:	False
Pure Form:	True
Reactive Hazard:	False
Solid:	False
Facility Name:	East Point Transfer Station
Contact Info:	Howard Palmour
Contact Type:	Emergency Contact
Email:	hpalmour@republicservices.com
Phone1:	6789458086
Phone2:	7702942977
Phone3:	7702942977
Phone4:	Not reported
Phone5:	Not reported
Hazardous 1 least hazardous/4 most hazardous:	0
Flammable 1 least flammable/4 most flammable:	2
Reactive 1 least reactive/4 very reactive:	0
Any characteristic over/above H F and R category:	-

Inventory:

Facility Id:	5417995
Year:	2015
Chemical Inventory ID:	Not reported
Acute Health Risks:	False
Average Daily Amount:	18000.0
Average Daily Amount Code:	Not reported
CB Record ID:	Not reported
Chemical Same as Last Year:	Not reported
Chronic Health Risk:	True
CAS Number:	68476346
EHS Substance:	Not reported
Last Modified:	Not reported
Days on Site:	Not reported
Chemical Name:	OILS, FUEL: 2-D
Fire Hazard:	True
Gas:	False
Liquid:	True
Max Daily Amount:	36000.0
Max Daily Amount Code:	Not reported
Max Amount in Largest Container:	Not reported
Mixture Form:	False
Sudden Release of Pressure Hazard:	False
Pure Form:	True
Reactive Hazard:	False
Solid:	False
Facility Name:	East Point Transfer Station
Contact Info:	Howard Palmour
Contact Type:	Emergency Contact

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

SANITATION TRANSFER STATION (Continued)

U001478758

Email: hpalmour@republicservices.com
Phone1: 6789458086
Phone2: 7702942977
Phone3: 7702942977
Phone4: Not reported
Phone5: Not reported
Hazardous 1 least hazardous/4 most hazardous: 0
Flammable 1 least flammable/4 most flammable: 2
Reactive 1 least reactive/4 very reactive: 0
Any characteristic over/above H F and R category: -

Inventory:

Facility Id: 5417995
Year: 2015
Chemical Inventory ID: Not reported
Acute Health Risks: False
Average Daily Amount: 18000.0
Average Daily Amount Code: Not reported
CB Record ID: Not reported
Chemical Same as Last Year: Not reported
Chronic Health Risk: True
CAS Number: 68476346
EHS Substance: Not reported
Last Modified: Not reported
Days on Site: Not reported
Chemical Name: OILS, FUEL: 2-D
Fire Hazard: True
Gas: False
Liquid: True
Max Daily Amount: 36000.0
Max Daily Amount Code: Not reported
Max Amount in Largest Container: Not reported
Mixture Form: False
Sudden Release of Pressure Hazard: False
Pure Form: True
Reactive Hazard: False
Solid: False
Facility Name: East Point Transfer Station
Contact Info: Howard Palmour
Contact Type: Emergency Contact
Email: hpalmour@republicservices.com
Phone1: 6789458086
Phone2: 7702942977
Phone3: 7702942977
Phone4: Not reported
Phone5: Not reported
Hazardous 1 least hazardous/4 most hazardous: 0
Flammable 1 least flammable/4 most flammable: 2
Reactive 1 least reactive/4 very reactive: 0
Any characteristic over/above H F and R category: -

Inventory:

Facility Id: 5417995
Year: 2015
Chemical Inventory ID: Not reported
Acute Health Risks: False
Average Daily Amount: 18000.0
Average Daily Amount Code: Not reported

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

SANITATION TRANSFER STATION (Continued)

U001478758

CB Record ID:	Not reported
Chemical Same as Last Year:	Not reported
Chronic Health Risk:	True
CAS Number:	68476346
EHS Substance:	Not reported
Last Modified:	Not reported
Days on Site:	Not reported
Chemical Name:	OILS, FUEL: 2-D
Fire Hazard:	True
Gas:	False
Liquid:	True
Max Daily Amount:	36000.0
Max Daily Amount Code:	Not reported
Max Amount in Largest Container:	Not reported
Mixture Form:	False
Sudden Release of Pressure Hazard:	False
Pure Form:	True
Reactive Hazard:	False
Solid:	False
Facility Name:	East Point Transfer Station
Contact Info:	Howard Palmour
Contact Type:	Emergency Contact
Email:	hpalmour@republicservices.com
Phone1:	6789458086
Phone2:	7702942977
Phone3:	7702942977
Phone4:	Not reported
Phone5:	Not reported
Hazardous 1 least hazardous/4 most hazardous:	0
Flammable 1 least flammable/4 most flammable:	2
Reactive 1 least reactive/4 very reactive:	0
Any characteristic over/above H F and R category:	-

Inventory:

Facility Id:	5417995
Year:	2015
Chemical Inventory ID:	Not reported
Acute Health Risks:	False
Average Daily Amount:	18000.0
Average Daily Amount Code:	Not reported
CB Record ID:	Not reported
Chemical Same as Last Year:	Not reported
Chronic Health Risk:	True
CAS Number:	68476346
EHS Substance:	Not reported
Last Modified:	Not reported
Days on Site:	Not reported
Chemical Name:	OILS, FUEL: 2-D
Fire Hazard:	True
Gas:	False
Liquid:	True
Max Daily Amount:	36000.0
Max Daily Amount Code:	Not reported
Max Amount in Largest Container:	Not reported
Mixture Form:	False
Sudden Release of Pressure Hazard:	False
Pure Form:	True
Reactive Hazard:	False

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

SANITATION TRANSFER STATION (Continued)

U001478758

Solid: False
Facility Name: East Point Transfer Station
Contact Info: Howard Palmour
Contact Type: Emergency Contact
Email: hpalmour@republicservices.com
Phone1: 6789458086
Phone2: 7702942977
Phone3: 7702942977
Phone4: Not reported
Phone5: Not reported
Hazardous 1 least hazardous/4 most hazardous: 0
Flammable 1 least flammable/4 most flammable: 2
Reactive 1 least reactive/4 very reactive: 0
Any characteristic over/above H F and R category: -

Reporting Year: 2014
Facility ID: 5024744
Facility Country: Not reported
Company Name: BFI Transfer Systems of Georgia, LLC
Date Submitted: 03/02/2015
Filing Type: Tier2
SIC Code: Not reported
NAICS Code: 562111
Dun&Bradstreet Code: 020138298
Chemicals Same as Last Year: Not reported
Data Tier 2 Signed: Not reported
Dikes/Saveguard Measures: Not reported
Facility Department: Not reported
Facility Date Modified: 03/02/2015
State Fees Total: Not reported
Mailing Address: Not reported
Mailing City,St,Zip: Not reported
Mailing Country: Not reported
Latitude: 33.66981101532491
Longitude: -84.43006979231262
Lat/Long Location Desc: Not reported
Lat/Long Method: Not reported
Number Employees on Site: Not reported
Site Coordinate Abbrvtns Sbmtd: Not reported
Fire District: Not reported
Notes: Not reported
Validity: Not reported

Reporting Year: 2012
Facility ID: 4109206
Facility Country: Not reported
Company Name: Republic Services
Date Submitted: Not reported
Filing Type: Not reported
SIC Code: Not reported
NAICS Code: Not reported
Dun&Bradstreet Code: Not reported
Chemicals Same as Last Year: Not reported
Data Tier 2 Signed: 02/27/2013
Dikes/Saveguard Measures: Not reported
Facility Department: Not reported
Facility Date Modified: 02/27/2013

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

SANITATION TRANSFER STATION (Continued)**U001478758**

State Fees Total:	Not reported
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Mailing Country:	Not reported
Latitude:	33.66914
Longitude:	-84.42807
Lat/Long Location Desc:	Not reported
Lat/Long Method:	Not reported
Number Employees on Site:	Not reported
Site Coordinate Abbrvtns Sbmtd:	Not reported
Fire District:	Not reported
Notes:	Not reported
Validity:	Not reported
Contact 1:	Howard Palmour Republic Services
Contact Type 1:	Emergency Contact
Contact Email 1:	hpalmour@republicservices.com
Contact 1 Telephone1:	7702942977
Contact 1 Telephone2:	7702942977
Contact 1 Phone3:	Not reported
Contact Name 2:	Howard Palmour Republic Services
Contact Type 2:	Owner / Operator
Contact Email 2:	hpalmour@republicservices.com
Contact 2 Telephone1:	7702942977
Contact 2 Telephone2:	7.70294e+009
Contact Name 3:	Tim Laraway
Contact Type 3:	Regulatory Point of Contact
Contact Email 3:	tlaraway@republicservices.com
Contact 3 Telephone1:	6786140210
Contact 3 Telephone2:	Not reported
Contact 3 Telephone3:	Not reported
Contact Name 4:	Not reported
Contact Type 4:	Not reported
Contact Email 4:	Not reported
Contact 4 Telephone1:	Not reported
Contact 4 Telephone2:	Not reported
Contact Name 5:	Not reported
Contact Type 5:	Not reported
Contact Email 5:	Not reported
Contact 5 Telephone1:	Not reported
Contact 5 Telephone2:	Not reported
Contact 5 Telephone3:	Not reported

Inventory:

Facility Id:	4109206
Year:	2012
Chemical Inventory ID:	Not reported
Acute Health Risks:	True
Average Daily Amount:	4165.0
Average Daily Amount Code:	Not reported
CB Record ID:	Not reported
Chemical Same as Last Year:	Not reported
Chronic Health Risk:	True
CAS Number:	68476346
EHS Substance:	Not reported
Last Modified:	Not reported
Days on Site:	Not reported
Chemical Name:	Diesel Fuel #2
Fire Hazard:	True

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

SANITATION TRANSFER STATION (Continued)

U001478758

Gas:	False	
Liquid:	True	
Max Daily Amount:	9373.0	
Max Daily Amount Code:	Not reported	
Max Amount in Largest Container:	Not reported	
Mixture Form:	False	
Sudden Release of Pressure Hazard:	False	
Pure Form:	True	
Reactive Hazard:	True	
Solid:	False	
Facility Name:	East Point Transfer Station	
Contact Info:	Howard Palmour Republic Services	
Contact Type:	Emergency Contact	
Email:	hpalmour@republicservices.com	
Phone1:	7702942977	
Phone2:	7702942977	
Phone3:	Not reported	
Phone4:	Not reported	
Phone5:	Not reported	
Hazardous 1 least hazardous/4 most hazardous:	0	
Flammable 1 least flammable/4 most flammable:	2	
Reactive 1 least reactive/4 very reactive:	0	
Any characteristic over/above H F and R category:	-	

Inventory:

Facility Id:	4109206	
Year:	2012	
Chemical Inventory ID:	Not reported	
Acute Health Risks:	True	
Average Daily Amount:	4165.0	
Average Daily Amount Code:	Not reported	
CB Record ID:	Not reported	
Chemical Same as Last Year:	Not reported	
Chronic Health Risk:	True	
CAS Number:	68476346	
EHS Substance:	Not reported	
Last Modified:	Not reported	
Days on Site:	Not reported	
Chemical Name:	Diesel Fuel #2	
Fire Hazard:	True	
Gas:	False	
Liquid:	True	
Max Daily Amount:	9373.0	
Max Daily Amount Code:	Not reported	
Max Amount in Largest Container:	Not reported	
Mixture Form:	False	
Sudden Release of Pressure Hazard:	False	
Pure Form:	True	
Reactive Hazard:	True	
Solid:	False	
Facility Name:	East Point Transfer Station	
Contact Info:	Howard Palmour Republic Services	
Contact Type:	Emergency Contact	
Email:	hpalmour@republicservices.com	
Phone1:	7702942977	
Phone2:	7702942977	
Phone3:	Not reported	
Phone4:	Not reported	

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

SANITATION TRANSFER STATION (Continued)

U001478758

Phone5: Not reported
Hazardous 1 least hazardous/4 most hazardous: 0
Flammable 1 least flammable/4 most flammable: 2
Reactive 1 least reactive/4 very reactive: 0
Any characteristic over/above H F and R category: -

Inventory:

Facility Id: 4109206
Year: 2012
Chemical Inventory ID: Not reported
Acute Health Risks: True
Average Daily Amount: 4165.0
Average Daily Amount Code: Not reported
CB Record ID: Not reported
Chemical Same as Last Year: Not reported
Chronic Health Risk: True
CAS Number: 68476346
EHS Substance: Not reported
Last Modified: Not reported
Days on Site: Not reported
Chemical Name: Diesel Fuel #2
Fire Hazard: True
Gas: False
Liquid: True
Max Daily Amount: 9373.0
Max Daily Amount Code: Not reported
Max Amount in Largest Container: Not reported
Mixture Form: False
Sudden Release of Pressure Hazard: False
Pure Form: True
Reactive Hazard: True
Solid: False
Facility Name: East Point Transfer Station
Contact Info: Howard Palmour Republic Services
Contact Type: Emergency Contact
Email: hpalmour@republicservices.com
Phone1: 7702942977
Phone2: 7702942977
Phone3: Not reported
Phone4: Not reported
Phone5: Not reported
Hazardous 1 least hazardous/4 most hazardous: 0
Flammable 1 least flammable/4 most flammable: 2
Reactive 1 least reactive/4 very reactive: 0
Any characteristic over/above H F and R category: -

Inventory:

Facility Id: 4109206
Year: 2012
Chemical Inventory ID: Not reported
Acute Health Risks: True
Average Daily Amount: 4165.0
Average Daily Amount Code: Not reported
CB Record ID: Not reported
Chemical Same as Last Year: Not reported
Chronic Health Risk: True
CAS Number: 68476346
EHS Substance: Not reported

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

SANITATION TRANSFER STATION (Continued)

U001478758

Last Modified:	Not reported
Days on Site:	Not reported
Chemical Name:	Diesel Fuel #2
Fire Hazard:	True
Gas:	False
Liquid:	True
Max Daily Amount:	9373.0
Max Daily Amount Code:	Not reported
Max Amount in Largest Container:	Not reported
Mixture Form:	False
Sudden Release of Pressure Hazard:	False
Pure Form:	True
Reactive Hazard:	True
Solid:	False
Facility Name:	East Point Transfer Station
Contact Info:	Howard Palmour Republic Services
Contact Type:	Emergency Contact
Email:	hpalmour@republicservices.com
Phone1:	7702942977
Phone2:	7702942977
Phone3:	Not reported
Phone4:	Not reported
Phone5:	Not reported
Hazardous 1 least hazardous/4 most hazardous:	0
Flammable 1 least flammable/4 most flammable:	2
Reactive 1 least reactive/4 very reactive:	0
Any characteristic over/above H F and R category:	-

Inventory:

Facility Id:	4109206
Year:	2012
Chemical Inventory ID:	Not reported
Acute Health Risks:	True
Average Daily Amount:	4165.0
Average Daily Amount Code:	Not reported
CB Record ID:	Not reported
Chemical Same as Last Year:	Not reported
Chronic Health Risk:	True
CAS Number:	68476346
EHS Substance:	Not reported
Last Modified:	Not reported
Days on Site:	Not reported
Chemical Name:	Diesel Fuel #2
Fire Hazard:	True
Gas:	False
Liquid:	True
Max Daily Amount:	9373.0
Max Daily Amount Code:	Not reported
Max Amount in Largest Container:	Not reported
Mixture Form:	False
Sudden Release of Pressure Hazard:	False
Pure Form:	True
Reactive Hazard:	True
Solid:	False
Facility Name:	East Point Transfer Station
Contact Info:	Howard Palmour Republic Services
Contact Type:	Emergency Contact
Email:	hpalmour@republicservices.com

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

SANITATION TRANSFER STATION (Continued)**U001478758**

Phone1: 7702942977
Phone2: 7702942977
Phone3: Not reported
Phone4: Not reported
Phone5: Not reported
Hazardous 1 least hazardous/4 most hazardous: 0
Flammable 1 least flammable/4 most flammable: 2
Reactive 1 least reactive/4 very reactive: 0
Any characteristic over/above H F and R category: -

Inventory:

Facility Id: 4109206
Year: 2012
Chemical Inventory ID: Not reported
Acute Health Risks: True
Average Daily Amount: 4165.0
Average Daily Amount Code: Not reported
CB Record ID: Not reported
Chemical Same as Last Year: Not reported
Chronic Health Risk: True
CAS Number: 68476346
EHS Substance: Not reported
Last Modified: Not reported
Days on Site: Not reported
Chemical Name: Diesel Fuel #2
Fire Hazard: True
Gas: False
Liquid: True
Max Daily Amount: 9373.0
Max Daily Amount Code: Not reported
Max Amount in Largest Container: Not reported
Mixture Form: False
Sudden Release of Pressure Hazard: False
Pure Form: True
Reactive Hazard: True
Solid: False
Facility Name: East Point Transfer Station
Contact Info: Howard Palmour Republic Services
Contact Type: Emergency Contact
Email: hpalmour@republicservices.com
Phone1: 7702942977
Phone2: 7702942977
Phone3: Not reported
Phone4: Not reported
Phone5: Not reported
Hazardous 1 least hazardous/4 most hazardous: 0
Flammable 1 least flammable/4 most flammable: 2
Reactive 1 least reactive/4 very reactive: 0
Any characteristic over/above H F and R category: -

Reporting Year: 2011
Facility ID: 2936618
Facility Country: Not reported
Company Name: Not reported
Date Submitted: Not reported
Filing Type: Not reported
SIC Code: Not reported
NAICS Code: Not reported

PRELIMINARY MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

SANITATION TRANSFER STATION (Continued)**U001478758**

Dun&Bradstreet Code:	Not reported
Chemicals Same as Last Year:	Not reported
Data Tier 2 Signed:	02/29/2012
Dikes/Saveguard Measures:	Not reported
Facility Department:	Not reported
Facility Date Modified:	02/29/2012
State Fees Total:	Not reported
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Mailing Country:	Not reported
Latitude:	33.66914
Longitude:	-84.42807
Lat/Long Location Desc:	Not reported
Lat/Long Method:	Not reported
Number Employees on Site:	Not reported
Site Coordinate Abbrvtns Sbmtd:	Not reported
Fire District:	Not reported
Notes:	Not reported
Validity:	Not reported
Contact 1:	Not reported
Contact Type 1:	Not reported
Contact Email 1:	Not reported
Contact 1 Telephone1:	Not reported
Contact 1 Telephone2:	Not reported
Contact 1 Phone3:	Not reported
Contact Name 2:	Not reported
Contact Type 2:	Not reported
Contact Email 2:	Not reported
Contact 2 Telephone1:	Not reported
Contact 2 Telephone2:	Not reported
Contact Name 3:	Not reported
Contact Type 3:	Not reported
Contact Email 3:	Not reported
Contact 3 Telephone1:	Not reported
Contact 3 Telephone2:	Not reported
Contact 3 Telephone3:	Not reported
Contact Name 4:	Not reported
Contact Type 4:	Not reported
Contact Email 4:	Not reported
Contact 4 Telephone1:	Not reported
Contact 4 Telephone2:	Not reported
Contact Name 5:	Not reported
Contact Type 5:	Not reported
Contact Email 5:	Not reported
Contact 5 Telephone1:	Not reported
Contact 5 Telephone2:	Not reported
Contact 5 Telephone3:	Not reported

Inventory:

Facility Id:	2936618
Year:	2011
Chemical Inventory ID:	Not reported
Acute Health Risks:	True
Average Daily Amount:	4165.0
Average Daily Amount Code:	Not reported
CB Record ID:	Not reported
Chemical Same as Last Year:	Not reported
Chronic Health Risk:	True

PRELIMINARY MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

SANITATION TRANSFER STATION (Continued)

U001478758

CAS Number:	68476346	
EHS Substance:	Not reported	
Last Modified:	Not reported	
Days on Site:	Not reported	
Chemical Name:	Diesel Fuel #2	
Fire Hazard:	True	
Gas:	False	
Liquid:	True	
Max Daily Amount:	9373.0	
Max Daily Amount Code:	Not reported	
Max Amount in Largest Container:	Not reported	
Mixture Form:	False	
Sudden Release of Pressure Hazard:	False	
Pure Form:	True	
Reactive Hazard:	True	
Solid:	False	
Facility Name:	Not reported	
Contact Info:	Not reported	
Contact Type:	Not reported	
Email:	Not reported	
Phone1:	Not reported	
Phone2:	Not reported	
Phone3:	Not reported	
Phone4:	Not reported	
Phone5:	Not reported	
Hazardous 1 least hazardous/4 most hazardous:		Not reported
Flammable 1 least flammable/4 most flammable:		Not reported
Reactive 1 least reactive/4 very reactive:		Not reported
Any characteristic over/above H F and R category:		Not reported

Inventory:

Facility Id:	2936618
Year:	2011
Chemical Inventory ID:	Not reported
Acute Health Risks:	True
Average Daily Amount:	4165.0
Average Daily Amount Code:	Not reported
CB Record ID:	Not reported
Chemical Same as Last Year:	Not reported
Chronic Health Risk:	True
CAS Number:	68476346
EHS Substance:	Not reported
Last Modified:	Not reported
Days on Site:	Not reported
Chemical Name:	Diesel Fuel #2
Fire Hazard:	True
Gas:	False
Liquid:	True
Max Daily Amount:	9373.0
Max Daily Amount Code:	Not reported
Max Amount in Largest Container:	Not reported
Mixture Form:	False
Sudden Release of Pressure Hazard:	False
Pure Form:	True
Reactive Hazard:	True
Solid:	False
Facility Name:	Not reported
Contact Info:	Not reported

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

SANITATION TRANSFER STATION (Continued)

U001478758

Contact Type:	Not reported	
Email:	Not reported	
Phone1:	Not reported	
Phone2:	Not reported	
Phone3:	Not reported	
Phone4:	Not reported	
Phone5:	Not reported	
Hazardous 1 least hazardous/4 most hazardous:	Not reported	
Flammable 1 least flammable/4 most flammable:	Not reported	
Reactive 1 least reactive/4 very reactive:	Not reported	
Any characteristic over/above H F and R category:	Not reported	

Inventory:

Facility Id:	2936618	
Year:	2011	
Chemical Inventory ID:	Not reported	
Acute Health Risks:	True	
Average Daily Amount:	4165.0	
Average Daily Amount Code:	Not reported	
CB Record ID:	Not reported	
Chemical Same as Last Year:	Not reported	
Chronic Health Risk:	True	
CAS Number:	68476346	
EHS Substance:	Not reported	
Last Modified:	Not reported	
Days on Site:	Not reported	
Chemical Name:	Diesel Fuel #2	
Fire Hazard:	True	
Gas:	False	
Liquid:	True	
Max Daily Amount:	9373.0	
Max Daily Amount Code:	Not reported	
Max Amount in Largest Container:	Not reported	
Mixture Form:	False	
Sudden Release of Pressure Hazard:	False	
Pure Form:	True	
Reactive Hazard:	True	
Solid:	False	
Facility Name:	Not reported	
Contact Info:	Not reported	
Contact Type:	Not reported	
Email:	Not reported	
Phone1:	Not reported	
Phone2:	Not reported	
Phone3:	Not reported	
Phone4:	Not reported	
Phone5:	Not reported	
Hazardous 1 least hazardous/4 most hazardous:	Not reported	
Flammable 1 least flammable/4 most flammable:	Not reported	
Reactive 1 least reactive/4 very reactive:	Not reported	
Any characteristic over/above H F and R category:	Not reported	

Inventory:

Facility Id:	2936618
Year:	2011
Chemical Inventory ID:	Not reported
Acute Health Risks:	True
Average Daily Amount:	4165.0

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

SANITATION TRANSFER STATION (Continued)

U001478758

Average Daily Amount Code:	Not reported
CB Record ID:	Not reported
Chemical Same as Last Year:	Not reported
Chronic Health Risk:	True
CAS Number:	68476346
EHS Substance:	Not reported
Last Modified:	Not reported
Days on Site:	Not reported
Chemical Name:	Diesel Fuel #2
Fire Hazard:	True
Gas:	False
Liquid:	True
Max Daily Amount:	9373.0
Max Daily Amount Code:	Not reported
Max Amount in Largest Container:	Not reported
Mixture Form:	False
Sudden Release of Pressure Hazard:	False
Pure Form:	True
Reactive Hazard:	True
Solid:	False
Facility Name:	Not reported
Contact Info:	Not reported
Contact Type:	Not reported
Email:	Not reported
Phone1:	Not reported
Phone2:	Not reported
Phone3:	Not reported
Phone4:	Not reported
Phone5:	Not reported
Hazardous 1 least hazardous/4 most hazardous:	Not reported
Flammable 1 least flammable/4 most flammable:	Not reported
Reactive 1 least reactive/4 very reactive:	Not reported
Any characteristic over/above H F and R category:	Not reported

Inventory:

Facility Id:	2936618
Year:	2011
Chemical Inventory ID:	Not reported
Acute Health Risks:	True
Average Daily Amount:	4165.0
Average Daily Amount Code:	Not reported
CB Record ID:	Not reported
Chemical Same as Last Year:	Not reported
Chronic Health Risk:	True
CAS Number:	68476346
EHS Substance:	Not reported
Last Modified:	Not reported
Days on Site:	Not reported
Chemical Name:	Diesel Fuel #2
Fire Hazard:	True
Gas:	False
Liquid:	True
Max Daily Amount:	9373.0
Max Daily Amount Code:	Not reported
Max Amount in Largest Container:	Not reported
Mixture Form:	False
Sudden Release of Pressure Hazard:	False
Pure Form:	True

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

SANITATION TRANSFER STATION (Continued)

U001478758

Reactive Hazard:	True	
Solid:	False	
Facility Name:	Not reported	
Contact Info:	Not reported	
Contact Type:	Not reported	
Email:	Not reported	
Phone1:	Not reported	
Phone2:	Not reported	
Phone3:	Not reported	
Phone4:	Not reported	
Phone5:	Not reported	
Hazardous 1 least hazardous/4 most hazardous:	Not reported	
Flammable 1 least flammable/4 most flammable:	Not reported	
Reactive 1 least reactive/4 very reactive:	Not reported	
Any characteristic over/above H F and R category:	Not reported	
Inventory:		
Facility Id:	2936618	
Year:	2011	
Chemical Inventory ID:	Not reported	
Acute Health Risks:	True	
Average Daily Amount:	4165.0	
Average Daily Amount Code:	Not reported	
CB Record ID:	Not reported	
Chemical Same as Last Year:	Not reported	
Chronic Health Risk:	True	
CAS Number:	68476346	
EHS Substance:	Not reported	
Last Modified:	Not reported	
Days on Site:	Not reported	
Chemical Name:	Diesel Fuel #2	
Fire Hazard:	True	
Gas:	False	
Liquid:	True	
Max Daily Amount:	9373.0	
Max Daily Amount Code:	Not reported	
Max Amount in Largest Container:	Not reported	
Mixture Form:	False	
Sudden Release of Pressure Hazard:	False	
Pure Form:	True	
Reactive Hazard:	True	
Solid:	False	
Facility Name:	Not reported	
Contact Info:	Not reported	
Contact Type:	Not reported	
Email:	Not reported	
Phone1:	Not reported	
Phone2:	Not reported	
Phone3:	Not reported	
Phone4:	Not reported	
Phone5:	Not reported	
Hazardous 1 least hazardous/4 most hazardous:	Not reported	
Flammable 1 least flammable/4 most flammable:	Not reported	
Reactive 1 least reactive/4 very reactive:	Not reported	
Any characteristic over/above H F and R category:	Not reported	

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site
Database(s)
EDR ID Number
EPA ID Number

B12
SE
1/8-1/4
0.176 mi.
927 ft.
NO MAN'S LAND
SOUTH MARTIN STREET
EAST POINT, GA 30344
Site 2 of 2 in cluster B
US BROWNFIELDS
FINDS
1016351171
N/A

US BROWNFIELDS:

Property Name: NO MAN'S LAND
Recipient Name: East Point, City of
Grant Type: Assessment
Property Number: Not reported
Parcel size: 5
Latitude: 33.669943
Longitude: -84.430422
HCM Label: Not reported
Map Scale: Not reported
Point of Reference: Not reported
Highlights: Not reported
Datum: Not reported
Acres Property ID: 12214
IC Data Access: Not reported
Start Date: Not reported
Redev Completion Date: Not reported
Completed Date: Not reported
Acres Cleaned Up: Not reported
Cleanup Funding: Not reported
Cleanup Funding Source: Not reported
Assessment Funding: Not reported
Assessment Funding Source: Not reported
Redevelopment Funding: Not reported
Redev. Funding Source: Not reported
Redev. Funding Entity Name: Not reported
Redevelopment Start Date: Not reported
Assessment Funding Entity: Not reported
Cleanup Funding Entity: Not reported
Grant Type: N/A
Accomplishment Type: Phase I Environmental Assessment
Accomplishment Count: 0
Cooperative Agreement Number: 98457498
Start Date: 06/30/2000 00:00:00
Ownership Entity: Not reported
Completion Date: 06/30/2000 00:00:00
Current Owner: Not reported
Did Owner Change: Not reported
Cleanup Required: N
Video Available: Not reported
Photo Available: Not reported
Institutional Controls Required: Not reported
IC Category Proprietary Controls: Not reported
IC Cat. Info. Devices: Not reported
IC Cat. Gov. Controls: Not reported
IC Cat. Enforcement Permit Tools: Not reported
IC in place date: Not reported
IC in place: U
State/tribal program date: Not reported
State/tribal program ID: Not reported
State/tribal NFA date: Not reported
Air contaminated: Not reported
Air cleaned: Not reported

PRELIMINARY MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

NO MAN'S LAND (Continued)**1016351171**

Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controlled substance found:	Not reported
Controlled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Not reported
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Surface Water:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
Nickel Cleaned Up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

NO MAN'S LAND (Continued)

1016351171

Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Property Description:	Cotton Mill
Below Poverty Number:	775
Below Poverty Percent:	42.0%
Meidan Income:	4135
Meidan Income Number:	1214
Meidan Income Percent:	65.8%
Vacant Housing Number:	205
Vacant Housing Percent:	24.1%
Unemployed Number:	234
Unemployed Percent:	12.7%

FINDS:

Registry ID: 110039532716

Environmental Interest/Information System

US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES)
is an federal online database for Brownfields Grantees to
electronically submit data directly to EPA.

The FINDS: database may contain additional details for this site.
Please contact your EDR Account Executive for more information

13
SSW
1/8-1/4
0.212 mi.
1119 ft.

CITY OF ATLANTA - GUN CLUB ROAD SANITARY LANDFILL
1359 GUN CLUB ROAD
ATLANTA, GA

ODI 1007443983
N/A

ODI:

Non Compliance Category: 08
Latitude: 33 47 37
Longitude: 084 27 36

PRELIMINARY MAP FINDINGS

Map ID			EDR ID Number
Direction			
Distance			
Distance (ft.)	Site	Database(s)	EPA ID Number

C14
WSW
1/8-1/4
0.230 mi.
1214 ft.

CROSBY STEVENS CO
1645 CENTRAL AVE
EAST POINT, GA 30344

Site 1 of 2 in cluster C

SEMS **1003867872**
GAD069194108

SEMS:

Site ID:	0401539
EPA ID:	GAD069194108
Cong District:	05
FIPS Code:	13121
Latitude:	33.68
Longitude:	-84.441667
FF:	N
NPL:	Not on the NPL
Non NPL Status:	Site Reassessment Ongoing

SEMS Detail:

Region:	04
Site ID:	0401539
EPA ID:	GAD069194108
Site Name:	CROSBY STEVENS CO
NPL:	N
FF:	N
OU:	00
Action Code:	VU
Action Name:	UNARCHIVE
SEQ:	1
Start Date:	Not reported
Finish Date:	1/19/2010 5:00:00 AM
Qual:	Not reported
Current Action Lead:	EPA Perf In-Hse

Region:	04
Site ID:	0401539
EPA ID:	GAD069194108
Site Name:	CROSBY STEVENS CO
NPL:	N
FF:	N
OU:	00
Action Code:	VS
Action Name:	ARCH SITE
SEQ:	1
Start Date:	Not reported
Finish Date:	1/23/1990 5:00:00 AM
Qual:	Not reported
Current Action Lead:	EPA Perf In-Hse

Region:	04
Site ID:	0401539
EPA ID:	GAD069194108
Site Name:	CROSBY STEVENS CO
NPL:	N
FF:	N
OU:	00
Action Code:	PA
Action Name:	PA
SEQ:	1
Start Date:	Not reported
Finish Date:	12/1/1979 5:00:00 AM

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

CROSBY STEVENS CO (Continued)**1003867872**

Qual: L
Current Action Lead: EPA Perf

Region: 04
Site ID: 0401539
EPA ID: GAD069194108
Site Name: CROSBY STEVENS CO
NPL: N
FF: N
OU: 00
Action Code: DS
Action Name: DISCVRY
SEQ: 1
Start Date: 1979-11-01 05:00:00
Finish Date: 11/1/1979 5:00:00 AM
Qual: Not reported
Current Action Lead: EPA Perf

Region: 04
Site ID: 0401539
EPA ID: GAD069194108
Site Name: CROSBY STEVENS CO
NPL: N
FF: N
OU: 00
Action Code: SI
Action Name: SI
SEQ: 1
Start Date: Not reported
Finish Date: 1/23/1990 5:00:00 AM
Qual: N
Current Action Lead: EPA Perf

Region: 04
Site ID: 0401539
EPA ID: GAD069194108
Site Name: CROSBY STEVENS CO
NPL: N
FF: N
OU: 00
Action Code: SI
Action Name: SI
SEQ: 2
Start Date: 2010-07-01 05:00:00
Finish Date: 9/30/2010 4:00:00 AM
Qual: L
Current Action Lead: St Perf

Region: 04
Site ID: 0401539
EPA ID: GAD069194108
Site Name: CROSBY STEVENS CO
NPL: N
FF: N
OU: 00
Action Code: PA
Action Name: PA

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

CROSBY STEVENS CO (Continued)

1003867872

SEQ: 2
Start Date: Not reported
Finish Date: 8/14/2009 5:00:00 AM
Qual: H
Current Action Lead: St Perf

C15
WSW
1/8-1/4
0.230 mi.
1214 ft.

ACME BOX & SALVAGE CORPORATION
1645 CENTRAL AVENUE
EAST POINT, GA 30344

RCRA NonGen / NLR
FINDS
ECHO

1000195521
GAD092144708

Site 2 of 2 in cluster C

RCRA NonGen / NLR:

Date form received by agency: 08/28/1991
Facility name: ACME BOX & SALVAGE CORPORATION
Facility address: 1645 CENTRAL AVENUE
EAST POINT, GA 30344
EPA ID: GAD092144708
Mailing address: PO BOX 90216
EAST POINT, GA 30344
Contact: Not reported
Contact address: Not reported
Not reported
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 04
Land type: Facility is not located on Indian land. Additional information is not known.
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: OPERNAME
Owner/operator address: OPERSTREET
OPERCITY, WY 99999
Owner/operator country: Not reported
Owner/operator telephone: 404-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported
Owner/operator name: Not reported
Owner/operator address: OWNERSTREET
OWNERCITY, WY 99999
Owner/operator country: Not reported
Owner/operator telephone: 404-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

ACME BOX & SALVAGE CORPORATION (Continued)

1000195521

Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 02/04/1981
Site name: ACME BOX & SALVAGE CORPORATION
Classification: Not a generator, verified

Violation Status: No violations found

Evaluation Action Summary:

Evaluation date: 06/21/1991
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110005669856

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

The FINDS: database may contain additional details for this site.
Please contact your EDR Account Executive for more information

ECHO:

Envid: 1000195521
Registry ID: 110005669856
DFR URL: <http://echo.epa.gov/detailed-facility-report?fid=110005669856>

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

16
SSW
1/8-1/4
0.246 mi.
1301 ft.

PLASMET E-SOLUTIONS LLC
3245 MARYLAND AVE
EAST POINT, GA 30344

RCRA NonGen / NLR **1014923189**
GAR000063032

RCRA NonGen / NLR:

Date form received by agency: 05/10/2013
Facility name: PLASMET E-SOLUTIONS LLC
Facility address: 3245 MARYLAND AVE
EAST POINT, GA 30344
EPA ID: GAR000063032
Mailing address: MARYLAND AVE
EAST POINT, GA 30344
Contact: CHAS YANCEY
Contact address: MARYLAND AVE
EAST POINT, GA 30344
Contact country: US
Contact telephone: 770-547-6014
Contact email: CY@PLASMET.COM
EPA Region: 04
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: PLASMET E-SOLUTIONS LLC
Owner/operator address: MARYLAND AVE
EAST POINT, GA 30344
Owner/operator country: US
Owner/operator telephone: 770-547-6014
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 10/28/2011
Owner/Op end date: Not reported

Owner/operator name: CHAS YANCEY
Owner/operator address: Not reported
GA
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 10/28/2011
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

PLASMET E-SOLUTIONS LLC (Continued)

1014923189

On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 01/04/2012

Site name: PLASMET E-SOLUTIONS LLC

Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D001

. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKEY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D008

. Waste name: LEAD

. Waste code: F003

. Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Violation Status: No violations found

17
SE
1/4-1/2
0.251 mi.
1327 ft.

VIRGINIA CAROLINA CHEMICAL (VCC) NORMAN BERRY DRIVE
3171 NORMAN BERRY DRIVE
EAST POINT, GA 30344

SEMS 1012042962
GAN000410378

SEMS:

Site ID: 0410378
EPA ID: GAN000410378
Cong District: Not reported
FIPS Code: 13121
Latitude: +33.66766
Longitude: -084.42876
FF: N
NPL: Not on the NPL
Non NPL Status: Site Reassessment Ongoing

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

VIRGINIA CAROLINA CHEMICAL (VCC) NORMAN BERRY DRIVE (Continued)

1012042962

SEMS Detail:

Region: 04
Site ID: 0410378
EPA ID: GAN000410378
Site Name: VIRGINIA CAROLINA CHEMICAL (VCC) NORMAN BERRY DRIVE
NPL: N
FF: N
OU: 00
Action Code: DS
Action Name: DISCVRY
SEQ: 1
Start Date: 2009-03-30 04:00:00
Finish Date: 3/30/2009 4:00:00 AM
Qual: Not reported
Current Action Lead: EPA Perf

Region: 04
Site ID: 0410378
EPA ID: GAN000410378
Site Name: VIRGINIA CAROLINA CHEMICAL (VCC) NORMAN BERRY DRIVE
NPL: N
FF: N
OU: 00
Action Code: SI
Action Name: SI
SEQ: 1
Start Date: Not reported
Finish Date: 9/30/2010 4:00:00 AM
Qual: L
Current Action Lead: St Perf

Region: 04
Site ID: 0410378
EPA ID: GAN000410378
Site Name: VIRGINIA CAROLINA CHEMICAL (VCC) NORMAN BERRY DRIVE
NPL: N
FF: N
OU: 00
Action Code: PA
Action Name: PA
SEQ: 1
Start Date: Not reported
Finish Date: 12/11/2009 5:00:00 AM
Qual: H
Current Action Lead: St Perf

18
SE
1/4-1/2
0.259 mi.
1368 ft.

TIFT SITE
SOUTH MARTIN STREET
EAST POINT, GA 30344

SHWS S102444442
N/A

SHWS:

Facility Id: 10393
Regulated Substances(RS): Acetophenone-Soil; Antimony-GW/Soil; Barium-GW; Benzo(a)pyrene-Soil; Cadmium-GW/Soil; Copper-GW/Soil; DDT-Soil; Fluoranthene-Soil;

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

TIFT SITE (Continued)

S102444442

Lead-GW/Soil; Nickel-GW; Zinc-GW/Soil; alpha-Benzenehexachloride-Soil; Arsenic-GW/Soil; Benzo(a)anthracene-Soil; Benzo(b)fluoranthene-Soil; Chrysene-Soil; DDE-Soil; Dieldrin-Soil; Indeno(1,2,3-cd)pyrene-Soil; Mercury-GW/Soil; Silver-Soil

RS Released/Threats to Health Env: This site has a known release of Lead in soil at levels exceeding the reportable quantity. This site has unlimited access. The nearest resident individual is between 301 and 1000 feet from the area affected by the release.

Status of Cleanup Activities: Cleanup activities are being conducted for source materials, soil, and groundwater.

GA EPD Dir Determination Re Correction Action: The Director has determined that this site requires corrective action.

Owner Name: Thomas W. Tift

Owner Address: 3401 Norman Berry Dr.

Owner City,St,Zip: East Point, GA 30344

Last Known Property Owner NAME B: East Point Housing Authority

Last Known Property Owner ADDRESS B: 3056 Norman Berry Dr.

Last Known Property Owner CITY B: East Point

Last Known Property Owner STATE B: GA

Last Known Property Owner ZIP B: 30344-2528

Last Known Property Owner NAME C: Michael Chanin

Last Known Property Owner ADDRESS C: 5105 Randall Lane

Last Known Property Owner CITY C: Bethesda

Last Known Property Owner STATE C: MD

Last Known Property Owner ZIP C: 20816

Last Known Property Owner NAME D: Not reported

Last Known Property Owner ADDRESS D: Not reported

Last Known Property Owner CITY D: Not reported

Last Known Property Owner STATE D: Not reported

Last Known Property Owner ZIP D: Not reported

Latitude: 33 40 ' 01 " N

Longitude: 84 25 ' 33 " W

19
SW
1/4-1/2
0.262 mi.
1386 ft.

CARDEN'S GLASS CO INC
1392 CENTRAL AVE
EAST POINT, GA 30344

LUST **U003296100**
UST **N/A**
Financial Assurance

LUST:

Facility ID: 09060657

Leak ID: Not reported

Description: Not reported

Cleanup Status: NFA - No Further Action

Date Received: 05/15/1997

Project Officer: William Logan

Project Name: UST - 1 - CARDEN'S GLASS CO INC

Site Code Description: Owner/Operator funded site

No Further Action Date: 05/01/1998

Facility:

Facility Id: 9060657

Facility Status: Inactive

Facility Type: Not Marked

District: Not reported

Owner Name: TOWER FINANCIAL SERVICES INC

Contact ID: Not reported

Owner Address: 2970 PEACHTREE ROAD SUITE 350

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

CARDEN'S GLASS CO INC (Continued)**U003296100**

Owner City: ATLANTA
Owner State: GA
Owner Zip: 30305
Owner Telephone: 404 2627367

Tank:

Tank ID: 1
Tank Status: Removed from Ground
Tank Material: Not Marked/Unknown
Pipe Type: Not reported
Tank Overfill Type: Not reported
Install Date: 03/20/1997
Facility ID: 9060657
Status Date: Not reported
Product: Gas (Historical Use)
Pipe Material: Not Marked
Overfill Protection: Not reported
Overfill Installed: Not reported
Tank Exempt From Spill: Not reported
Date Spill Device Installed: Not reported

GA Financial Assurance 1:

Region: 1
Facility ID: 9060657
Financial Responsibility: Not Marked

20
South
1/4-1/2
0.316 mi.
1667 ft.

YARBROUGH MOTOR CO
3272 BACHELOR STREET
EAST POINT, GA 30344

LUST **U003763379**
UST **N/A**
Financial Assurance

LUST:

Facility ID: 09060831
Leak ID: Not reported
Description: Not reported
Cleanup Status: NFA - No Further Action
Date Received: 11/01/2000
Project Officer: Kelly Adams
Project Name: UST - 1 - YARBROUGH MOTOR CO
Site Code Description: Owner/Operator funded site
No Further Action Date: 07/11/2005

Facility:

Facility Id: 9060831
Facility Status: Inactive
Facility Type: Other
District: Not reported
Owner Name: YARBROUGH MOTOR COMPANY
Contact ID: Not reported
Owner Address: 3272 BACHELOR STREET
Owner City: EAST POINT
Owner State: GA
Owner Zip: 30344
Owner Telephone: 770 7749265

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

YARBROUGH MOTOR CO (Continued)

U003763379

Tank:

Tank ID: 1
Tank Status: Removed from Ground
Tank Material: Bare Steel
Pipe Type: Safe Suction (Euro)
Tank Overfill Type: Not reported
Install Date: 01/01/1960
Facility ID: 9060831
Status Date: Not reported
Product: Gas (Historical Use)
Pipe Material: Bare Steel
Overfill Protection: Not reported
Overfill Installed: Not reported
Tank Exempt From Spill: Not reported
Date Spill Device Installed: Not reported

GA Financial Assurance 1:

Region: 1
Facility ID: 9060831
Financial Responsibility: Not Marked

D21
West
1/4-1/2
0.318 mi.
1679 ft.
ALLIED CHEMICAL CORP
1427 CENTRAL AVE
EAST POINT, GA 30344
Site 1 of 3 in cluster D

SEMS-ARCHIVE
SPILLS
US AIRS
FINDS
ECHO
NPDES
1000212785
GAD000649160

SEMS Archive:

Site ID: 0401270
EPA ID: GAD000649160
Cong District: 05
FIPS Code: 13121
FF: N
NPL: Not on the NPL
Non NPL Status: NFRAP-Site does not qualify for the NPL based on existing information
Latitude: 33.68
Longitude: -84.441667

SEMS Archive Detail:

Region: 04
Site ID: 0401270
EPA ID: GAD000649160
Site Name: ALLIED CHEMICAL CORP
NPL: N
FF: N
OU: 00
Action Code: VS
Action Name: ARCH SITE
SEQ: 1
Start Date: Not reported
Finish Date: 1988-07-26 04:00:00
Qual: Not reported
Current Action Lead: EPA Perf In-Hse

Region: 04

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

ALLIED CHEMICAL CORP (Continued)**1000212785**

Site ID: 0401270
EPA ID: GAD000649160
Site Name: ALLIED CHEMICAL CORP
NPL: N
FF: N
OU: 00
Action Code: DS
Action Name: DISCVRY
SEQ: 1
Start Date: 1979-11-01 05:00:00
Finish Date: 1979-11-01 05:00:00
Qual: Not reported
Current Action Lead: EPA Perf

Region: 04
Site ID: 0401270
EPA ID: GAD000649160
Site Name: ALLIED CHEMICAL CORP
NPL: N
FF: N
OU: 00
Action Code: PA
Action Name: PA
SEQ: 1
Start Date: Not reported
Finish Date: 1979-12-01 05:00:00
Qual: L
Current Action Lead: EPA Perf

Region: 04
Site ID: 0401270
EPA ID: GAD000649160
Site Name: ALLIED CHEMICAL CORP
NPL: N
FF: N
OU: 00
Action Code: SI
Action Name: SI
SEQ: 1
Start Date: Not reported
Finish Date: 1988-07-26 04:00:00
Qual: N
Current Action Lead: St Perf

SPILLS:

CTS Number: Not reported
Spill Number: Not reported
UN Number: Not reported
UN Number2: Not reported
Report Number: Not reported
Report Date: Not reported
Report Time: Not reported
Spill Date: Not reported
Spill Time: Not reported
Incident Type: Not reported
Material Involved: SULFURIC ACID

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

ALLIED CHEMICAL CORP (Continued)

1000212785

Quantity:	Not reported
Phase:	Not reported
Radioactive:	Not reported
Material 2:	Not reported
Quantity 2:	Not reported
Phase 2:	Not reported
Radioactive 2:	Not reported
Waterway Impctd:	Not reported
Evacuation:	Not reported
Caller:	Not reported
Organization:	Not reported
Org Phone:	Not reported
Primary Concern:	Not reported
Associate Name:	Not reported
Investigation Date:	Not reported
Resolved:	Not reported
Closure Date:	Not reported
Ten Days Follow Up:	Not reported
Transferred Record:	Not reported
Fire:	Not reported
Police:	Not reported
Sheriff:	Not reported
GSP:	Not reported
Medical:	Not reported
EPA:	Not reported
USCG:	Not reported
EMA:	Not reported
DRN:	Not reported
DOT:	Not reported
Responsible Prty:	Not reported
RP Contact:	Not reported
RP Address:	Not reported
RP Phone:	Not reported
RP City:	Not reported
Action Code:	Not reported
Action:	Not reported
Investigator:	Not reported
EOC Operator:	Not reported
Time EOC Notifd:	Not reported
Time Dispatched:	Not reported
Complaint Code:	Not reported
Complaint ID:	Not reported
Cmplaint Referred:	Not reported
Report Sum:	Not reported
At:	Not reported
DDO:	Not reported
Date Recieved:	Not reported
Comments:	Not reported
Comments 1:	Not reported
Referred:	Not reported
Comments 2:	Not reported
Substance:	SULFURIC ACID
Comments 3:	Not reported
Location:	N/A
Comments 4:	Not reported
Source:	Not reported
Comments 5:	Not reported

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

ALLIED CHEMICAL CORP (Continued)

1000212785

Details:	Not reported
Additional Info:	Not reported
Comments 6:	Not reported
Comments 7:	Not reported
Incident:	Not reported
Primary Concern 1 Description:	Not reported
Primary Concern 2:	Not reported
Primary Concern 2 Description:	Not reported
Source Address 1:	Not reported
Source Address 2:	Not reported
Source City:	Not reported
Source State:	Not reported
Source Zip:	Not reported
Direction:	Not reported
Caller Address 1:	Not reported
Caller Address 2:	Not reported
Caller City:	Not reported
Caller State:	Not reported
Caller Zip:	Not reported
Comp City:	Not reported
Branch:	Not reported
BDesc:	Not reported
Program:	Not reported
Prog Desc:	Not reported
Accept Date:	Not reported
Assign Date:	Not reported
FUI Need:	Not reported
Refer 2:	Not reported
Contact:	Not reported
Active:	Not reported
Facility ID:	Not reported
Approved Date:	Not reported
Facility Status:	Not reported

US AIRS MINOR:

Envid:	1000212785
Region Code:	04
Programmatic ID:	AIR GA0000001312100087
Facility Registry ID:	110001128681
D and B Number:	Not reported
Primary SIC Code:	2819
NAICS Code:	999999
Default Air Classification Code:	MIN
Facility Type of Ownership Code:	Not reported
Air CMS Category Code:	Not reported
HPV Status:	Not reported

FINDS:

Registry ID:	110001128681
--------------	--------------

Environmental Interest/Information System

NCDB (National Compliance Data Base) supports implementation of the Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA) and the Toxic Substances Control Act (TSCA). The system tracks inspections in regions and states with cooperative agreements, enforcement actions,

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

ALLIED CHEMICAL CORP (Continued)

1000212785

and settlements.

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AFS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

TSCA SUBMITTER

US EPA TRIS (Toxics Release Inventory System) contains information from facilities on the amounts of over 300 listed toxic chemicals that these facilities release directly to air, water, land, or that are transported off-site.

AIR MINOR

The FINDS: database may contain additional details for this site. Please contact your EDR Account Executive for more information

ECHO:

Envid: 1000212785
Registry ID: 110001128681
DFR URL: <http://echo.epa.gov/detailed-facility-report?fid=110001128681>

NPDES:

NPDES Id: Not reported
Notice of Intent Num: 1673
Facility Type Desc: Not reported
NOI Type: Notice of Intent
River Basin: Not reported
Permit Sub Type: Not reported

D22
West
1/4-1/2
0.318 mi.
1679 ft.
GENERAL CHEMICAL CORP
1427 CENTRAL AVE
EAST POINT, GA 30344
Site 2 of 3 in cluster D

GA NON-HSI
LUST
UST
Financial Assurance
TIER 2
U003181410
N/A

NON HSI:

Latitude: 33.4036
Longitude: -84.2620
Ground Water Pathway Score: 8.13
On-Site Pathway Score: 0
Report Date: Not reported
Additional Info: Not reported
Contamination: Not reported

LUST:

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

GENERAL CHEMICAL CORP (Continued)

U003181410

Facility ID: 00600583
Leak ID: Not reported
Description: Not reported
Cleanup Status: NFA - Suspected Release
Date Received: Not reported
Project Officer: EPD Migration
Project Name: UST - 1 - GENERAL CHEMICAL CORP
Site Code Description: Owner/Operator funded site
No Further Action Date: Not reported

Facility ID: 00600583
Leak ID: Not reported
Description: Not reported
Cleanup Status: NFA - No Further Action
Date Received: 07/30/1998
Project Officer: William Logan
Project Name: UST - 2 - GENERAL CHEMICAL CORP
Site Code Description: Owner/Operator funded site
No Further Action Date: 02/22/1999

Facility:

Facility Id: 600583
Facility Status: Inactive
Facility Type: Commercial
District: Not reported
Owner Name: GENERAL CHEMICAL CORPORATION
Contact ID: Not reported
Owner Address: 1427 CENTRAL AVENUE
Owner City: EAST POINT
Owner State: GA
Owner Zip: 30344
Owner Telephone: 404 7611370

Tank:

Tank ID: 1
Tank Status: Removed from Ground
Tank Material: Cathodically Protected Steel
Pipe Type: Not reported
Tank Overfill Type: Not reported
Install Date: 05/09/1974
Facility ID: 600583
Status Date: Not reported
Product: Gas (Historical Use)
Pipe Material: Galvanized Steel
Overfill Protection: Not reported
Overfill Installed: Not reported
Tank Exempt From Spill: Not reported
Date Spill Device Installed: Not reported

Tank ID: 2
Tank Status: Removed from Ground
Tank Material: Cathodically Protected Steel
Pipe Type: Suction (American)
Tank Overfill Type: Not reported
Install Date: 05/10/1968
Facility ID: 600583
Status Date: Not reported

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

GENERAL CHEMICAL CORP (Continued)

U003181410

Product:	Gas (Historical Use)
Pipe Material:	Galvanized Steel
Overfill Protection:	Not reported
Overfill Installed:	06/01/1991
Tank Exempt From Spill:	Not reported
Date Spill Device Installed:	06/01/1991
Tank ID:	3
Tank Status:	Removed from Ground
Tank Material:	Bare Steel
Pipe Type:	Not reported
Tank Overfill Type:	Not reported
Install Date:	05/14/1952
Facility ID:	600583
Status Date:	Not reported
Product:	Diesel
Pipe Material:	Galvanized Steel
Overfill Protection:	Not reported
Overfill Installed:	Not reported
Tank Exempt From Spill:	Not reported
Date Spill Device Installed:	Not reported
Tank ID:	4
Tank Status:	Removed from Ground
Tank Material:	Bare Steel
Pipe Type:	Not reported
Tank Overfill Type:	Not reported
Install Date:	05/14/1952
Facility ID:	600583
Status Date:	Not reported
Product:	Diesel
Pipe Material:	Galvanized Steel
Overfill Protection:	Not reported
Overfill Installed:	Not reported
Tank Exempt From Spill:	Not reported
Date Spill Device Installed:	Not reported

GA Financial Assurance 1:

Region:	1
Facility ID:	600583
Financial Responsibility:	G.U.S.T. Trust Fund

GA TIER 2:

Reporting Year:	2016
Facility ID:	5844520
Facility Country:	Not reported
Company Name:	Chemtrade Solutions LLC
Date Submitted:	02/14/2017
Filing Type:	302 312
SIC Code:	2819
NAICS Code:	325180
Dun&Bradstreet Code:	05-622-9008
Chemicals Same as Last Year:	Not reported
Data Tier 2 Signed:	Not reported
Dikes/Saveguard Measures:	Not reported

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

GENERAL CHEMICAL CORP (Continued)

U003181410

Facility Department:	Not reported
Facility Date Modified:	02/14/2017
State Fees Total:	Not reported
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Mailing Country:	Not reported
Latitude:	33.67077
Longitude:	-84.43625
Lat/Long Location Desc:	Not reported
Lat/Long Method:	Not reported
Number Employees on Site:	Not reported
Site Coordinate Abbrvtns Sbmtd:	Not reported
Fire District:	Not reported
Notes:	Not reported
Validity:	Not reported
Inventory:	
Facility Id:	5844520
Year:	2016
Chemical Inventory ID:	Not reported
Acute Health Risks:	True
Average Daily Amount:	210000.0
Average Daily Amount Code:	Not reported
CB Record ID:	Not reported
Chemical Same as Last Year:	Not reported
Chronic Health Risk:	False
CAS Number:	10043013
EHS Substance:	Not reported
Last Modified:	Not reported
Days on Site:	Not reported
Chemical Name:	Aluminum Sulfate
Fire Hazard:	False
Gas:	False
Liquid:	False
Max Daily Amount:	650000.0
Max Daily Amount Code:	Not reported
Max Amount in Largest Container:	Not reported
Mixture Form:	False
Sudden Release of Pressure Hazard:	False
Pure Form:	True
Reactive Hazard:	False
Solid:	True
Facility Name:	Atlanta Works
Contact Info:	Ashesh Champaneria
Contact Type:	Fac. Emergency Coordinator
Email:	AChampaneria@chemtradelogistics.com
Phone1:	803-984-3993
Phone2:	Not reported
Phone3:	Not reported
Phone4:	Not reported
Phone5:	Not reported
Hazardous 1 least hazardous/4 most hazardous:	1
Flammable 1 least flammable/4 most flammable:	0
Reactive 1 least reactive/4 very reactive:	0
Any characteristic over/above H F and R category:	-
Inventory:	
Facility Id:	5844520

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

GENERAL CHEMICAL CORP (Continued)

U003181410

Year:	2016
Chemical Inventory ID:	Not reported
Acute Health Risks:	True
Average Daily Amount:	210000.0
Average Daily Amount Code:	Not reported
CB Record ID:	Not reported
Chemical Same as Last Year:	Not reported
Chronic Health Risk:	False
CAS Number:	10043013
EHS Substance:	Not reported
Last Modified:	Not reported
Days on Site:	Not reported
Chemical Name:	Aluminum Sulfate
Fire Hazard:	False
Gas:	False
Liquid:	False
Max Daily Amount:	650000.0
Max Daily Amount Code:	Not reported
Max Amount in Largest Container:	Not reported
Mixture Form:	False
Sudden Release of Pressure Hazard:	False
Pure Form:	True
Reactive Hazard:	False
Solid:	True
Facility Name:	Atlanta Works
Contact Info:	Ashesh Champaneria
Contact Type:	Fac. Emergency Coordinator
Email:	AChampaneria@chemtradelogistics.com
Phone1:	803-984-3993
Phone2:	Not reported
Phone3:	Not reported
Phone4:	Not reported
Phone5:	Not reported
Hazardous 1 least hazardous/4 most hazardous:	1
Flammable 1 least flammable/4 most flammable:	0
Reactive 1 least reactive/4 very reactive:	0
Any characteristic over/above H F and R category:	-

Reporting Year:	2015
Facility ID:	5409170
Facility Country:	Not reported
Company Name:	Chemtrade Solutions LLC
Date Submitted:	02/20/2016
Filing Type:	312
SIC Code:	2819
NAICS Code:	325180
Dun&Bradstreet Code:	05-622-9008
Chemicals Same as Last Year:	Not reported
Data Tier 2 Signed:	Not reported
Dikes/Saveguard Measures:	Not reported
Facility Department:	Not reported
Facility Date Modified:	02/21/2016
State Fees Total:	Not reported
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Mailing Country:	Not reported
Latitude:	33.67077

PRELIMINARY MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

GENERAL CHEMICAL CORP (Continued)**U003181410**

Longitude:	-84.43625
Lat/Long Location Desc:	Not reported
Lat/Long Method:	Not reported
Number Employees on Site:	Not reported
Site Coordinate Abbrvtns Sbmtd:	Not reported
Fire District:	Not reported
Notes:	Not reported
Validity:	Not reported

Inventory:

Facility Id:	5409170
Year:	2015
Chemical Inventory ID:	Not reported
Acute Health Risks:	True
Average Daily Amount:	210000.0
Average Daily Amount Code:	Not reported
CB Record ID:	Not reported
Chemical Same as Last Year:	Not reported
Chronic Health Risk:	False
CAS Number:	10043013
EHS Substance:	Not reported
Last Modified:	Not reported
Days on Site:	Not reported
Chemical Name:	Aluminum Sulfate
Fire Hazard:	False
Gas:	False
Liquid:	False
Max Daily Amount:	650000.0
Max Daily Amount Code:	Not reported
Max Amount in Largest Container:	Not reported
Mixture Form:	False
Sudden Release of Pressure Hazard:	False
Pure Form:	True
Reactive Hazard:	False
Solid:	True
Facility Name:	Atlanta Works
Contact Info:	Kevin Goes
Contact Type:	Emergency Contact
Email:	kgoes@chemtradelogistics.com
Phone1:	404-761-1181
Phone2:	678-585-6129
Phone3:	678-5856129
Phone4:	Not reported
Phone5:	Not reported
Hazardous 1 least hazardous/4 most hazardous:	1
Flammable 1 least flammable/4 most flammable:	0
Reactive 1 least reactive/4 very reactive:	0
Any characteristic over/above H F and R category:	-

Inventory:

Facility Id:	5409170
Year:	2015
Chemical Inventory ID:	Not reported
Acute Health Risks:	True
Average Daily Amount:	210000.0
Average Daily Amount Code:	Not reported
CB Record ID:	Not reported
Chemical Same as Last Year:	Not reported

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

GENERAL CHEMICAL CORP (Continued)

U003181410

Chronic Health Risk:	False
CAS Number:	10043013
EHS Substance:	Not reported
Last Modified:	Not reported
Days on Site:	Not reported
Chemical Name:	Aluminum Sulfate
Fire Hazard:	False
Gas:	False
Liquid:	False
Max Daily Amount:	650000.0
Max Daily Amount Code:	Not reported
Max Amount in Largest Container:	Not reported
Mixture Form:	False
Sudden Release of Pressure Hazard:	False
Pure Form:	True
Reactive Hazard:	False
Solid:	True
Facility Name:	Atlanta Works
Contact Info:	Kevin Goes
Contact Type:	Emergency Contact
Email:	kgoes@chemtradelogistics.com
Phone1:	404-761-1181
Phone2:	678-585-6129
Phone3:	678-5856129
Phone4:	Not reported
Phone5:	Not reported
Hazardous 1 least hazardous/4 most hazardous:	1
Flammable 1 least flammable/4 most flammable:	0
Reactive 1 least reactive/4 very reactive:	0
Any characteristic over/above H F and R category:	-

D23
West 1427 CENTRAL AVENUE
1/4-1/2 EAST POINT, GA
0.318 mi.
1679 ft. Site 3 of 3 in cluster D

VCP S117884500
N/A

VCP:

Tax Parcel Id#:	14 013100010176; 14 013100010184
Associated with HSI #:	10498
Date Of Application:	01/10/2013
Applicant:	General Chemical Corp
VRP Application #:	VRP887983819
Date App Stat Comm:	04/12/2013
Date App Stat2:	Not reported
Date Ist Prog Report:	07/15/2018
Date Progress Report Comm:	06/26/2018
Compliance Status Report Date:	01/17/2018
Compliance Status Report Date2:	09/06/2017
Application Status Date:	04/10/2013
VRP Application Date:	2013-01-10 00:00:00
Check List Date:	Not reported

[Click here for DBF VRP:](#)

[Click here for DBF Comments:](#)

PRELIMINARY MAP FINDINGS

Map ID		EDR ID Number
Direction		
Distance		
Distance (ft.)Site	Database(s)	EPA ID Number

(Continued)

S117884500

[Click here for DBF Approval:](#)

[Click here for DBF Progress Report:](#)

[Click here for DBF Progress Report:](#)

[Click here for Compliance Status Report:](#)

E24	EAST POINT AUTO BODY FACILITY	GA NON-HSI	S112009860
WSW	1466 CENTRAL AVENUE		N/A
1/4-1/2	EAST POINT, GA		
0.322 mi.			
1698 ft.	Site 1 of 2 in cluster E		

NON HSI:

Latitude:	33.67000
Longitude:	84.436944
Ground Water Pathway Score:	8.13
On-Site Pathway Score:	19.75
Report Date:	05/23/2012
Additional Info:	Not reported
Contamination:	lead

E25	3141 VIVIAN SYKES STREET	GA NON-HSI	S122422008
WSW	3141 VIVIAN SYKES STREET		N/A
1/4-1/2	EAST POINT, GA 30344		
0.348 mi.			
1839 ft.	Site 2 of 2 in cluster E		

NON HSI:

Latitude:	33.66944
Longitude:	84.436667
Ground Water Pathway Score:	2.10
On-Site Pathway Score:	69.10
Report Date:	06/14/2018
Additional Info:	Tax Parcels #: 14 015800130212 & 14 015800130089
Contamination:	Barium

26	NAV SVCS	LUST	1006780145
SW	1454 WILLINGHAM DR	UST	N/A
1/4-1/2	EAST POINT, GA 30344	FINDS	
0.357 mi.		Financial Assurance	
1886 ft.			

LUST:

Facility ID:	00600459
Leak ID:	Not reported
Description:	Not reported
Cleanup Status:	NFA -Monitoring Only (MNA)
Date Received:	08/28/2000
Project Officer:	EPD Migration
Project Name:	UST - 1 - NAV SVCS
Site Code Description:	Eligible GUST trust fund reimbursement site
No Further Action Date:	10/10/2003

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

NAV SVCS (Continued)

1006780145

Facility:

Facility Id: 600459
Facility Status: Inactive
Facility Type: Commercial
District: Not reported
Owner Name: N A V SERVICES
Contact ID: Not reported
Owner Address: 1454 WILLINGHAM DR
Owner City: EAST POINT
Owner State: GA
Owner Zip: 30344
Owner Telephone: 404 7687600

Tank:

Tank ID: 1
Tank Status: Removed from Ground
Tank Material: Bare Steel
Pipe Type: Not reported
Tank Overfill Type: Not reported
Install Date: 06/06/1976
Facility ID: 600459
Status Date: Not reported
Product: Diesel
Pipe Material: Galvanized Steel
Overfill Protection: Not reported
Overfill Installed: Not reported
Tank Exempt From Spill: Not reported
Date Spill Device Installed: Not reported

Tank ID: 2
Tank Status: Removed from Ground
Tank Material: Bare Steel
Pipe Type: Not reported
Tank Overfill Type: Not reported
Install Date: 06/06/1976
Facility ID: 600459
Status Date: Not reported
Product: Diesel
Pipe Material: Galvanized Steel
Overfill Protection: Not reported
Overfill Installed: Not reported
Tank Exempt From Spill: Not reported
Date Spill Device Installed: Not reported

Tank ID: 3
Tank Status: Removed from Ground
Tank Material: Bare Steel
Pipe Type: Not reported
Tank Overfill Type: Not reported
Install Date: 06/05/1982
Facility ID: 600459
Status Date: Not reported
Product: Diesel
Pipe Material: Galvanized Steel
Overfill Protection: Not reported
Overfill Installed: Not reported
Tank Exempt From Spill: Not reported

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

NAV SVCS (Continued)

1006780145

Date Spill Device Installed: Not reported

Tank ID: 4
Tank Status: Removed from Ground
Tank Material: Bare Steel
Pipe Type: Not reported
Tank Overfill Type: Not reported
Install Date: 06/05/1982
Facility ID: 600459
Status Date: Not reported
Product: Diesel
Pipe Material: Galvanized Steel
Overfill Protection: Not reported
Overfill Installed: Not reported
Tank Exempt From Spill: Not reported
Date Spill Device Installed: Not reported

Tank ID: 5
Tank Status: Removed from Ground
Tank Material: Marked Unknown
Pipe Type: Not reported
Tank Overfill Type: Not reported
Install Date: 06/06/1976
Facility ID: 600459
Status Date: Not reported
Product: Used Oil
Pipe Material: Galvanized Steel
Overfill Protection: True
Overfill Installed: Not reported
Tank Exempt From Spill: True
Date Spill Device Installed: Not reported

Payment:
Facility ID: 600459
Obligation Date: 06/03/2003
Obligation Amount: \$3,453.00
Payment date: Not reported
Request Amount: \$0.00
Check Amount: \$0.00
Comments: OBLIGATION FOR A CAA
Date Sent to Accounting: Not reported
Task Number: 03-1940

Facility ID: 600459
Obligation Date: Not reported
Obligation Amount: \$0.00
Payment date: 07/03/2003
Request Amount: \$13,452.74
Check Amount: \$3,379.60
Comments: APP 1-3;\$10K DEDUCTIBLE
Date Sent to Accounting: Not reported
Task Number: 03-1940

Facility ID: 600459
Obligation Date: 09/02/2003
Obligation Amount: \$12,586.00
Payment date: Not reported

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

NAV SVCS (Continued)

1006780145

Request Amount:	\$0.00
Check Amount:	\$0.00
Comments:	Obligation for B CAA
Date Sent to Accounting:	Not reported
Task Number:	03-2016
Facility ID:	600459
Obligation Date:	Not reported
Obligation Amount:	\$0.00
Payment date:	10/27/2003
Request Amount:	\$4,342.90
Check Amount:	\$4,342.90
Comments:	APP 1B
Date Sent to Accounting:	Not reported
Task Number:	03-2016
Facility ID:	600459
Obligation Date:	Not reported
Obligation Amount:	\$0.00
Payment date:	02/19/2004
Request Amount:	\$3,576.43
Check Amount:	\$3,576.43
Comments:	APP 2B; FINAL APPLICATION
Date Sent to Accounting:	Not reported
Task Number:	03-2016
Facility ID:	600459
Obligation Date:	02/19/2004
Obligation Amount:	\$-4,666.67
Payment date:	Not reported
Request Amount:	\$0.00
Check Amount:	\$0.00
Comments:	TO DEOBLIGATE UNSPENT B CAA FUNDS; SITE RECEIVED NFA 10/10/2003 AND COMPLETION RPT WAS APPROVED 11/14/2003
Date Sent to Accounting:	Not reported
Task Number:	03-2016
Facility ID:	600459
Obligation Date:	06/24/2011
Obligation Amount:	\$-73.40
Payment date:	Not reported
Request Amount:	\$0.00
Check Amount:	\$0.00
Comments:	Deobligation & Termination of A CAA: B CAA executed & payments initiated.
Date Sent to Accounting:	Not reported
Task Number:	03-1940

FINDS:

Registry ID: 110013494986

Environmental Interest/Information System

GEIMS (Geographic Environmental Information Management System) provides the EPA and Public a single point of access to core data for all facilities and sites regulated or monitored by the EPA and a

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

NAV SVCS (Continued)

1006780145

single system for the reporting of all environmental data.

The FINDS: database may contain additional details for this site.
Please contact your EDR Account Executive for more information

GA Financial Assurance 1:

Region: 1
Facility ID: 600459
Financial Responsibility: Not Marked

F27
WNW
1/4-1/2
0.365 mi.
1925 ft.
SOUTHERN TRANSFORMER
3015 RN MARTIN STREET
ATLANTA, GA 30344
Site 1 of 3 in cluster F

GA NON-HSI **S105872235**
N/A

NON HSI:
Latitude: Not reported
Longitude: Not reported
Ground Water Pathway Score: 4.88
On-Site Pathway Score: 0.00
Report Date: 05/03/2003
Additional Info: Not reported
Contamination: trichloroethene; benzo(a)pyrene

F28
WNW
1/4-1/2
0.365 mi.
1925 ft.
D&N ELECTRIC COMPANY (FORMER SOUTHERN TRANSFORMER FACILITY)
3015 R.N. MARTIN STREET
EAST POINT, GA 30334
Site 2 of 3 in cluster F

GA NON-HSI **S109350697**
N/A

NON HSI:
Latitude: 33.67277
Longitude: 84.437778
Ground Water Pathway Score: 4.90
On-Site Pathway Score: 0.00
Report Date: 11/21/2008
Additional Info: Not reported
Contamination: H20: trichloroethene, OS: benzo(a)pyrene

F29
WNW
1/4-1/2
0.365 mi.
1925 ft.
MGA HOLDINGS
3015 R N MARTIN STREET
EAST POINT, GA 30344
Site 3 of 3 in cluster F

SEMS **1024363907**
GAN000406900

SEMS:
Site ID: 0406900
EPA ID: GAN000406900
Cong District: Not reported
FIPS Code: 13121
Latitude: +33.672743
Longitude: -84.437772

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

MGA HOLDINGS (Continued)**1024363907**

FF: N
NPL: Not on the NPL
Non NPL Status: PA Start Needed

SEMS Detail:
Region: 04
Site ID: 0406900
EPA ID: GAN000406900
Site Name: MGA HOLDINGS
NPL: N
FF: N
OU: 00
Action Code: DS
Action Name: DISCVRY
SEQ: 1
Start Date: 2018-08-23 04:00:00
Finish Date: 8/23/2018 4:00:00 AM
Qual: Not reported
Current Action Lead: EPA Perf In-Hse

30
WSW
1/4-1/2
0.401 mi.
2117 ft.

DOBBS INTERNATIONAL SERVICES INC
3160 AERO COURT
EAST POINT, GA 30344

LUST **U001478942**
UST **N/A**
Financial Assurance

LUST:
Facility ID: 00601342
Leak ID: Not reported
Description: Not reported
Cleanup Status: NFA - No Further Action
Date Received: 11/23/1992
Project Officer: EPD Migration
Project Name: UST - 1 - DOBBS INTERNATIONAL SERVICES INC
Site Code Description: Owner/Operator funded site
No Further Action Date: 02/23/1995

Facility:
Facility Id: 601342
Facility Status: Inactive
Facility Type: Commercial
District: Not reported
Owner Name: DOBBS INTERNATIONAL SERVICES
Contact ID: Not reported
Owner Address: 5100 POPULAR AVE
Owner City: MEMPHIS
Owner State: TN
Owner Zip: 38138
Owner Telephone: 901 7663600

Tank:
Tank ID: 1
Tank Status: Removed from Ground
Tank Material: Bare Steel
Pipe Type: Not reported
Tank Overfill Type: Not reported
Install Date: 05/11/1972

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

DOBBS INTERNATIONAL SERVICES INC (Continued)

U001478942

Facility ID:	601342
Status Date:	Not reported
Product:	Gas (Historical Use)
Pipe Material:	Unknown
Overfill Protection:	Not reported
Overfill Installed:	Not reported
Tank Exempt From Spill:	Not reported
Date Spill Device Installed:	Not reported
Tank ID:	2
Tank Status:	Removed from Ground
Tank Material:	Bare Steel
Pipe Type:	Not reported
Tank Overfill Type:	Not reported
Install Date:	05/11/1972
Facility ID:	601342
Status Date:	Not reported
Product:	Used Oil
Pipe Material:	Unknown
Overfill Protection:	True
Overfill Installed:	Not reported
Tank Exempt From Spill:	True
Date Spill Device Installed:	Not reported
Tank ID:	3
Tank Status:	Removed from Ground
Tank Material:	Bare Steel
Pipe Type:	Not reported
Tank Overfill Type:	Not reported
Install Date:	05/11/1972
Facility ID:	601342
Status Date:	Not reported
Product:	Used Oil
Pipe Material:	Unknown
Overfill Protection:	True
Overfill Installed:	Not reported
Tank Exempt From Spill:	True
Date Spill Device Installed:	Not reported
Tank ID:	4
Tank Status:	Removed from Ground
Tank Material:	Bare Steel
Pipe Type:	Not reported
Tank Overfill Type:	Not reported
Install Date:	05/11/1972
Facility ID:	601342
Status Date:	Not reported
Product:	Used Oil
Pipe Material:	Unknown
Overfill Protection:	True
Overfill Installed:	Not reported
Tank Exempt From Spill:	True
Date Spill Device Installed:	Not reported

GA Financial Assurance 1:
Region:

1

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

DOBBS INTERNATIONAL SERVICES INC (Continued)**U001478942**

Facility ID: 601342
Financial Responsibility: Not Marked

31
West
1/4-1/2
0.414 mi.
2185 ft.

PALLET EXPRESS INC
3131 AERO COURT
EAST POINT, GA 30344

LUST **U004141719**
UST **N/A**
Financial Assurance

LUST:

Facility ID: 10000974
Leak ID: 1
Description: Confirmed Release
Cleanup Status: NFA - No Further Action
Date Received: 09/21/2005
Project Officer: Ron Wallace
Project Name: UST - 1 - PALLET EXPRESS INC
Site Code Description: Owner/Operator funded site
No Further Action Date: 10/14/2005

Facility:

Facility Id: 10000974
Facility Status: Inactive
Facility Type: Not reported
District: Not reported
Owner Name: PALLET EXPRESS INC
Contact ID: Not reported
Owner Address: 6300 NEW TAMPA HIGHWAY
Owner City: LAKELAND
Owner State: GA
Owner Zip: 33815
Owner Telephone: 863 4131004

Tank:

Tank ID: 1
Tank Status: Removed from Ground
Tank Material: Bare Steel
Pipe Type: Not reported
Tank Overfill Type: Not reported
Install Date: 08/19/2005
Facility ID: 10000974
Status Date: Not reported
Product: Diesel
Pipe Material: Galvanized Steel
Overfill Protection: False
Overfill Installed: Not reported
Tank Exempt From Spill: False
Date Spill Device Installed: Not reported

Tank ID: 2
Tank Status: Removed from Ground
Tank Material: Bare Steel
Pipe Type: Not reported
Tank Overfill Type: Not reported
Install Date: 08/19/2005
Facility ID: 10000974
Status Date: Not reported
Product: Diesel

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

PALLETT EXPRESS INC (Continued)

U004141719

Pipe Material: Galvanized Steel
Overfill Protection: False
Overfill Installed: Not reported
Tank Exempt From Spill: False
Date Spill Device Installed: Not reported

GA Financial Assurance 1:

Region: 1
Facility ID: 10000974
Financial Responsibility: Not reported

32
NNE
1/4-1/2
0.435 mi.
2298 ft.

FIRST BAPTIST CHURCH
20 FIFTH STREET
ATLANTA, GA 30308

LUST U003296144
UST N/A
Financial Assurance

LUST:

Facility ID: 09060709
Leak ID: Not reported
Description: Not reported
Cleanup Status: NFA - No Further Action
Date Received: 02/18/1998
Project Officer: William Logan
Project Name: UST - 1 - FIRST BAPTIST CHURCH
Site Code Description: Owner/Operator funded site
No Further Action Date: 08/07/1998

Facility:

Facility Id: 9060709
Facility Status: Inactive
Facility Type: Other
District: Not reported
Owner Name: FIRST BAPTIST CHURCH
Contact ID: Not reported
Owner Address: 20 PEACHTREE STREET
Owner City: ATLANTA
Owner State: GA
Owner Zip: 30308
Owner Telephone: 404 3478268

Tank:

Tank ID: 1
Tank Status: Removed from Ground
Tank Material: Bare Steel
Pipe Type: Safe Suction (Euro)
Tank Overfill Type: Not reported
Install Date: 01/12/1998
Facility ID: 9060709
Status Date: Not reported
Product: Gas (Historical Use)
Pipe Material: Bare Steel
Overfill Protection: Not reported
Overfill Installed: Not reported
Tank Exempt From Spill: Not reported
Date Spill Device Installed: Not reported

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

FIRST BAPTIST CHURCH (Continued)

U003296144

Tank ID: 2
Tank Status: Removed from Ground
Tank Material: Bare Steel
Pipe Type: Safe Suction (Euro)
Tank Overfill Type: Not reported
Install Date: 01/12/1998
Facility ID: 9060709
Status Date: Not reported
Product: Gas (Historical Use)
Pipe Material: Bare Steel
Overfill Protection: Not reported
Overfill Installed: Not reported
Tank Exempt From Spill: Not reported
Date Spill Device Installed: Not reported

GA Financial Assurance 1:

Region: 1
Facility ID: 9060709
Financial Responsibility: Self Insured

G33
WSW
1/4-1/2
0.466 mi.
2460 ft.

NEWELL TRANSPORTATION LLC
1525 WILLINGHAM DRIVE
EAST POINT, GA 30344

Site 1 of 2 in cluster G

LUST
UST
Financial Assurance

U003006141
N/A

LUST:

Facility ID: 09060557
Leak ID: Not reported
Description: Not reported
Cleanup Status: NFA - No Further Action
Date Received: 05/03/2017
Project Officer: Kristy Litts
Project Name: 9060557 Release 1
Site Code Description: Owner/Operator funded site
No Further Action Date: 05/19/2017

Facility:

Facility Id: 9060557
Facility Status: Active
Facility Type: Commercial
District: Not reported
Owner Name: Not reported
Contact ID: Not reported
Owner Address: Not reported
Owner City: Not reported
Owner State: GA
Owner Zip: Not reported
Owner Telephone: Not reported

Tank:

Tank ID: 1
Tank Status: Temporarily out of use
Tank Material: Galvanic (STIP-3)
Pipe Type: Pressurized
Tank Overfill Type: Not reported

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

NEWELL TRANSPORTATION LLC (Continued)**U003006141**

Install Date: 07/01/1988
Facility ID: 9060557
Status Date: Not reported
Product: Diesel
Pipe Material: Fiberglass Reinforced Plastic
Overfill Protection: Not reported
Overfill Installed: 05/20/1996
Tank Exempt From Spill: Not reported
Date Spill Device Installed: 05/20/1996

Tank ID: 2
Tank Status: Temporarily out of use
Tank Material: Galvanic (STIP-3)
Pipe Type: Pressurized
Tank Overfill Type: Not reported
Install Date: 07/01/1988
Facility ID: 9060557
Status Date: Not reported
Product: Gas (Historical Use)
Pipe Material: Fiberglass Reinforced Plastic
Overfill Protection: Not reported
Overfill Installed: 05/20/1996
Tank Exempt From Spill: Not reported
Date Spill Device Installed: 05/20/1996

GA Financial Assurance 1:

Region: 1
Facility ID: 9060557
Financial Responsibility: Not reported

G34
WSW
1/4-1/2
0.466 mi.
2460 ft.

BUS DOCTOR OF ATLANTA
1525 WILLINGHAM DR. AND 3144 PLANT ST.
EAST POINT, GA 30344

Site 2 of 2 in cluster G

INST CONTROL
BROWNFIELDS

S114564694
N/A

INST CONTROL:

Facility ID: 1478
Risk: Non-Residential
Restricted: Restricted

BROWNFIELD:

Facility ID: 1478
Acreage: 2.350
Risk: Non-Residential
Restricted: Restricted
Status: N-HSI
Date Cleanup Plan: 09/29/2014
Date Cleanup Completed: Not reported

PRELIMINARY MAP FINDINGS

Map ID			EDR ID Number
Direction			
Distance			
Distance (ft.)	Site	Database(s)	EPA ID Number
35			
NNE	28 THIRD ST.	GA NON-HSI	S105872123
1/4-1/2	ATLANTA, GA		N/A
0.470 mi.			
2482 ft.			
	NON HSI:		
	Latitude:	Not reported	
	Longitude:	Not reported	
	Ground Water Pathway Score:	0.81	
	On-Site Pathway Score:	0	
	Report Date:	Not reported	
	Additional Info:	Not reported	
	Contamination:	di-n-butylphthalate	
36	ATLANTA UTILITY WORKS	SEMS-ARCHIVE	1003867854
NW	1504 WASHINGTON AVE		GAD003279387
1/4-1/2	EAST POINT, GA 30344		
0.476 mi.			
2511 ft.			
	SEMS Archive:		
	Site ID:	0401325	
	EPA ID:	GAD003279387	
	Cong District:	05	
	FIPS Code:	13121	
	FF:	N	
	NPL:	Not on the NPL	
	Non NPL Status:	NFRAP-Site does not qualify for the NPL based on existing information	
	Latitude:	33.68	
	Longitude:	-84.441667	
	SEMS Archive Detail:		
	Region:	04	
	Site ID:	0401325	
	EPA ID:	GAD003279387	
	Site Name:	ATLANTA UTILITY WORKS	
	NPL:	N	
	FF:	N	
	OU:	00	
	Action Code:	VS	
	Action Name:	ARCH SITE	
	SEQ:	1	
	Start Date:	Not reported	
	Finish Date:	1990-03-15 05:00:00	
	Qual:	Not reported	
	Current Action Lead:	EPA Perf In-Hse	
	Region:	04	
	Site ID:	0401325	
	EPA ID:	GAD003279387	
	Site Name:	ATLANTA UTILITY WORKS	
	NPL:	N	
	FF:	N	
	OU:	00	
	Action Code:	SI	
	Action Name:	SI	
	SEQ:	1	
	Start Date:	Not reported	
	Finish Date:	1990-03-15 05:00:00	

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

ATLANTA UTILITY WORKS (Continued)

1003867854

Qual: N
Current Action Lead: EPA Perf

Region: 04
Site ID: 0401325
EPA ID: GAD003279387
Site Name: ATLANTA UTILITY WORKS
NPL: N
FF: N
OU: 00
Action Code: PA
Action Name: PA
SEQ: 1
Start Date: Not reported
Finish Date: 1979-12-01 05:00:00
Qual: L
Current Action Lead: EPA Perf

Region: 04
Site ID: 0401325
EPA ID: GAD003279387
Site Name: ATLANTA UTILITY WORKS
NPL: N
FF: N
OU: 00
Action Code: DS
Action Name: DISCVRY
SEQ: 1
Start Date: 1979-11-01 05:00:00
Finish Date: 1979-11-01 05:00:00
Qual: Not reported
Current Action Lead: EPA Perf

37
WNW
1/4-1/2
0.489 mi.
2581 ft.

LEGGETTE & PLATT
3030 PLANT ST
EAST POINT, GA 30364

GA NON-HSI **U001478946**
UST **N/A**
Financial Assurance

NON HSI:
Latitude: 33.67194
Longitude: 84.438889
Ground Water Pathway Score: 4.90
On-Site Pathway Score: 0.00
Report Date: 10/01/2010
Additional Info: Not reported
Contamination: tetrachloroethene

Facility:
Facility Id: 601347
Facility Status: Inactive
Facility Type: Commercial
District: Not reported
Owner Name: LEGGETT & PLATT INC
Contact ID: Not reported
Owner Address: 240 PEACHTREE STREET NE

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

LEGGETTE & PLATT (Continued)**U001478946**

Owner City: ATLANTA
Owner State: GA
Owner Zip: 30303
Owner Telephone: 404 5235342

Tank:

Tank ID: 1
Tank Status: Removed from Ground
Tank Material: Bare Steel
Pipe Type: Not reported
Tank Overfill Type: Not reported
Install Date: 08/11/1986
Facility ID: 601347
Status Date: Not reported
Product: Gas (Historical Use)
Pipe Material: Galvanized Steel
Overfill Protection: Not reported
Overfill Installed: Not reported
Tank Exempt From Spill: Not reported
Date Spill Device Installed: Not reported

GA Financial Assurance 1:

Region: 1
Facility ID: 601347
Financial Responsibility: Not Marked

38
West
1/4-1/2
0.496 mi.
2618 ft.

B&W SVC CO INC
3082 PLANT ST
EAST POINT, GA 30344

LUST **U001478250**
UST **N/A**
Financial Assurance

LUST:

Facility ID: 00600452
Leak ID: Not reported
Description: Not reported
Cleanup Status: NFA - Clean Closure
Date Received: Not reported
Project Officer: William Logan
Project Name: UST - CLOSURE - B&W SVC CO INC
Site Code Description: Potential GUST trust fund reimbursement site
No Further Action Date: 05/24/2013

Facility:

Facility Id: 600452
Facility Status: Inactive
Facility Type: Contractor
District: Not reported
Owner Name: B & W SERVICE COMPANY INC
Contact ID: Not reported
Owner Address: 7155 CANELEAF DR
Owner City: FAIRBURN
Owner State: GA
Owner Zip: 30213
Owner Telephone: 404 7617827

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

B&W SVC CO INC (Continued)**U001478250**

Tank:

Tank ID: 1
Tank Status: Removed from Ground
Tank Material: Fiberglass
Pipe Type: Pressurized
Tank Overfill Type: Not reported
Install Date: 05/08/1994
Facility ID: 600452
Status Date: Not reported
Product: Diesel
Pipe Material: Fiberglass Reinforced Plastic
Overfill Protection: Not reported
Overfill Installed: 03/25/1994
Tank Exempt From Spill: Not reported
Date Spill Device Installed: 03/25/1994

Tank ID: 2
Tank Status: Removed from Ground
Tank Material: Fiberglass
Pipe Type: Pressurized
Tank Overfill Type: Not reported
Install Date: 05/08/1994
Facility ID: 600452
Status Date: Not reported
Product: Diesel
Pipe Material: Fiberglass Reinforced Plastic
Overfill Protection: Not reported
Overfill Installed: 03/25/1994
Tank Exempt From Spill: Not reported
Date Spill Device Installed: 03/25/1994

GA Financial Assurance 1:

Region: 1
Facility ID: 600452
Financial Responsibility: G.U.S.T. Trust Fund

39
East
1/2-1
0.729 mi.
3850 ft.

3080 SYLVAN ROAD
3080 SYLVAN RD. AND 3065 SPRINGDALE RD.
HAPEVILLE, GA 30354

GA NON-HSI **S110840995**
BROWNFIELDS **N/A**

NON HSI:

Latitude: 33.67083
Longitude: 84.417778
Ground Water Pathway Score: 6.50
On-Site Pathway Score: Deferred
Report Date: 04/02/2012
Additional Info: Not reported
Contamination: 1,2-dichloroethane

BROWNFIELD:

Facility ID: 1349
Acreage: 3.850
Risk: Residential

PRELIMINARY MAP FINDINGS

Map ID		EDR ID Number
Direction		
Distance		
Distance (ft.)	Site	Database(s) EPA ID Number

3080 SYLVAN ROAD (Continued)

S110840995

Restricted: Not Restricted
 Status: N-HSI
 Date Cleanup Plan: 02/23/2011
 Date Cleanup Completed: 07/24/2012

40
 West
 1/2-1
 0.730 mi.
 3852 ft.

FORMER CROWE MARINE
3067 MAIN ST
EAST POINT, GA 30344

GA NON-HSI
 LUST
 S103908803
 N/A

NON HSI:

Latitude: 33.67140
 Longitude: 84.444100
 Ground Water Pathway Score: 6.20
 On-Site Pathway Score: 0.00
 Report Date: 03/01/1999
 Additional Info: Not reported
 Contamination: tetrachloroethene

LUST:

Facility ID: 09060274
 Leak ID: Not reported
 Description: Not reported
 Cleanup Status: Transferred
 Date Received: 03/08/1993
 Project Officer: EPD Migration
 Project Name: UST - 1 - CROWE MARINE
 Site Code Description: Owner/Operator funded site
 No Further Action Date: Not reported

41
 South
 1/2-1
 0.837 mi.
 4419 ft.

FORMER EASTERN AIRLINES HANGER & MAINTENANCE FACILITY
900 TOFFIE TERRACE, SW
ATLANTA, GA

GA NON-HSI
 S105872220
 N/A

NON HSI:

Latitude: 33.7575
 Longitude: 84.5106
 Ground Water Pathway Score: 7.93
 On-Site Pathway Score: 0
 Report Date: 08/01/1998
 Additional Info: Not reported
 Contamination: Not reported

PRELIMINARY MAP FINDINGS

Map ID			EDR ID Number
Direction			
Distance			
Distance (ft.)	Site	Database(s)	EPA ID Number
42	VACANT PARKING LOT	GA NON-HSI	S105174724
South	SE CORNER OF VIRGINIA AVE/TOFFIE TERRACE		N/A
1/2-1	HAPEVILLE, GA 30344		
0.865 mi.			
4566 ft.			
	NON HSI:		
	Latitude:	33.65861	
	Longitude:	84.429167	
	Ground Water Pathway Score:	6.50	
	On-Site Pathway Score:	11.11	
	Report Date:	08/01/2001	
	Additional Info:	Not reported	
	Contamination:	tetrachloroethene	
43	LAFARGE ROAD MARKING	SEMS-ARCHIVE	1000383442
NNW	2675 MARTIN ST	CORRACTS	GAD088935960
1/2-1	EAST POINT, GA 30344	RCRA-TSDF	
0.886 mi.		RCRA-LQG	
4677 ft.		RAATS	
		FINDS	
		ECHO	
	SEMS Archive:		
	Site ID:	0401604	
	EPA ID:	GAD088935960	
	Cong District:	05	
	FIPS Code:	13121	
	FF:	N	
	NPL:	Not on the NPL	
	Non NPL Status:	NFRAP-Site does not qualify for the NPL based on existing information	
	Latitude:	33.625	
	Longitude:	-82.443611	
	SEMS Archive Detail:		
	Region:	04	
	Site ID:	0401604	
	EPA ID:	GAD088935960	
	Site Name:	PRISMO UNIVERSIAL CORP	
	NPL:	N	
	FF:	N	
	OU:	00	
	Action Code:	VS	
	Action Name:	ARCH SITE	
	SEQ:	1	
	Start Date:	Not reported	
	Finish Date:	1997-01-01 05:00:00	
	Qual:	Not reported	
	Current Action Lead:	EPA Perf In-Hse	
	Region:	04	
	Site ID:	0401604	
	EPA ID:	GAD088935960	
	Site Name:	PRISMO UNIVERSIAL CORP	
	NPL:	N	
	FF:	N	
	OU:	00	
	Action Code:	DS	
	Action Name:	DISCVRY	
	SEQ:	1	

PRELIMINARY MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

LAFARGE ROAD MARKING (Continued)**1000383442**

Start Date:	1980-11-01 05:00:00
Finish Date:	1980-11-01 05:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf
Region:	04
Site ID:	0401604
EPA ID:	GAD088935960
Site Name:	PRISMO UNIVERSIAL CORP
NPL:	N
FF:	N
OU:	00
Action Code:	SI
Action Name:	SI
SEQ:	1
Start Date:	Not reported
Finish Date:	1990-01-23 05:00:00
Qual:	N
Current Action Lead:	EPA Perf
Region:	04
Site ID:	0401604
EPA ID:	GAD088935960
Site Name:	PRISMO UNIVERSIAL CORP
NPL:	N
FF:	N
OU:	00
Action Code:	PA
Action Name:	PA
SEQ:	1
Start Date:	Not reported
Finish Date:	1986-09-22 04:00:00
Qual:	L
Current Action Lead:	St Perf

CORRACTS:

EPA ID:	GAD088935960
EPA Region:	4
Area Name:	ENTIRE FACILITY
Actual Date:	20130528
Action:	SF931
NAICS Code(s):	32551
	Paint and Coating Manufacturing
Original schedule date:	Not reported
Schedule end date:	Not reported

EPA ID:	GAD088935960
EPA Region:	4
Area Name:	ENTIRE FACILITY
Actual Date:	20130523
Action:	SF931
NAICS Code(s):	32551
	Paint and Coating Manufacturing
Original schedule date:	Not reported
Schedule end date:	Not reported

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

LAFARGE ROAD MARKING (Continued)**1000383442**

EPA ID: GAD088935960
EPA Region: 4
Area Name: ENTIRE FACILITY
Actual Date: 20130416
Action: SF931
NAICS Code(s): 32551
Paint and Coating Manufacturing
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: GAD088935960
EPA Region: 4
Area Name: ENTIRE FACILITY
Actual Date: 20130416
Action: SF450
NAICS Code(s): 32551
Paint and Coating Manufacturing
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: GAD088935960
EPA Region: 4
Area Name: ENTIRE FACILITY
Actual Date: 20130416
Action: SF155
NAICS Code(s): 32551
Paint and Coating Manufacturing
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: GAD088935960
EPA Region: 4
Area Name: ENTIRE FACILITY
Actual Date: 20130326
Action: SF931
NAICS Code(s): 32551
Paint and Coating Manufacturing
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: GAD088935960
EPA Region: 4
Area Name: ENTIRE FACILITY
Actual Date: 20101119
Action: SF190
NAICS Code(s): 32551
Paint and Coating Manufacturing
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: GAD088935960
EPA Region: 4
Area Name: ENTIRE FACILITY
Actual Date: 20101119
Action: CA184
NAICS Code(s): 32551
Paint and Coating Manufacturing

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

LAFARGE ROAD MARKING (Continued)**1000383442**

Original schedule date: Not reported

Schedule end date: Not reported

EPA ID: GAD088935960

EPA Region: 4

Area Name: ENTIRE FACILITY

Actual Date: 20091118

Action: CA110 - RFI Workplan Received

NAICS Code(s): 32551

Paint and Coating Manufacturing

Original schedule date: Not reported

Schedule end date: Not reported

EPA ID: GAD088935960

EPA Region: 4

Area Name: ENTIRE FACILITY

Actual Date: 19981020

Action: CA400 - Date For Remedy Selection (CM Imposed)

NAICS Code(s): 32551

Paint and Coating Manufacturing

Original schedule date: Not reported

Schedule end date: Not reported

EPA ID: GAD088935960

EPA Region: 4

Area Name: ENTIRE FACILITY

Actual Date: 19981020

Action: CA450 - Corrective Measures Design Approved

NAICS Code(s): 32551

Paint and Coating Manufacturing

Original schedule date: Not reported

Schedule end date: Not reported

EPA ID: GAD088935960

EPA Region: 4

Area Name: ENTIRE FACILITY

Actual Date: 19980930

Action: CA075ME - CA Prioritization, Facility or area was assigned a medium corrective action priority

NAICS Code(s): 32551

Paint and Coating Manufacturing

Original schedule date: Not reported

Schedule end date: Not reported

EPA ID: GAD088935960

EPA Region: 4

Area Name: ENTIRE FACILITY

Actual Date: 19970925

Action: CA725NO - Current Human Exposures Under Control, Current human exposures are NOT under control

NAICS Code(s): 32551

Paint and Coating Manufacturing

Original schedule date: Not reported

Schedule end date: Not reported

EPA ID: GAD088935960

EPA Region: 4

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

LAFARGE ROAD MARKING (Continued)**1000383442**

Area Name: ENTIRE FACILITY
Actual Date: 19970925
Action: CA750NO - Migration of Contaminated Groundwater under Control, Unacceptable migration of contaminated groundwater is observed or expected
NAICS Code(s): 32551
Paint and Coating Manufacturing
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: GAD088935960
EPA Region: 4
Area Name: ENTIRE FACILITY
Actual Date: 19950630
Action: CA050 - RFA Completed
NAICS Code(s): 32551
Paint and Coating Manufacturing
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: GAD088935960
EPA Region: 4
Area Name: ENTIRE FACILITY
Actual Date: 19910520
Action: CA400 - Date For Remedy Selection (CM Imposed)
NAICS Code(s): 32551
Paint and Coating Manufacturing
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: GAD088935960
EPA Region: 4
Area Name: ENTIRE FACILITY
Actual Date: 19910318
Action: CA400 - Date For Remedy Selection (CM Imposed)
NAICS Code(s): 32551
Paint and Coating Manufacturing
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: GAD088935960
EPA Region: 4
Area Name: ENTIRE FACILITY
Actual Date: 19910318
Action: CA150 - RFI Workplan Approved
NAICS Code(s): 32551
Paint and Coating Manufacturing
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: GAD088935960
EPA Region: 4
Area Name: ENTIRE FACILITY
Actual Date: 19910318
Action: CA450 - Corrective Measures Design Approved
NAICS Code(s): 32551
Paint and Coating Manufacturing

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

LAFARGE ROAD MARKING (Continued)

1000383442

Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: GAD088935960
EPA Region: 4
Area Name: ENTIRE FACILITY
Actual Date: 19910201
Action: CA110 - RFI Workplan Received
NAICS Code(s): 32551
Paint and Coating Manufacturing
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: GAD088935960
EPA Region: 4
Area Name: ENTIRE FACILITY
Actual Date: 19900330
Action: CA100 - RFI Imposition
NAICS Code(s): 32551
Paint and Coating Manufacturing
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: GAD088935960
EPA Region: 4
Area Name: ENTIRE FACILITY
Actual Date: 19900330
Action: CA150 - RFI Workplan Approved
NAICS Code(s): 32551
Paint and Coating Manufacturing
Original schedule date: Not reported
Schedule end date: Not reported

RCRA-TSDF:

Date form received by agency: 02/29/2016
Facility name: LAFARGE ROAD MARKING
Facility address: 2675 N MARTIN STREET
EAST POINT, GA 30344
EPA ID: GAD088935960
Mailing address: JAIME COURT
MORRIS PLAINS, NJ 07950
Contact: JOSEPH MCCARTHY
Contact address: JAIME COURT
MORRIS PLAINS, NJ 07950
Contact country: US
Contact telephone: 973-625-3916
Contact email: JMCCARTHY@LAFARGEROADMARKING.COM
EPA Region: 04
Land type: Private
Classification: TSDF
Description: Handler is engaged in the treatment, storage or disposal of hazardous waste
Classification: Large Quantity Generator
Description: Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

LAFARGE ROAD MARKING (Continued)**1000383442**

cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name: LAFARGE ROAD MARKING
Owner/operator address: Not reported
GA
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 11/06/2006
Owner/Op end date: Not reported

Owner/operator name: LAFARGE ROAD MARKING
Owner/operator address: Not reported
Not reported
Owner/operator country: Not reported
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 11/06/2006
Owner/Op end date: Not reported

Owner/operator name: KAIROS DEVELOPMENT CORPORATION
Owner/operator address: PEACHTREE ROAD NE
ATLANTA, GA 30309
Owner/operator country: US
Owner/operator telephone: 404-350-1440
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 11/06/2006
Owner/Op end date: Not reported

Owner/operator name: KAIROS
Owner/operator address: PEACHTREE RD, NE
ATLANTA, GA 30309
Owner/operator country: US
Owner/operator telephone: 404-350-1440
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

LAFARGE ROAD MARKING (Continued)

1000383442

Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 11/06/2006
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKEY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2-TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE LISTED IN F001, F004, OR F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE,

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

LAFARGE ROAD MARKING (Continued)

1000383442

2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Historical Generators:

Date form received by agency: 04/28/2014

Site name: LAFARGE ROAD MARKING

Classification: Large Quantity Generator

. Waste code: D008

. Waste name: LEAD

. Waste code: D040

. Waste name: TRICHLOROETHYLENE

Date form received by agency: 05/15/2013

Site name: LAFARGE ROAD MARKING

Classification: Large Quantity Generator

. Waste code: D008

. Waste name: LEAD

. Waste code: D018

. Waste name: BENZENE

. Waste code: D040

. Waste name: TRICHLOROETHYLENE

Date form received by agency: 09/26/1994

Site name: LINEAR DYNAMICS INC

Classification: Not a generator, verified

Date form received by agency: 11/14/1980

Site name: LINEAR DYNAMICS INC

Classification: Not a generator, verified

. Waste code: F001

. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLOROETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE, AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: K078

. Waste name: K078

. Waste code: K079

. Waste name: K079

. Waste code: K081

. Waste name: K081

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

LAFARGE ROAD MARKING (Continued)

1000383442

. Waste code:	K082
. Waste name:	K082
. Waste code:	U002
. Waste name:	ACETONE (I)
. Waste code:	U056
. Waste name:	BENZENE, HEXAHYDRO- (I)
. Waste code:	U112
. Waste name:	ACETIC ACID ETHYL ESTER (I)
. Waste code:	U154
. Waste name:	METHANOL (I)
. Waste code:	U159
. Waste name:	2-BUTANONE (I,T)
. Waste code:	U161
. Waste name:	METHYL ISOBUTYL KETONE (I)
. Waste code:	U220
. Waste name:	BENZENE, METHYL-
. Waste code:	U226
. Waste name:	ETHANE, 1,1,1-TRICHLORO-
. Waste code:	U239
. Waste name:	BENZENE, DIMETHYL- (I,T)

Biennial Reports:

Last Biennial Reporting Year: 2017

Annual Waste Handled:

Waste code:	D001
Waste name:	IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKEY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Amount (Lbs): 30601

Waste code:	F002
Waste name:	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2-TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE LISTED IN F001, F004, OR F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Amount (Lbs): 30601

Waste code: F003

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

LAFARGE ROAD MARKING (Continued)**1000383442**

Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Amount (Lbs): 30601

Waste code: F005

Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Amount (Lbs): 30601

Corrective Action Summary:

Event date: 03/30/1990
Event: INVESTIGATION WORKPLAN APPROVED

Event date: 03/30/1990
Event: INVESTIGATION IMPOSITION

Event date: 02/01/1991
Event: INVESTIGATION WORKPLAN RECEIVED

Event date: 03/18/1991
Event: INVESTIGATION WORKPLAN APPROVED

Event date: 03/18/1991
Event: REMEDY DECISION

Event date: 03/18/1991
Event: CORRECTIVE MEASURES DESIGN APPROVED

Event date: 05/20/1991
Event: REMEDY DECISION

Event date: 06/30/1995
Event: RFA COMPLETED

Event date: 09/25/1997
Event: HUMAN EXPOSURES CONTROLLED DETERMINATION-FACILITY DOES NOT MEET DEFINITION

Event date: 09/25/1997
Event: RELEASE TO GW CONTROLLED DETERMINATION-FACILITY DOES NOT MEET DEFINITION

Event date: 09/30/1998

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

LAFARGE ROAD MARKING (Continued)**1000383442**

Event:	CA PRIORITIZATION-MEDIUM CA PRIORITY
Event date:	10/20/1998
Event:	REMEDY DECISION
Event date:	10/20/1998
Event:	CORRECTIVE MEASURES DESIGN APPROVED
Event date:	11/18/2009
Event:	INVESTIGATION WORKPLAN RECEIVED
Event date:	11/19/2010
Event:	DRAFT RFI REPORT RECEIVED
Event date:	11/19/2010
Event:	INVESTIGATION REPORT RECEIVED
Event date:	03/26/2013
Event:	SEMI-ANNUAL EFFECTIVENESS REVIEW
Event date:	04/16/2013
Event:	INVESTIGATION SUPPLEMENTAL INFO REQ BY AGENCY
Event date:	04/16/2013
Event:	ADEM NOT EPA OF CONCUR W/ROD/ESD/AMEND
Event date:	04/16/2013
Event:	SEMI-ANNUAL EFFECTIVENESS REVIEW
Event date:	05/23/2013
Event:	SEMI-ANNUAL EFFECTIVENESS REVIEW
Event date:	05/28/2013
Event:	SEMI-ANNUAL EFFECTIVENESS REVIEW

Facility Has Received Notices of Violations:

Regulation violated:	Not reported
Area of violation:	State Statute or Regulation
Date violation determined:	03/01/2016
Date achieved compliance:	05/23/2016
Violation lead agency:	State
Enforcement action:	WRITTEN INFORMAL
Enforcement action date:	05/02/2016
Enf. disposition status:	Not reported
Enf. disp. status date:	Not reported
Enforcement lead agency:	State
Proposed penalty amount:	Not reported
Final penalty amount:	Not reported
Paid penalty amount:	Not reported
Regulation violated:	SR - EPD-HW-562
Area of violation:	TSD IS-Ground-Water Monitoring
Date violation determined:	06/07/1994
Date achieved compliance:	06/23/1994
Violation lead agency:	State
Enforcement action:	WRITTEN INFORMAL
Enforcement action date:	06/07/1994

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

LAFARGE ROAD MARKING (Continued)**1000383442**

Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 03/21/1990
Date achieved compliance: 04/18/1990
Violation lead agency: State
Enforcement action: FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date: 03/30/1990
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 262.11
Area of violation: Generators - General
Date violation determined: 04/18/1986
Date achieved compliance: 08/01/1986
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 06/03/1986
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 262.30 - .33
Area of violation: Generators - General
Date violation determined: 04/18/1986
Date achieved compliance: 08/01/1986
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 06/03/1986
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 262.34
Area of violation: Generators - General
Date violation determined: 04/18/1986
Date achieved compliance: 08/01/1986
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 06/03/1986
Enf. disposition status: Not reported

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

LAFARGE ROAD MARKING (Continued)**1000383442**

Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:

Evaluation date: 05/23/2017
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 03/01/2016
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: State Statute or Regulation
Date achieved compliance: 05/23/2016
Evaluation lead agency: State

Evaluation date: 03/01/2014
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 03/20/2009
Evaluation: CORRECTIVE ACTION COMPLIANCE EVALUATION
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 06/07/1994
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: TSD IS-Ground-Water Monitoring
Date achieved compliance: 06/23/1994
Evaluation lead agency: State

Evaluation date: 08/23/1991
Evaluation: COMPLIANCE SCHEDULE EVALUATION
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 10/23/1990
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 03/21/1990
Evaluation: FOCUSED COMPLIANCE INSPECTION
Area of violation: Generators - General
Date achieved compliance: 04/18/1990
Evaluation lead agency: State

Evaluation date: 03/22/1988
Evaluation: NON-FINANCIAL RECORD REVIEW

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

LAFARGE ROAD MARKING (Continued)**1000383442**

Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 03/01/1988
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 01/20/1988
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 01/20/1988
Evaluation: FOCUSED COMPLIANCE INSPECTION
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 07/02/1986
Evaluation: FOCUSED COMPLIANCE INSPECTION
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 05/21/1986
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 04/18/1986
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 08/01/1986
Evaluation lead agency: State

Evaluation date: 04/25/1985
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 02/20/1985
Evaluation: GROUNDWATER MONITORING EVALUATION
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110000738621

Environmental Interest/Information System
AFS (Aerometric Information Retrieval System (AIRS) Facility

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

LAFARGE ROAD MARKING (Continued)

1000383442

Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZARDOUS WASTE BIENNIAL REPORTER

AIR MINOR

The FINDS: database may contain additional details for this site.
Please contact your EDR Account Executive for more information

ECHO:

Envid: 1000383442
Registry ID: 110000738621
DFR URL: <http://echo.epa.gov/detailed-facility-report?fid=110000738621>

44
South
1/2-1
0.897 mi.
4738 ft.

1200 VIRGINIA AVENUE SITE
1200 VIRGINIA AVENUE
HAPEVILLE, GA 30344

GA NON-HSI S106854548
BROWNFIELDS N/A

NON HSI:

Latitude: 33.65777
Longitude: 84.428889
Ground Water Pathway Score: 3.30
On-Site Pathway Score: 9.90
Report Date: 03/05/2005
Additional Info: Not reported
Contamination: benzene

BROWNFIELD:

Facility ID: 1154
Acreage: 5.323
Risk: Residential
Restricted: Not Restricted
Status: N-HSI
Date Cleanup Plan: 12/29/2006
Date Cleanup Completed: 02/16/2007

PRELIMINARY MAP FINDINGS

Map ID		EDR ID Number
Direction		
Distance		
Distance (ft.)	Site	Database(s) EPA ID Number

45
WSW
1/2-1
0.916 mi.
4835 ft.

HARRIS-STONE CLEANERS
3303 MAIN ST
COLLEGE PARK, GA 30337

GA NON-HSI
RCRA NonGen / NLR
FINDS
ECHO
DRYCLEANERS

1000362677
GAD981217169

NON HSI:

Latitude: 33.66500
 Longitude: 84.446200
 Ground Water Pathway Score: 2.43
 On-Site Pathway Score: 9.25
 Report Date: 01/01/1998
 Additional Info: Not reported
 Contamination: tetrachloroethene; tetrachloroethylene; trichloroethylene;
 1,2-dichloroethane; cis-1,2-dichloroethylene

RCRA NonGen / NLR:

Date form received by agency: 02/06/2001
 Facility name: HARRIS-STONE CLEANERS
 Facility address: 3303 MAIN ST
 COLLEGE PARK, GA 30337
 EPA ID: GAD981217169
 Mailing address: MAIN ST
 COLLEGE PARK, GA 30337
 Contact: ALLEN ADAMS
 Contact address: 3303 MAIN ST
 COLLEGE PARK, GA 30337
 Contact country: US
 Contact telephone: 404-761-8891
 Contact email: Not reported
 EPA Region: 04
 Land type: Private
 Classification: Non-Generator
 Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: OPERNAME
 Owner/operator address: OPERSTREET
 OPERCITY, WY 99999
 Owner/operator country: Not reported
 Owner/operator telephone: 404-555-1212
 Owner/operator email: Not reported
 Owner/operator fax: Not reported
 Owner/operator extension: Not reported
 Legal status: Private
 Owner/Operator Type: Operator
 Owner/Op start date: Not reported
 Owner/Op end date: Not reported
 Owner/operator name: ADAMS ALLEN
 Owner/operator address: 3303 MAIN ST
 COLLEGE PARK, GA 30337
 Owner/operator country: Not reported
 Owner/operator telephone: 404-761-8891
 Owner/operator email: Not reported
 Owner/operator fax: Not reported
 Owner/operator extension: Not reported
 Legal status: Private

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

HARRIS-STONE CLEANERS (Continued)

1000362677

Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKEY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2-TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE LISTED IN F001, F004, OR F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Historical Generators:

Date form received by agency: 07/25/1986
Site name: HARRIS-STONE CLEANERS
Classification: Conditionally Exempt Small Quantity Generator

Facility Has Received Notices of Violations:

Regulation violated: SR - 262.34
Area of violation: Generators - Pre-transport
Date violation determined: 03/20/1991
Date achieved compliance: 08/07/1991
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 04/29/1991
Enf. disposition status: Not reported
Enf. disp. status date: Not reported

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

HARRIS-STONE CLEANERS (Continued)

1000362677

Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 262.11
Area of violation: Generators - General
Date violation determined: 03/20/1991
Date achieved compliance: 02/19/1992
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 04/29/1991
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:

Evaluation date: 03/15/1991
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Pre-transport
Date achieved compliance: 08/07/1991
Evaluation lead agency: State

Evaluation date: 03/15/1991
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 02/19/1992
Evaluation lead agency: State

FINDS:

Registry ID: 110005672575

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

The FINDS: database may contain additional details for this site.
Please contact your EDR Account Executive for more information

ECHO:

Envid: 1000362677
Registry ID: 110005672575
DFR URL: <http://echo.epa.gov/detailed-facility-report?fid=110005672575>

DRYCLN:

Contact Name: Not reported
Phone Number: Not reported

PRELIMINARY MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

HARRIS-STONE CLEANERS (Continued)**1000362677**

Contact Name:	Not reported
MSA code:	Not reported
MSA desc:	Not reported
CBSA code:	Not reported
CBSA descr:	Not reported
Metro Micro Indicator:	Not reported
CSA code:	Not reported
Csa descr:	Not reported
Census tract:	Not reported
Census block group:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Match level code:	Not reported
Secondary address:	Not reported
Secondary city:	Not reported
Secondary state:	Not reported
Secondary zip10:	Not reported
Secondary carrier route code:	Not reported
Fax number:	Not reported
Toll free number:	Not reported
Web site:	Not reported
Selected SIC code:	Not reported
Selected SIC desc:	Not reported
Primary SIC code:	Not reported
Primary SIC desc:	Not reported
NAICS code:	Not reported
NAICS desc:	Not reported
Location employment size code:	Not reported
Location employment size desc:	Not reported
Actual location employment size:	Not reported
Modeled employment size:	Not reported
Location sales volume code:	Not reported
Location sales volume desc:	Not reported
Actual location sales volume:	Not reported
Corporate sales volume code:	Not reported
Corporate sales volume desc:	Not reported
Actual corporate sales volume:	Not reported
Asset size:	Not reported
Name:	Not reported
Title:	Not reported
Ethnicity code:	Not reported
Infousa id:	Not reported
Site Number:	Not reported
HQ branch code:	Not reported
HQ branch desc:	Not reported
Public company indicator code:	Not reported
Public filing indicator:	Not reported
Individual firm code:	Not reported
Individual firm desc:	Not reported
Year SIC added:	Not reported
Year first appeared in yellow pages:	Not reported
Yellow page code:	Not reported
Transaction date:	Not reported
Call status code:	Not reported
Call status desc:	Not reported
Credit score code:	Not reported
Credit score desc:	Not reported

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

HARRIS-STONE CLEANERS (Continued)

1000362677

Actual credit score:	Not reported
Ad size code:	Not reported
Population code:	Not reported
Population desc:	Not reported
Square footage code:	Not reported
Square footage desc:	Not reported
Radial distance from target element:	Not reported
Actnumbus multitenant location:	Not reported
Building num multi tenant:	Not reported
Number of pcs code:	Not reported
Affluent neighborhood location:	Not reported
Big business:	Not reported
Female owner exec:	Not reported
Highincomeexec:	Not reported
Hightechbusiness:	Not reported
Medium size business entrepreneur:	Not reported
Small business entrepreneur:	Not reported
Tertiary address:	Not reported
Tertiary city:	Not reported
Tertiary state:	Not reported
Tertiary zip10:	Not reported
White collar percentage:	Not reported
White collar indicator:	Not reported
Production date:	Not reported
Obsolescence date:	Not reported
Source:	Not reported
Bookno:	Not reported

46
NNW
1/2-1
0.931 mi.
4918 ft.

ATTWOOD CANVAS FACILITY
1526 EAST FORREST AVE.
ATLANTA, GA 30344

GA NON-HSI S107150848
BROWNFIELDS N/A

NON HSI:

Latitude:	33.68277
Longitude:	84.438889
Ground Water Pathway Score:	8.13
On-Site Pathway Score:	0.00
Report Date:	09/21/2005
Additional Info:	Not reported
Contamination:	Vinyl chloride

BROWNFIELD:

Facility ID:	1069
Acreage:	1.7
Risk:	Residential
Restricted:	Not Restricted
Status:	N-HSI
Date Cleanup Plan:	09/29/2005
Date Cleanup Completed:	11/15/2005

PRELIMINARY MAP FINDINGS

Map ID		EDR ID Number
Direction		
Distance		
Distance (ft.)	Site	Database(s) EPA ID Number

47
SE
1/2-1
0.933 mi.
4928 ft.

SAFETY-KLEEN CORP 3-013-01 HAPEVILLE
3440 LANG AVE
HAPEVILLE, GA 30354

SEMS
CORRACTS
RCRA-TSDF
RCRA NonGen / NLR
US FIN ASSUR
2020 COR ACTION

1000224298
GAD000823070

SEMS:

Site ID:	0401286
EPA ID:	GAD000823070
Cong District:	05
FIPS Code:	13121
Latitude:	33.660833
Longitude:	-84.404444
FF:	N
NPL:	Not on the NPL
Non NPL Status:	Deferred to RCRA (Subtitle C)

SEMS Detail:

Region:	04
Site ID:	0401286
EPA ID:	GAD000823070
Site Name:	SAFETY-KLEEN CORP 3-013-01
NPL:	N
FF:	N
OU:	00
Action Code:	DS
Action Name:	DISCVRY
SEQ:	1
Start Date:	1980-08-01 04:00:00
Finish Date:	8/1/1980 4:00:00 AM
Qual:	Not reported
Current Action Lead:	EPA Perf

Region:	04
Site ID:	0401286
EPA ID:	GAD000823070
Site Name:	SAFETY-KLEEN CORP 3-013-01
NPL:	N
FF:	N
OU:	00
Action Code:	SI
Action Name:	SI
SEQ:	1
Start Date:	Not reported
Finish Date:	1/8/1990 5:00:00 AM
Qual:	D
Current Action Lead:	St Perf

Region:	04
Site ID:	0401286
EPA ID:	GAD000823070
Site Name:	SAFETY-KLEEN CORP 3-013-01
NPL:	N
FF:	N
OU:	00
Action Code:	PA
Action Name:	PA
SEQ:	1
Start Date:	1987-09-30 04:00:00

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

SAFETY-KLEEN CORP 3-013-01 HAPEVILLE (Continued)**1000224298**

Finish Date: 11/20/1987 5:00:00 AM
Qual: N
Current Action Lead: St Perf

CORRACTS:

EPA ID: GAD000823070
EPA Region: 4
Area Name: ENTIRE FACILITY-THREE SEPARATE SWMU'S
Actual Date: 20120522
Action: CA999NF - Corrective Action Process Terminated, No Further Action
NAICS Code(s): Not reported
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: GAD000823070
EPA Region: 4
Area Name: ENTIRE FACILITY-THREE SEPARATE SWMU'S
Actual Date: 20100930
Action: CA400 - Date For Remedy Selection (CM Imposed)
NAICS Code(s): Not reported
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: GAD000823070
EPA Region: 4
Area Name: ENTIRE FACILITY-THREE SEPARATE SWMU'S
Actual Date: 20100930
Action: CA550RC
NAICS Code(s): Not reported
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: GAD000823070
EPA Region: 4
Area Name: ENTIRE FACILITY-THREE SEPARATE SWMU'S
Actual Date: 20030929
Action: CA750YE - Migration of Contaminated Groundwater under Control, Yes,
Migration of Contaminated Groundwater Under Control has been verified
NAICS Code(s): Not reported
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: GAD000823070
EPA Region: 4
Area Name: ENTIRE FACILITY-THREE SEPARATE SWMU'S
Actual Date: 19981007
Action: CA400 - Date For Remedy Selection (CM Imposed)
NAICS Code(s): Not reported
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: GAD000823070
EPA Region: 4
Area Name: ENTIRE FACILITY-THREE SEPARATE SWMU'S
Actual Date: 19960923
Action: CA725YE - Current Human Exposures Under Control, Yes, Current Human

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

SAFETY-KLEEN CORP 3-013-01 HAPEVILLE (Continued)

1000224298

Exposures Under Control has been verified

NAICS Code(s): Not reported
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: GAD000823070
EPA Region: 4
Area Name: ENTIRE FACILITY-THREE SEPARATE SWMU'S
Actual Date: 19960923
Action: CA750NO - Migration of Contaminated Groundwater under Control, Unacceptable migration of contaminated groundwater is observed or expected

NAICS Code(s): Not reported
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: GAD000823070
EPA Region: 4
Area Name: ENTIRE FACILITY-THREE SEPARATE SWMU'S
Actual Date: 19950929
Action: CA200 - RFI Approved

NAICS Code(s): Not reported
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: GAD000823070
EPA Region: 4
Area Name: ENTIRE FACILITY-THREE SEPARATE SWMU'S
Actual Date: 19931008
Action: CA140 - RFI Workplan Notice Of Deficiency Issued

NAICS Code(s): Not reported
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: GAD000823070
EPA Region: 4
Area Name: ENTIRE FACILITY-THREE SEPARATE SWMU'S
Actual Date: 19930930
Action: CA226YC

NAICS Code(s): Not reported
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: GAD000823070
EPA Region: 4
Area Name: ENTIRE FACILITY-THREE SEPARATE SWMU'S
Actual Date: 19930930
Action: CA225IN - Stabilization Measures Evaluation, This facility is not, amenable to stabilization activity because of, a lack of technical data. An evaluation has been completed, but further data is necessary to determine stabilization measures, feasibility or appropriateness. This status should be changed when data becomes available

NAICS Code(s): Not reported
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: GAD000823070

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

SAFETY-KLEEN CORP 3-013-01 HAPEVILLE (Continued)

1000224298

EPA Region: 4
Area Name: ENTIRE FACILITY-THREE SEPARATE SWMU'S
Actual Date: 19920629
Action: CA225NR - Stabilization Measures Evaluation, This facility is, not amenable to stabilization activity at the, present time for reasons other than (1) it appears to be technically, infeasible or inappropriate (NF) or (2) there is a lack of technical, information (IN). Reasons for this conclusion may be the status of, closure at the facility, the degree of risk, timing considerations, the status of corrective action work at the facility, or other, administrative considerations

NAICS Code(s): Not reported
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: GAD000823070
EPA Region: 4
Area Name: ENTIRE FACILITY-THREE SEPARATE SWMU'S
Actual Date: 19911108
Action: CA075HI - CA Prioritization, Facility or area was assigned a high corrective action priority

NAICS Code(s): Not reported
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: GAD000823070
EPA Region: 4
Area Name: ENTIRE FACILITY-THREE SEPARATE SWMU'S
Actual Date: 19911004
Action: CA150 - RFI Workplan Approved

NAICS Code(s): Not reported
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: GAD000823070
EPA Region: 4
Area Name: ENTIRE FACILITY-THREE SEPARATE SWMU'S
Actual Date: 19910401
Action: CA110 - RFI Workplan Received

NAICS Code(s): Not reported
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: GAD000823070
EPA Region: 4
Area Name: ENTIRE FACILITY-THREE SEPARATE SWMU'S
Actual Date: 19890929
Action: CA100 - RFI Imposition

NAICS Code(s): Not reported
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: GAD000823070
EPA Region: 4
Area Name: ENTIRE FACILITY-THREE SEPARATE SWMU'S
Actual Date: 19890317
Action: CA050 - RFA Completed

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

SAFETY-KLEEN CORP 3-013-01 HAPEVILLE (Continued)

1000224298

NAICS Code(s): Not reported
Original schedule date: Not reported
Schedule end date: Not reported

RCRA-TSDF:

Date form received by agency: 06/07/2002
Facility name: SAFETY-KLEEN CORP 3-013-01 HAPEVILLE
Facility address: 3440 LANG AVE
HAPEVILLE, GA 30354
EPA ID: GAD000823070
Mailing address: BIG TIMBER ROAD
ELGIN, IL 60123
Contact: PAUL PEDERSON
Contact address: 655 BIG TIMBER ROAD
ELGIN, IL 60123
Contact country: US
Contact telephone: 312-697-8460
Contact email: Not reported
EPA Region: 04
Land type: Facility is not located on Indian land. Additional information is not known.
Classification: TSDF
Description: Handler is engaged in the treatment, storage or disposal of hazardous waste
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: Not reported
Owner/operator address: OWNERSTREET
ATLANTA, GA 99999
Owner/operator country: Not reported
Owner/operator telephone: 404-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

SAFETY-KLEEN CORP 3-013-01 HAPEVILLE (Continued)

1000224298

- . Waste code: D001
- . Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKEY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

- . Waste code: F002
- . Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2-TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE LISTED IN F001, F004, OR F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

- . Waste code: F004
- . Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: CRESOLS AND CRESYLIC ACID, AND NITROBENZENE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Historical Generators:

- Date form received by agency: 04/28/1994
- Site name: SAFETY-KLEEN CORP
- Classification: Large Quantity Generator

- Date form received by agency: 03/31/1992
- Site name: SAFETY-KLEEN
- Classification: Large Quantity Generator

- Date form received by agency: 03/12/1992
- Site name: SAFETY-KLEEN CORP 3-013-01 HAPEVILLE
- Classification: Large Quantity Generator

- Date form received by agency: 02/23/1990
- Site name: SAFETY-KLEEN CORP 3-013-01
- Classification: Large Quantity Generator

- Date form received by agency: 11/18/1980
- Site name: SAFETY-KLEEN CORP 3-013-01 HAPEVILLE
- Classification: Not a generator, verified

- . Waste code: F002
- . Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2-TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE LISTED IN F001, F004, OR

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

SAFETY-KLEEN CORP 3-013-01 HAPEVILLE (Continued)

1000224298

F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Date form received by agency: 08/18/1980

Site name: SAFETY-KLEEN CORP 3-013-01 HAPEVILLE

Classification: Large Quantity Generator

Corrective Action Summary:

Event date: 03/17/1989

Event: RFA COMPLETED

Event date: 04/07/1989

Event: RFA COMPLETED

Event date: 09/29/1989

Event: INVESTIGATION IMPOSITION

Event date: 04/01/1991

Event: INVESTIGATION WORKPLAN RECEIVED

Event date: 10/04/1991

Event: INVESTIGATION WORKPLAN APPROVED

Event date: 11/08/1991

Event: CA PRIORITIZATION-HIGH CA PRIORITY

Event date: 06/29/1992

Event: STABILIZATION MEASURES EVALUATION-FACILITY NOT AMENABLE TO STABILIZATION

Event date: 09/30/1993

Event: STABILIZATION MEASURES EVALUATION-FURTHER INVESTIGATION NECESSARY

Event date: 09/30/1993

Event: REGION IV - RPS STABILIZATION CATEGORIES

Event date: 10/08/1993

Event: INVESTIGATION WORKPLAN NOTICE OF DEFICIENCY ISSUED

Event date: 09/29/1995

Event: INVESTIGATION COMPLETE

Event date: 09/23/1996

Event: RELEASE TO GW CONTROLLED DETERMINATION-FACILITY DOES NOT MEET DEFINITION

Event date: 09/23/1996

Event: HUMAN EXPOSURES CONTROLLED DETERMINATION-YES, APPLICABLE AS OF THIS DATE

Event date: 10/07/1998

Event: REMEDY DECISION

Event date: 09/29/2003

Event: RELEASE TO GW CONTROLLED DETERMINATION-YES, APPLICABLE AS OF THIS DATE

Event date: 09/30/2010

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

SAFETY-KLEEN CORP 3-013-01 HAPEVILLE (Continued)**1000224298**

Event: REMEDY DECISION

Event date: 09/30/2010
Event: REMEDY CONSTRUCTION-REMEDY CONSTRUCTED

Event date: 05/22/2012
Event: CA PROCESS IS TERMINATED-NO FURTHER ACTION

Facility Has Received Notices of Violations:

Regulation violated: SR - CO EPD-HW-510
Area of violation: TSD - Financial Requirements
Date violation determined: 09/23/2002
Date achieved compliance: 11/25/2002
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 09/23/2002
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 265.115 OF GA RULES
Area of violation: TSD - Closure/Post-Closure
Date violation determined: 03/26/1996
Date achieved compliance: 08/07/1996
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 03/26/1996
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - Financial Requirements
Date violation determined: 11/17/1994
Date achieved compliance: 12/06/1994
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 11/17/1994
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 264.142(a)(4)(b)
Area of violation: TSD - Financial Requirements
Date violation determined: 06/29/1994
Date achieved compliance: 12/12/1994
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

SAFETY-KLEEN CORP 3-013-01 HAPEVILLE (Continued)**1000224298**

Enforcement action date: 06/29/1994
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 12-8-68
Area of violation: TSD - Financial Requirements
Date violation determined: 10/27/1993
Date achieved compliance: 11/12/1993
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 10/27/1993
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 264.147
Area of violation: TSD - Financial Requirements
Date violation determined: 02/11/1993
Date achieved compliance: 11/12/1993
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 02/11/1993
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - General
Date violation determined: 03/13/1991
Date achieved compliance: 10/04/1991
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 04/12/1991
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - General
Date violation determined: 10/15/1990
Date achieved compliance: 11/14/1990
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 10/15/1990

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

SAFETY-KLEEN CORP 3-013-01 HAPEVILLE (Continued)**1000224298**

Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - General
Date violation determined: 12/27/1989
Date achieved compliance: 03/06/1990
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 02/08/1990
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - General
Date violation determined: 08/11/1989
Date achieved compliance: 09/29/1989
Violation lead agency: State
Enforcement action: FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date: 09/29/1989
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: 20000
Final penalty amount: 20000
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - Financial Requirements
Date violation determined: 08/11/1989
Date achieved compliance: 09/29/1989
Violation lead agency: State
Enforcement action: FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date: 09/29/1989
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: 20000
Final penalty amount: 20000
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - General
Date violation determined: 12/02/1988
Date achieved compliance: 02/10/1989
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 01/18/1989
Enf. disposition status: Not reported

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

SAFETY-KLEEN CORP 3-013-01 HAPEVILLE (Continued)**1000224298**

Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: LDR - General
Date violation determined: 12/02/1988
Date achieved compliance: 02/10/1989
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 01/18/1989
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: LDR - General
Date violation determined: 06/15/1988
Date achieved compliance: 02/10/1989
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/06/1988
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - General
Date violation determined: 06/15/1988
Date achieved compliance: 02/10/1989
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/06/1988
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - General
Date violation determined: 06/18/1987
Date achieved compliance: 08/03/1987
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/20/1987
Enf. disposition status: Not reported
Enf. disp. status date: Not reported

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

SAFETY-KLEEN CORP 3-013-01 HAPEVILLE (Continued)**1000224298**

Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: LDR - General
Date violation determined: 06/18/1987
Date achieved compliance: 08/03/1987
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/20/1987
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - Financial Requirements
Date violation determined: 06/10/1987
Date achieved compliance: 10/23/1987
Violation lead agency: State
Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - Financial Requirements
Date violation determined: 06/10/1987
Date achieved compliance: 07/13/1987
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 06/10/1987
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - General
Date violation determined: 09/19/1986
Date achieved compliance: 01/15/1987
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 12/09/1986
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

SAFETY-KLEEN CORP 3-013-01 HAPEVILLE (Continued)**1000224298**

Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - General
Date violation determined: 09/19/1986
Date achieved compliance: 03/26/1987
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 02/23/1987
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - General
Date violation determined: 09/19/1986
Date achieved compliance: 01/15/1987
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 10/15/1986
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:

Evaluation date: 09/27/2010
Evaluation: CORRECTIVE ACTION COMPLIANCE EVALUATION
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 10/13/2006
Evaluation: FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 02/17/2006
Evaluation: FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA Contractor/Grantee

Evaluation date: 10/12/2005
Evaluation: FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

SAFETY-KLEEN CORP 3-013-01 HAPEVILLE (Continued)**1000224298**

Evaluation date:	10/11/2005
Evaluation:	FINANCIAL RECORD REVIEW
Area of violation:	Not reported
Date achieved compliance:	Not reported
Evaluation lead agency:	State
Evaluation date:	06/10/2004
Evaluation:	FINANCIAL RECORD REVIEW
Area of violation:	Not reported
Date achieved compliance:	Not reported
Evaluation lead agency:	State
Evaluation date:	05/27/2003
Evaluation:	FINANCIAL RECORD REVIEW
Area of violation:	Not reported
Date achieved compliance:	Not reported
Evaluation lead agency:	State
Evaluation date:	09/23/2002
Evaluation:	FINANCIAL RECORD REVIEW
Area of violation:	TSD - Financial Requirements
Date achieved compliance:	11/25/2002
Evaluation lead agency:	State
Evaluation date:	04/22/2002
Evaluation:	FINANCIAL RECORD REVIEW
Area of violation:	Not reported
Date achieved compliance:	Not reported
Evaluation lead agency:	State
Evaluation date:	12/22/1999
Evaluation:	FINANCIAL RECORD REVIEW
Area of violation:	Not reported
Date achieved compliance:	Not reported
Evaluation lead agency:	State
Evaluation date:	09/01/1998
Evaluation:	FINANCIAL RECORD REVIEW
Area of violation:	Not reported
Date achieved compliance:	Not reported
Evaluation lead agency:	State
Evaluation date:	08/18/1998
Evaluation:	FINANCIAL RECORD REVIEW
Area of violation:	Not reported
Date achieved compliance:	Not reported
Evaluation lead agency:	State
Evaluation date:	05/04/1998
Evaluation:	FINANCIAL RECORD REVIEW
Area of violation:	Not reported
Date achieved compliance:	Not reported
Evaluation lead agency:	State
Evaluation date:	02/18/1998
Evaluation:	FOCUSED COMPLIANCE INSPECTION
Area of violation:	Not reported

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

SAFETY-KLEEN CORP 3-013-01 HAPEVILLE (Continued)

1000224298

Date achieved compliance:	Not reported
Evaluation lead agency:	State
Evaluation date:	10/31/1997
Evaluation:	FOCUSED COMPLIANCE INSPECTION
Area of violation:	Not reported
Date achieved compliance:	Not reported
Evaluation lead agency:	State
Evaluation date:	10/09/1997
Evaluation:	FINANCIAL RECORD REVIEW
Area of violation:	Not reported
Date achieved compliance:	Not reported
Evaluation lead agency:	State
Evaluation date:	06/19/1997
Evaluation:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation:	Not reported
Date achieved compliance:	Not reported
Evaluation lead agency:	State
Evaluation date:	06/18/1997
Evaluation:	FINANCIAL RECORD REVIEW
Area of violation:	Not reported
Date achieved compliance:	Not reported
Evaluation lead agency:	State
Evaluation date:	08/23/1996
Evaluation:	FINANCIAL RECORD REVIEW
Area of violation:	Not reported
Date achieved compliance:	Not reported
Evaluation lead agency:	State
Evaluation date:	04/04/1996
Evaluation:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation:	Not reported
Date achieved compliance:	Not reported
Evaluation lead agency:	State
Evaluation date:	03/26/1996
Evaluation:	FOCUSED COMPLIANCE INSPECTION
Area of violation:	TSD - Closure/Post-Closure
Date achieved compliance:	08/07/1996
Evaluation lead agency:	State
Evaluation date:	01/10/1996
Evaluation:	FINANCIAL RECORD REVIEW
Area of violation:	Not reported
Date achieved compliance:	Not reported
Evaluation lead agency:	State
Evaluation date:	04/18/1995
Evaluation:	FINANCIAL RECORD REVIEW
Area of violation:	Not reported
Date achieved compliance:	Not reported
Evaluation lead agency:	State

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

SAFETY-KLEEN CORP 3-013-01 HAPEVILLE (Continued)

1000224298

Evaluation date: 03/28/1995
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 09/27/1994
Evaluation: FINANCIAL RECORD REVIEW
Area of violation: TSD - Financial Requirements
Date achieved compliance: 12/06/1994
Evaluation lead agency: State

Evaluation date: 06/29/1994
Evaluation: FINANCIAL RECORD REVIEW
Area of violation: TSD - Financial Requirements
Date achieved compliance: 12/12/1994
Evaluation lead agency: State

Evaluation date: 06/27/1994
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 10/21/1993
Evaluation: FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 09/30/1993
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 05/18/1993
Evaluation: FINANCIAL RECORD REVIEW
Area of violation: TSD - Financial Requirements
Date achieved compliance: 11/12/1993
Evaluation lead agency: State

Evaluation date: 04/10/1993
Evaluation: FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 11/09/1992
Evaluation: FINANCIAL RECORD REVIEW
Area of violation: TSD - Financial Requirements
Date achieved compliance: 11/12/1993
Evaluation lead agency: State

Evaluation date: 08/30/1992
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: Not reported

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

SAFETY-KLEEN CORP 3-013-01 HAPEVILLE (Continued)

1000224298

Date achieved compliance:	Not reported
Evaluation lead agency:	State
Evaluation date:	06/28/1992
Evaluation:	NON-FINANCIAL RECORD REVIEW
Area of violation:	Not reported
Date achieved compliance:	Not reported
Evaluation lead agency:	State
Evaluation date:	03/11/1992
Evaluation:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation:	Not reported
Date achieved compliance:	Not reported
Evaluation lead agency:	State
Evaluation date:	01/08/1992
Evaluation:	FINANCIAL RECORD REVIEW
Area of violation:	Not reported
Date achieved compliance:	Not reported
Evaluation lead agency:	State
Evaluation date:	03/13/1991
Evaluation:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation:	TSD - General
Date achieved compliance:	10/04/1991
Evaluation lead agency:	State
Evaluation date:	10/15/1990
Evaluation:	NON-FINANCIAL RECORD REVIEW
Area of violation:	TSD - General
Date achieved compliance:	11/14/1990
Evaluation lead agency:	State
Evaluation date:	12/27/1989
Evaluation:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation:	TSD - General
Date achieved compliance:	03/06/1990
Evaluation lead agency:	State
Evaluation date:	09/20/1989
Evaluation:	FOCUSED COMPLIANCE INSPECTION
Area of violation:	Not reported
Date achieved compliance:	Not reported
Evaluation lead agency:	State
Evaluation date:	08/11/1989
Evaluation:	FINANCIAL RECORD REVIEW
Area of violation:	TSD - General
Date achieved compliance:	09/29/1989
Evaluation lead agency:	State
Evaluation date:	08/11/1989
Evaluation:	FINANCIAL RECORD REVIEW
Area of violation:	TSD - Financial Requirements
Date achieved compliance:	09/29/1989
Evaluation lead agency:	State

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

SAFETY-KLEEN CORP 3-013-01 HAPEVILLE (Continued)**1000224298**

Evaluation date:	07/05/1989
Evaluation:	NON-FINANCIAL RECORD REVIEW
Area of violation:	Not reported
Date achieved compliance:	Not reported
Evaluation lead agency:	State
Evaluation date:	07/05/1989
Evaluation:	FINANCIAL RECORD REVIEW
Area of violation:	Not reported
Date achieved compliance:	Not reported
Evaluation lead agency:	State
Evaluation date:	12/02/1988
Evaluation:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation:	LDR - General
Date achieved compliance:	02/10/1989
Evaluation lead agency:	State
Evaluation date:	12/02/1988
Evaluation:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation:	TSD - General
Date achieved compliance:	02/10/1989
Evaluation lead agency:	State
Evaluation date:	06/15/1988
Evaluation:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation:	LDR - General
Date achieved compliance:	02/10/1989
Evaluation lead agency:	State
Evaluation date:	06/15/1988
Evaluation:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation:	TSD - General
Date achieved compliance:	02/10/1989
Evaluation lead agency:	State
Evaluation date:	06/10/1988
Evaluation:	NON-FINANCIAL RECORD REVIEW
Area of violation:	Not reported
Date achieved compliance:	Not reported
Evaluation lead agency:	State
Evaluation date:	11/09/1987
Evaluation:	NON-FINANCIAL RECORD REVIEW
Area of violation:	Not reported
Date achieved compliance:	Not reported
Evaluation lead agency:	State
Evaluation date:	07/31/1987
Evaluation:	FINANCIAL RECORD REVIEW
Area of violation:	Not reported
Date achieved compliance:	Not reported
Evaluation lead agency:	State
Evaluation date:	06/18/1987
Evaluation:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation:	TSD - General

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

SAFETY-KLEEN CORP 3-013-01 HAPEVILLE (Continued)

1000224298

Date achieved compliance: 08/03/1987
Evaluation lead agency: State

Evaluation date: 06/18/1987
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: LDR - General
Date achieved compliance: 08/03/1987
Evaluation lead agency: State

Evaluation date: 06/10/1987
Evaluation: FINANCIAL RECORD REVIEW
Area of violation: TSD - Financial Requirements
Date achieved compliance: 07/13/1987
Evaluation lead agency: State

Evaluation date: 06/10/1987
Evaluation: FINANCIAL RECORD REVIEW
Area of violation: TSD - Financial Requirements
Date achieved compliance: 10/23/1987
Evaluation lead agency: State

Evaluation date: 02/16/1987
Evaluation: FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 09/19/1986
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - General
Date achieved compliance: 03/26/1987
Evaluation lead agency: State

Evaluation date: 09/19/1986
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - General
Date achieved compliance: 01/15/1987
Evaluation lead agency: State

Evaluation date: 07/30/1985
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

US FIN ASSUR:

EPA ID: GAD000823070
County: Not reported
Mechanism type: I
Mechanism Type Description: INSURANCE
Cost estimate: 3000000
Face value: 3000000
Effective date: 2015-11-01 00:00:00
Provider: GREENWICH INSURANCE COMPANY
EPA region: 4

EPA ID: GAD000823070
County: Not reported

PRELIMINARY MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

SAFETY-KLEEN CORP 3-013-01 HAPEVILLE (Continued)

1000224298

Mechanism type: I
Mechanism Type Description: INSURANCE
Cost estimate: 159608
Face value: 159608
Effective date: 2010-07-31 00:00:00
Provider: INDIAN HARBOR INSURANCE COMPANY
EPA region: 4

EPA ID: GAD000823070
County: Not reported
Mechanism type: I
Mechanism Type Description: INSURANCE
Cost estimate: 3000000
Face value: 3000000
Effective date: 2016-11-01 00:00:00
Provider: INDIAN HARBOR INSURANCE COMPANY
EPA region: 4

2020 COR ACTION:
EPA ID: GAD000823070
Region: 4
Action: Remedy Construction

48
NNW
1/2-1
0.985 mi.
5202 ft.

DAIRY QUEEN
1519 NORMAN BERRY DRIVE
EAST POINT, GA 30344

GA NON-HSI S119008901
N/A

NON HSI:
Latitude: 33.68388
Longitude: 84.438333
Ground Water Pathway Score: 6.50
On-Site Pathway Score: 0.00
Report Date: 08/23/2016
Additional Info: Tax Parcel: 14 0156 LL0277
Contamination: Tetrachloroethene

Count: 7 records

ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
ATLANTA	S104819378	CENTENNIAL OLYMPIC PARK	179 HARRIS ST.		GA NON-HSI
ATLANTA	S103439807	GWCC (TRACT II)	INTERNATIONAL BETWEEN WALTON /LUCKIE		GA NON-HSI
ATLANTA	S103439806	GWCC (TRACT I)	INTERNATIONAL BETWEEN WALTON /LUCKIE		GA NON-HSI
EAST POINT	1012042970	HENRY CHANIN/MARTEL MANUFACTURING	CALHOUN AVENUE		SEMS
EAST POINT	U001493646	J M ZELLNER & SON TRANSFER CO	2836 MARTIN ST	30344	LUST, UST, Financial Assurance
EAST POINT	S110477156	GENERAL CHEMICAL CORPORATION	0 MARTIN STREET	30364	SHWS
HAPEVILLE	S113244860	SOUTHERN EMS	5454 NORTH CENTRAL AVENUE	30354	SWF/LF